



## Appendix 'F' – Structural Evaluation Reports



Prepared By:



City of Brantford

# Lorne Bridge (Structures 117, 131, 132) Structural Evaluation Report

**GMBP File: 119104**  
**May 2021**



## TABLE OF CONTENTS

<b>1. INTRODUCTION .....</b>	<b>1</b>
<b>2. BACKGROUND INFORMATION .....</b>	<b>1</b>
2.1 Existing Structure .....	1
2.2 Review of Background Information .....	2
<b>3. VISUAL SITE REVIEW .....</b>	<b>2</b>
<b>4. METHODOLOGY .....</b>	<b>3</b>
4.1 Existing Conditions .....	3
4.2 Evaluation Procedure .....	3
4.2.1 Dead Loads .....	3
4.2.2 Live Loads .....	4
4.2.3 Load Factors .....	4
<b>5. LORNE ARCH BRIDGE EVALUATION .....</b>	<b>5</b>
5.1 Background .....	5
5.2 Arch Bridge Characteristics .....	5
5.3 Structural Evaluation .....	6
5.4 Discussion .....	8
<b>6. LORNE GIRDER BRIDGE EVALUATION .....</b>	<b>9</b>
6.1 Background .....	9
6.2 Structural Evaluation .....	9
6.3 Discussion .....	9
<b>7. LORNE BRIDGE PEDESTRIAN UNDERPASS EVALUATION .....</b>	<b>9</b>
7.1 Background .....	9
7.2 Structural Evaluation .....	10
7.3 Discussion .....	10
<b>8. CONCLUSION AND RECOMMENDATIONS .....</b>	<b>10</b>
<b>9. LIMITATIONS .....</b>	<b>13</b>
<b>10. WORKS CITED .....</b>	<b>14</b>

## APPENDICES

- APPENDIX I: 2019 DETAILED VISUAL INSPECTION REPORTS (BY MCINTOSH PERRY)**  
**APPENDIX II: SELECT HISTORICAL STRUCTURAL DRAWINGS**

---

**CITY OF BRANTFORD****LORNE BRIDGE (STRUCTURES 117, 131, 132) STRUCTURAL EVALUATION REPORT****GMBP FILE: 119104****MAY 2021**

---

**1. INTRODUCTION**

**GM BluePlan Engineering Limited** (GMBP) was retained by the City of Brantford (City) to complete an Environmental Assessment (EA) of the Lorne Bridge to evaluate long-term plans for the crossing based on an assessment of the technical, economic, social and natural environments. As part of the assessment of the technical environment, this Structural Evaluation has been completed to assess the structure's ability to carry traffic loading to current standards, as well as to review and update the findings of the "Lorne Bridge Engineering Condition Assessment Report, April 2016" (Parsons 2016). A key consideration for this report is to remove the load posting on Lorne Bridge. Our evaluation has been carried out following Section 14 "Evaluation" of the Canadian Highway Bridge Design Code (S6-19).

**2. BACKGROUND INFORMATION****2.1 Existing Structure**

The Lorne Bridge is located on Colborne Street West, immediately west of Icomm Drive / Brant Avenue and crosses the Grand River. The structure is comprised of three separate structures, which are distinguished as follows:

- Structure 131: Lorne Arch Bridge
  - The structure spanning the Grand River with clear spans of 39.6 m, 42.7 m, 39.6 m
  - Three-span concrete spandrel arch bridge
  - Originally constructed in 1924 to replace steel truss bridges from 1878 and 1899, and underwent a major rehabilitation in 1981 to raise and widen the deck
  - A load limit of 30 tonnes was imposed on the bridge in 2016 for winter months
- Structure 132: Lorne Girder Bridge
  - The structure spanning the rail corridor east of the Grand River with a span of approximately 19.8 m
  - Immediately east of the Lorne Arch Bridge, a single span prestressed precast concrete box girder bridge
  - Originally constructed in 1924 to replace an overpass of unknown construction date and underwent a superstructure replacement in 1981 to its current condition
  - Includes large retaining walls along the rail corridor, which are assumed to date to construction prior to 1924
- Structure 117: Lorne Bridge Pedestrian Underpass
  - Immediately west of the Lorne Arch Bridge, a single span precast concrete box culvert allowing pedestrian and cyclist traffic to pass beneath Colborne Street West
  - Constructed in 1981

The most recent detailed visual inspection reports for each structure are provided in **Appendix I** to detail the conditions of each structure.



## 2.2 Review of Background Information

The following background information was provided by the City regarding the Lorne Bridge, and was reviewed as part of our structural evaluation:

- Lorne Bridge Drawings and Contract Specifications, City of Brantford (1923)
- Lorne Bridge Underpass Drawings, City of Brantford (1965)
- Lorne Bridge Report, J.D. Lee Engineering Ltd. (1969)
- L. E. & N. R. Subway at N. End of Lorne Bridge Drawing, Damas and Smith Limited (1971)
- Brant Ave. – Colborne St. Intersection Drawing, Damas and Smith Limited (1972)
- Proposed Lorne Bridge Improvements Widening to Five Lanes Drawing, Damas and Smith Limited (1972)
- Proposed Lorne Bridge Improvements Widening to Six Lanes Drawing, Damas and Smith Limited (1972)
- Subsurface Investigation Proposed Reconstruction of Lorne Bridge Report, Dominion Soil Investigation Inc. (1978)
- Lorne Bridge Reconstruction Approach Pavement Details Drawings, J.D. Lee Engineering Ltd. (1981)
- Additional Subsurface Investigation Proposed Reconstruction of Lorne Bridge Report, Dominion Soil Investigation Inc. (1979)
- Lorne Bridge Reconstruction Drawings, J.D. Lee Engineering Ltd. (1979)
- Geotechnical Investigation - Foundation Subgrade Evaluation - Lorne Bridge Report, Peto MacCallum Ltd. (1986)
- Road and Sewer Reconstruction of Colborne Street from Brant Avenue to Queen Street Drawing, City of Brantford (1990)
- Lorne Bridge Routine Visual Inspection Report, McCormick Rankin (1992)
- Expansion Joint Replacement – Lorne Bridge Drawings, McCormick Rankin (1995)
- Proposed Right Turning Lane on Colborne St. West at Icomm Drive Drawing, City of Brantford (2002)
- Colborne St. W. / Icomm Dr. / Brant Ave. Drawing, City of Brantford (2002)
- Lorne Bridge Condition Survey and Preliminary Engineering Report, McCormick Rankin Corporation (2004)
- Lorne Bridge Rehabilitation Drawings, Philips Engineering (2006)
- Crack Monitoring Reports for the Lorne Bridge, SPL Consultants Limited / WSP (2014-2016)
- Lorne Bridge Engineering Condition Assessment Report, Parsons (2016)
- Lorne Bridge Load Posting Letter, Parsons (2016)
- Site Investigation Report for Lorne Bridge, Ministry of Transportation Ontario (2018)
- OSIM Inspection Report, McIntosh Perry (2019)

## 3. VISUAL SITE REVIEW

Non-destructive visual site reviews were carried out by Jens Hummel, P.Eng., of GMBP in the following sequence:

- Lorne Arch Bridge
  - June 4, 2020: abutment faces, east arch soffit and vertical faces of arches
  - August 7, 2020: east abutment wall, east arch top of slab, centre arch top of slab and vertical faces, pier chambers, spandrel walls, deck soffit
  - August 13, 2020: west abutment wall, west arch top of slab and vertical faces, west pier at water level, west arch soffit, centre arch soffit, east abutment chamber

- Lorne Girder Bridge
  - August 13, 2020: deck soffit, box beams, east abutment
  - August 21, 2020: retaining walls
- Lorne Bridge Pedestrian Underpass
  - August 22, 2020: barrel

The top of the bridge deck was open to traffic and its general review was completed during the various site visits.

Access to the spandrel walls was provided through openings at the centre of the walls throughout the bridge length. A ladder was used at each of the abutments to access the top side of the arches and the spandrel walls. Chambers are located in the piers and the east abutment. There is no chamber located in the west abutment.

Elements not accessible and not visible were the bearing pads and their supports at the west arch abutment, the east arch abutment, and the west railway overpass abutment. Expansion joints were reviewed from the top and the sides but not from the underside.

## 4. METHODOLOGY

The structural evaluations were made in accordance with Section 14 of the CSA S6-19 Canadian Highway Bridge Design Code (CHBDC). Provided below is a detailed description of the methodology used for each evaluation. It should be noted that our evaluation refers to the capacity of superstructure elements only. Section 14 of the CHBDC does not refer to the evaluation of the substructure. Based on the defects noted during the site visits completed by GMBP, we do not believe that the substructure elements are a limiting factor in the capacity of any structure that was evaluated.

### 4.1 Existing Conditions

Where provided, drawings of the existing structure were reviewed to determine the capacity of structural elements. Refer to **Appendix II** for drawings of the evaluated structures. Note that, due to the number of drawings and reports for the Lorne Bridge, only relevant drawings for this evaluation have been included in the appendix. All material strengths were determined in accordance with Section 14 of the CHBDC using the estimated or provided date of construction.

For structural components with visible signs of defects or deterioration, the factored resistance was multiplied by a reduction factor that would be adequate to the level of deterioration.

### 4.2 Evaluation Procedure

#### 4.2.1 Dead Loads

Dead loads, such as the self-weight of all bridge components, were calculated in accordance with the CHBDC Table 3.4 and Clause 14.8 "Permanent Loads". The weights of materials used for the evaluation of each structure (where applicable) are summarized in **Table 1**.

**Table 1: Summary of Dead Loads for Evaluations**

Material	Weight
Steel	77.0 kN/m <sup>3</sup>
Concrete (plain)	23.5 kN/m <sup>3</sup>
Concrete (reinforced)	24.0 kN/m <sup>3</sup>
Asphalt Wearing Surface	23.5 kN/m <sup>3</sup>
Aluminum	27.0 kN/m <sup>3</sup>

Dead loads are apportioned into three categories: D1 (factory produced products, cast-in-place concrete – excluding decks), D2 (cast-in-place concrete decks, wood, field-measured asphalt, non-structural components), and D3 (asphalt, where the thickness is assumed to be 90 mm). In general, where the geometry could not be verified by field measurement the dead load was considered to be categorized as a D3 dead load.

#### 4.2.2 Live Loads

Three levels of Ontario truck or lane loading were used in the load rating and posting of each structure: CL1-625-ONT, CL2-625-ONT, and CL3-625-ONT (referred to as Evaluation Levels 1, 2 and 3, respectively). The Evaluation Level 1 design truck is applied to the structure. If a load posting is required, the remaining two design truck loads are applied to the bridge to provide appropriate ratings for a triple posting. Following procedures outlined in the CHBDC, single postings may be applicable once the structure has reached a determined level of deterioration. The Live Load Capacity Factor, F, is calculated to determine the residual strength in the structural elements that is available to resist applied live loads once all permanent loads (i.e., dead loads) have been accounted for by the member's strength. This factor is then used to determine the maximum weight that the bridge can support for the given Evaluation Level.

To represent multiple vehicles on the bridge simultaneously, a “lane load” was also considered as a separate live load case. This loading is comprised of the design truck load reduced by a prescribed factor as well as a distributed load across the entire span.

#### 4.2.3 Load Factors

Reliability Indices are used to determine the appropriate load factors for dead and live loads. These indices are dependent upon the element being analyzed, and its system behaviour, element behaviour and inspection level as outlined below:

- System behaviour, classified as one of the following:
  - (S1) Element failure will lead to total collapse
  - (S2) Element failure will likely not lead to total collapse
  - (S3) Element failure will lead to local failure only
- Element behaviour, classified as one of the following:
  - (E1) Element is subject to a sudden loss of capacity with little or no warning
  - (E2) Element is subject to a sudden loss of capacity with little or no warning but will retain post-failure capacity
  - (E3) Element is subject to gradual failure with warning of probable failure
- Inspection level, classified as one of the following:
  - (INSP1) Element is not accessible for inspection
  - (INSP2) Element is accessible for inspection to the satisfaction of the evaluator
  - (INSP3) Element is accessible for inspection and inspection is directed by the evaluator

Once the system behaviour, element behaviour and inspection level have been determined for the failure mode of each element being evaluated, a Reliability Index can be used to determine the appropriate dead and live load factors. It should be noted that a single element may have different load factors depending on the mode of failure being analyzed (i.e., a concrete beam being analyzed for shear may have different load factors for analysis than the same being analyzed for bending).

## 5. LORNE ARCH BRIDGE EVALUATION

### 5.1 Background

The Lorne Arch Bridge is a three-span spandrel arch bridge built of reinforced concrete in 1924 with span lengths of 39.6 m, 42.7 m, and 39.6 m. In 1981, the bridge was rehabilitated including the replacement and widening of the deck to accommodate five vehicle lanes and two pedestrian sidewalks. The two bridge abutments and piers use unreinforced mass concrete foundations to transfer loads directly to the bedrock. Chambers are present above the foundations for the east abutment and both piers. These chambers contain minimal reinforcement with the exception of the portions that were reconstructed as part of the 1981 rehabilitation.

The concrete arches built in 1924 are constructed of reinforced concrete. Based on the original drawings, the amount of longitudinal reinforcement would be considered to be compliant with minimum reinforcement requirements of the CHBDC (120% of the cracking moment) for ductility. The amount of transverse reinforcement is minimal and would not comply with current CHBDC minimum reinforcement amounts.

The three arches are solid arch slabs that support transverse concrete spandrel walls (columns) that, in turn, support the bridge deck. The original columns also contained minimal reinforcement. The shorter columns nearer to midspan were completely replaced as part of the 1981 rehabilitation, whereas the taller columns closer to the piers and abutments were only partially reconstructed.

The original bridge deck had expansion joints over the piers and abutments. The 1981 rehabilitation eliminated the expansion joints over the piers but retained the abutment expansion joints.

Overall, the bridge has a very robust appearance. It is noted that the solid arch slab is atypical in spandrel arch bridges, as there are usually two separate “arch girders” that support the spandrel columns and bridge deck. Arch bridges of similar construction style to the Lorne Arch Bridge were quite popular at the time of its construction, as shown by the large collection of concrete arch bridges built in Pennsylvania between 1918 and 1941 [1].

### 5.2 Arch Bridge Characteristics

Arch bridges are designed to maintain compression along the arch under self weight. The designer needs to balance the compression thrust line within the arch close to the arch centerline. If the thrust line shifts to the faces of the arch, the bridge becomes unstable and may develop concrete “hinges”. This was true of early versions of brick, stone and unreinforced concrete arch bridges as they were constructed of materials that were far weaker in tension than compression; however, several reinforced concrete arch bridges built at the beginning of the 20<sup>th</sup> century were also designed to be in compression under self-weight. Arch bridges can also be viewed as “prestressed” by the forces generated by the self-weight of the deck, spandrels and arch.

A differentiation may be made between regular arches and flat arches. To decide if a bridge is a regular arch or a flat arch, the rise-to-span ratio can be used. Flat arches have a rise-to-span ratio of 0.1 or less, whereas regular arches have a ratio of greater than 0.1 up to 1.0 or more [2]. The Lorne Arch Bridge has a rise-to-span ratio of 5.3 m / 42.7 m = 0.124 and may be classified as a regular arch shape.



Flat arches are more vulnerable to abutment settlement or horizontal movement as well as seasonal thermal cycling (i.e., horizontal expansion and contraction) [2] [3]; however, thermal sensitivity increases with larger spans. The CHBDC allows the analysis to not consider thermal loading if the bridge is reinforced to be ductile. Some literature sources describe a reduction of thermal restraint forces by concrete cracking, concrete creep and non-linear concrete behaviour ranging between 0.3 and 0.8 [4] [5] [6] [7].

### 5.3 Structural Evaluation


Based on our observations and review of available information, we do not believe that the deck and spandrel columns are limiting members in evaluation of the Lorne Arch Bridge. Therefore, these elements were not reviewed as part of this evaluation. The arch slabs are the primary element that would lead to the global failure of the bridge. These slabs also have a high degree of redundancy due to the solid transverse width of the slabs and the load spreading properties of concrete. The arch slabs appear to be generally uncracked for longitudinal bending action (i.e., no structurally significant cracks in the transverse direction). Longitudinal cracks are present in all spans, generally at the mid-width of the slab. We believe these cracks may be related to the construction methodology of the bridge (i.e., a cold joint) and/or to shrinkage.

In the Parsons 2016 report it was assumed that the bridge shows brittle behaviour. It is our assessment that this is a valid assumption for elements such as the abutments, piers and the original sections of spandrel columns. However, based on our research, we believe that the failure mode of the arch slabs would be in a ductile manner. As a minimum, the CHBDC requires that bending members are reinforced to resist 1.2 times the cracking moment of the section. This is to ensure that the section remains ductile after the concrete cracks from tensile forces due to bending. The existing drawings note that the longitudinal steel in the arch slabs is “1.25 inch square twisted bars at 12 inch centres”, and we have assumed a yield strength of 230 MPa for the existing reinforcing steel. This reinforcement was found to be sufficient to resist 1.2 times the cracking moment of the arch slab section. Therefore, we believe that the arch slab would show ductile behaviour.

Our analysis concentrated on the 42.7 m long arch slab span, as there were negligible differences between this span and the smaller spans and the only point of continuity for the arch spans is at the foundations. The foundations bear on bedrock and do not show any signs of structural distress related to overloading of the arch slabs.


We modeled a representative 1.0 m width section of the 42.7 m long arch slab span using a 2D finite element model utilizing the S-Frame structural analysis software. Dead loads were generated by the S-Frame model, or superimposed where appropriate. Live loading using the CL-625-ONT design truck for the three evaluation levels was applied following the provisions of the code and prorated to the 1.0 m width model.

In general, the arch slab was found to be in compression under dead loads. When live loads were introduced to the model, the critical load case was determined to be when the design truck was placed over one half of the span, with the tandem axle close to midspan. Refer to **Figure 1** below for a graphical representation of the longitudinal stress distribution due to the live load at the critical location. Note that only one truck is shown graphically; however, multiple trucks were analyzed as travelling in a synchronized manner across the bridge in accordance with the CHBDC. The concrete deck and spandrel columns were assumed to provide uniform lateral distribution of live loads on the bridge deck.



**Figure 1: Longitudinal Stress Distribution from Live Load at Critical Location**

As this result relates to the overall behaviour of the arch slab, if the tensile force in the slab exceeds the resistance of the reinforced concrete section, hinges will develop in the slab. This scenario is graphically represented in **Figure 2** below for illustration purposes.



**Figure 2: Assumed Hinge Development in Arch Slab when Applied Loading Exceeds Capacity**

The effect of seasonal thermal loading was considered in great detail, as it is our understanding that the current load limit on the Lorne Arch Bridge is due to the effects of thermal loading. The CHBDC notes that thermal loading does not need to be considered for ductile structures. The arch slab has been assumed to be ductile in the longitudinal direction, but not in the transverse direction. Based on our research on arch bridge behaviour, a reduction factor of 0.4 was applied to all forces induced from thermal loading [4] [5] [6] [7] [8].

Our design review for the Serviceability Limit State (SLS) conditions shows that the longitudinal tensile stresses at SLS do not exceed the tensile resistance of the concrete section (i.e., does not induce flexural cracking). This is supported by our site observations.

Our design review for the Ultimate Limit State (ULS) conditions shows that the concrete arch slab may crack due to longitudinal tensile forces. The existing reinforced concrete section was found to be sufficient to resist the tensile forces from flexure at ULS conditions.

Further analysis was completed that showed that the concrete arch slab would be capable of resisting the applied loads at ULS for a thermal load reduction factor up to 0.4.

## 5.4 Discussion

All engineering models used for calculation are a simplification of the actual structural system. The design and evaluation of arch bridges can be delicate since “prestress” by self-weight, concrete quality, loss of stiffness by local cracking, thrust force eccentricity in the arch, material uncertainties, support conditions, thermal creep of concrete, microcracking of concrete, and statically indeterminate structure behaviour under a seasonal thermal cycle are difficult to quantify and evaluate.

Our analysis suggests that the existing structure does not require a load posting, but this is largely based on our estimation of the arch behaviour and applicable reductions in thermal loading to the arch. Prior to recommending that the existing load limit be removed, additional monitoring to calibrate our analytical model against the actual behaviour of the bridge during a range of seasonal temperatures would be necessary. Load testing of the bridge may also be appropriate. Following collection of this data and calibration of the model, the existing load posting can be reviewed and adjusted accordingly. If it is determined that no reduction is appropriate, then the existing load posting should remain.

The concrete arch slabs contain marginal steel reinforcement in the transverse direction. We believe this to be the cause of, or a significant contributing factor to, the longitudinal separation cracks developed in the concrete arch slab. These cracks appear to run completely through the depth of the arch slab, as they are visible both at the top side and the underside of the slab. Comparing the existing transverse steel reinforcement to the current requirements, the reinforcement provided is approximately 7% - 9% of what would be required by the current CHBDC. However, we believe that the marginal transverse reinforcement and the resulting longitudinal cracks do not have a measurable impact on the load carrying capacity of the bridge due to the following:

- There are many similar reinforced and unreinforced concrete structures constructed around the same time period that also have very little transverse reinforcement. Older design methodologies utilized much larger concrete elements with less reinforcement as compared to current practices of more-slender members with increased reinforcement.
- Despite the longitudinal cracks, we do not observe any signs of structural distress (crushing of concrete, tensile cracks). The deterioration noted throughout the bridge could be thought to be caused largely by environmental degradation (numerous freeze/thaw cycles).
- The concrete arch slab has passed the test of time of almost 100 years.
- The new deck built in 1981 and the new tops of the spandrel columns do not show the same longitudinal cracks as the arch slab, suggesting that the spandrel columns and deck are sufficiently strong enough to hold the two to three ribs of the arch slab together.

Our assessment of the existing concrete arch slab has also assumed that the existing reinforcing steel in the arch slab is not undergoing active corrosion. We believe this to be a valid assumption due to the lack of efflorescence staining on the soffit, lack of rust staining on the soffit, and generally small amount of delamination and spalling on the arch slabs. Based on the original specifications, we would expect approximately 60 mm of cover to the main longitudinal reinforcing steel. This is relatively consistent with modern cover requirements, and actually quite substantial for the construction period. As part of the recommended comprehensive monitoring and evaluation program, the alkalinity of the concrete should be assessed to ensure a sufficiently basic environment for the main reinforcing steel that does not induce corrosion. The alkalinity of the concrete can be affected by the natural carbonation of concrete over time or the introduction of chlorides to the concrete from salt-laden waters.

The deck superstructure of this bridge has provided 40 years of service. A major rehabilitation is expected to be required in the next 10 years to maximize the overall service life of the bridge. As the existing foundations and piers are now 100 years old, they should also undergo significant repairs. Based on our observations and review of the Parsons 2016 report, the proposed rehabilitation option would involve asphalt resurfacing, waterproofing, expansion joint replacement, rock protection along piers and isolated concrete repairs to nearly all elements. Strengthening of the arch and piers was also recommended.

## **6. LORNE GIRDER BRIDGE EVALUATION**

### **6.1 Background**

The Lorne Girder Bridge is a concrete slab on prestressed precast concrete box girder bridge. The structure spans across a former railway corridor. The superstructure was constructed as part of the 1981 rehabilitation of the Lorne Arch Bridge, and utilizes the east abutment of the Lorne Arch Bridge as its west abutment (essentially making the east abutment of the Lorne Arch Bridge a pier). The original east abutment of the Lorne Girder Bridge was converted to a retaining wall as part of the 1981 rehabilitation and a new east abutment was constructed behind it. The bridge has a span of approximately 19.8 m.

The existing Lorne Girder Bridge was analyzed in 2016 by Parsons, and found to have sufficient load carrying capacity for the current requirements of the CHBDC.

### **6.2 Structural Evaluation**

The bridge is in overall good condition, and does not show signs of structural distress. In accordance with the CHBDC, we believe this bridge to qualify as a concrete bridge with multiple load paths that does not show signs of excessive material cracking, deformation or degradation. Therefore, we do not recommend a load posting for this structure.

### **6.3 Discussion**

The high concrete retaining wall that runs along the railway corridor in front of the east abutment, which was the east abutment of the previous bridge structure in this location, is in poor condition and requires rehabilitation work. We did not observe any evidence of instability or settlement of the wall, therefore removal of poor concrete and refacing would be an appropriate rehabilitation. This was recommended by Parsons in their 2016 report. The same is true for the smaller concrete retaining wall running in line with the east abutment of the arch bridge.

The superstructure of this bridge has provided 40 years of service. A major rehabilitation is expected to be required in the next 10 years to maximize the overall service life of the bridge. Based on our observations and review of the Parsons 2016 report, the proposed rehabilitation option would involve asphalt resurfacing, waterproofing, expansion joint replacement, retaining wall refacing, barrier installation and isolated concrete repairs to the abutments and soffit.

## **7. LORNE BRIDGE PEDESTRIAN UNDERPASS EVALUATION**

### **7.1 Background**

The Lorne Bridge Pedestrian Underpass is a precast concrete box culvert located west of the Lorne Arch Bridge with a span of 3.0 m. It provides pedestrian and cyclist access beneath Colborne Street West, and was constructed in 1981.



## 7.2 Structural Evaluation

The culvert is in overall good condition and does not show signs of structural distress. In accordance with the CHBDC, we believe this culvert to qualify as a concrete bridge with multiple load paths that does not show signs of excessive material cracking, deformation or degradation. Therefore, we do not recommend a load posting for this structure.

## 7.3 Discussion

The existing culvert has been known to have issues with water leaking through the joints between the precast units as noted by McCormick Rankin in their 1992 inspection report. To our knowledge, a repair of this issue has never been completed. A proper repair would involve excavation of the fill overtop of the culvert and installation of a waterproofing membrane. Subdrains that outlet to the ends of the culvert beyond the existing cast-in-place concrete wingwalls may also be appropriate. Replacement of the lighting within the culvert should also be considered at the same time. This work should be completed as part of the next major rehabilitation to the Lorne Bridge.

## 8. CONCLUSION AND RECOMMENDATIONS

Out of all the structures that make up the Lorne Bridge (arch bridge, railway overpass and retaining walls, pedestrian underpass), the Lorne Arch Bridge is the most significant structure and is in the greatest need of remedial action. The Parsons 2016 report completed a life-cycle cost analysis for various rehabilitation and replacement scenarios, and determined that major rehabilitation and strengthening of the Lorne Arch Bridge, minor rehabilitation of the Lorne Girder Bridge and refacing of the existing retaining walls was the option that provided the greatest net present value to the City.

We have discussed within the body of this report additional testing and monitoring that should be completed in order to accurately scope the level of rehabilitation. Our research into arch bridges has shown that the engineering profession has differing opinions on how thermal loading can influence arch bridge construction. The 2016 analysis by Parsons appears to provide an accurate representation of the behaviour of the bridge when the full thermal loading is applied to the structure. Garrett concludes that the temperature effects on structures are not well understood, and may produce load ratings that are unduly conservative [9]. He notes that the observed performance of the structure should also be a consideration and non-destructive or proof-load testing may be used to further rate or confirm models for arch bridges [9].

We have completed additional research that suggests that it may not be completely necessary to analyze the full thermal loading due to the believed ductile nature of the bridge in longitudinal bending and the ability of arch structures to artificially dampen the effects from thermal loading. It is our belief that the existing concrete arch slab of the Lorne Arch Bridge is a robust load carrying member that is difficult to approximate using modern methods of analysis, as also alluded to by Parsons. This is exemplified by the 1981 rehabilitation which increased the overall dead load to the bridge, increased the number of lanes and added a sidewalk, as well as the increase from the assumed 20 tonne design truck from 1923 to the 36 tonne HS20-44 design truck of the 1981 rehabilitation (per the drawings) to the current 62.5 tonne CL-625-ONT design truck without any additional strengthening to the arch [10].

If the City wishes to remove the existing 30 tonne load limit, without structural strengthening, we recommend that additional monitoring would be advisable to calibrate finite element models of the bridge and accurately inform the scope of rehabilitation. It is estimated that the monitoring program would be 18 months in duration and cost approximately \$150,000.

Alternatively, the City could proceed with the models as currently calibrated and design for strengthening to resist the full thermal load as recommended in Parsons 2016 report.

A summary of the recommended rehabilitation work for the Lorne Bridge is provided in Table 2 to Table 5 below.

In accordance with the 2018 Ontario Structure Inspection Manual (OSIM), with structures older than 30 years with critical components in poor condition, it is recommended that an Enhanced OSIM inspection be completed every 6 years in order to monitor member deterioration, until such time that a major rehabilitation is completed to address the poor condition members.

**Table 2: Rehabilitation Works Recommended – Lorne Arch Bridge**

Item	Rehabilitation Work	Location
1.0	Concrete repair work	<ul style="list-style-type: none"> <li>• East and West abutments (East shared with Lorne Girder Bridge)</li> <li>• East abutment access chamber</li> <li>• East &amp; West Pier, including underpinning and at top, especially non-vertical areas</li> <li>• Spandrel walls</li> <li>• Deck cantilever soffit, especially north side</li> <li>• Soffit of bridge deck</li> <li>• Concrete barrier and curb</li> </ul>
2.0	Replace spalled deck corbels	<ul style="list-style-type: none"> <li>• East Abutment access chamber. West Abutment</li> </ul>
3.0	Crack sealing	<ul style="list-style-type: none"> <li>• East and West abutments</li> <li>• West Pier</li> <li>• Underside of arches</li> </ul>
4.0	FRP mesh reinforcement	<ul style="list-style-type: none"> <li>• East &amp; West Pier chamber walls</li> <li>• Spandrel walls where horizontal and vertical cracks are present</li> <li>• Bridge longitudinal cracks along top side of arches</li> <li>• Underside of arches at midspan (if strengthening required to remove load rating)</li> </ul>
5.0	Replacement of expansion joints	<ul style="list-style-type: none"> <li>• Both ends of arch bridge</li> </ul>
6.0	Deck waterproofing and asphalt replacement	<ul style="list-style-type: none"> <li>• Entire bridge deck</li> </ul>
5.0	Cleaning and maintenance	<ul style="list-style-type: none"> <li>• Remove pigeon excrement on top of arches top faces near midspans and other locations of concentration</li> <li>• Flush expansion joints after winter season to remove debris</li> </ul>

Notes:

1. East end of bridge of the arch span is shared with the west end of the girder span.
2. Recommend completing a new detailed deck condition survey in advance of detailed design

**Table 3: Rehabilitation Works Recommended – Lorne Girder Bridge**

Item	Rehabilitation Work	Location
1.0	Concrete repair work	<ul style="list-style-type: none"> <li>West abutments</li> <li>Repair delamination of northern box girder at east abutment</li> <li>Deck cantilever soffit, especially north side</li> <li>Concrete barrier and curb</li> </ul>
2.0	Crack sealing	<ul style="list-style-type: none"> <li>West abutment</li> </ul>
3.0	Replacement of expansion joint seals	<ul style="list-style-type: none"> <li>Both ends of girder bridge</li> </ul>
4.0	Replace bearings	<ul style="list-style-type: none"> <li>East and west abutments</li> </ul>
5.0	Deck waterproofing and asphalt replacement	<ul style="list-style-type: none"> <li>Entire bridge deck</li> </ul>
6.0	Cleaning and maintenance	<ul style="list-style-type: none"> <li>Flush expansion joints after winter season to remove debris</li> <li>Clean graffiti from east abutment face</li> </ul>

Notes:

1. West abutment of girder span is shared with the east end of the arch span.
2. Recommend completing a new detailed deck condition survey in advance of detailed design

**Table 4: Rehabilitation Works Recommended – Lorne Bridge Pedestrian Underpass**

Item	Rehabilitation Work	Location
1.0	Concrete repair work	<ul style="list-style-type: none"> <li>Barrel/ walls / of culvert</li> </ul>
2.0	Repair/waterproof joints between culvert sections	<ul style="list-style-type: none"> <li>Throughout length of culvert, primarily three joints at each end</li> </ul>
3.0	Repair/replace tunnel light	<ul style="list-style-type: none"> <li>Within underpass</li> </ul>

**Table 5: Rehabilitation Works Recommended – East Bank Retaining Walls**

Item	Rehabilitation Work	Location
1.0	Repair or replace	<ul style="list-style-type: none"> <li>upper retaining wall (adjacent to girder span east abutment). Repairs include repairing the crown, locations of concrete disintegration, and construction joints.</li> </ul>
2.0	Remove	<ul style="list-style-type: none"> <li>Concrete retaining wall adjacent to girder span west abutment. Utilize minor slopes in-place of wall</li> </ul>

## 9. LIMITATIONS

The following limitations are applicable to this load limit evaluation report:

- This report is intended exclusively for the Client(s) named in the report. The material in it reflects our best judgment in light of the information reviewed by GM BluePlan Engineering Limited at the time of preparation. Unless otherwise agreed in writing by GM BluePlan Engineering Limited, this report shall not be used to imply warranty as to the fitness of the property for a particular purpose. This report is not a certification of compliance with past or present regulations. No portion of this report may be used as a separate entity, it is written to be read in its entirety.
- Only the specific information identified has been reviewed. GM BluePlan Engineering Limited is not obligated to identify mistakes or insufficiencies in the information obtained from the various sources or to verify the accuracy of the information. GM BluePlan Engineering Limited may use such specific information obtained in performing its services and is entitled to rely upon the accuracy and completeness thereof.
- This assessment does not wholly eliminate uncertainty regarding the potential for existing or future losses in connection with a property. No physical or destructive testing has been performed unless specifically recorded. Conditions existing, but not recorded, were not apparent given the level of study undertaken. We can perform further investigation on items of concern, if so required.

We thank you for engaging the services of GM BluePlan Engineering Limited, and trust that this report provides the information that you require at this time. If you have any questions, or if we may be of further assistance, please do not hesitate to contact us.

Your truly,

GM BLUEPLAN ENGINEERING LIMITED

Per:



Jens Hummel, P.Eng.

Per:



Jack Turner, P.Eng.





## 10. WORKS CITED

- [1] PennDOT, "Methodology for 2019 Concrete Arch Bridge Evaluation," 2019. [Online]. Available: <https://www.penndot.gov/ProjectAndPrograms/Cultural%20Resources/Documents/Historic%20Concrete%20Arch%20Bridge%20Methodology.pdf>. [Accessed 29 September 2020].
- [2] R. Stroschio, N. Lake, C. Toms and S. Pettifer, "An Integral Flat Arch Bridge," *Bridge Engineering*, vol. 171, no. 3, pp. 210-221, September 2018.
- [3] C. Menn, *Prestressed Concrete Bridges*, Basel: Birkhauser Verlag, 1990, pp. 282-284.
- [4] D. Proske and P. van Gelder, *Safety of Historical Stone Arch Bridges*, Heidelberg: Springer, 2009.
- [5] BMVBS, *Guideline for Recalculation of Existing Road Bridges*, Berlin: Federal Highway Research Institute BAST, 2011.
- [6] Institut fuer Bautechnik, *Concrete Bridges, Structural Design and Construction*, 1981.
- [7] A. Arnold, *Influence of Thermal Restraint Forces on Structures made of Concrete with and without Prestress*, University of Technology of Dortmund, 2008.
- [8] C. Larsson and G. Svensson, *Realistic Modeling of Thermal Effects in Concrete Bridges*, Lund: Lunds University, 2013.
- [9] G. P. Garrett, "Analytical Load Rating of an Open-Spandrel Arch Bridge: Case Study," *ASCE Journal of Bridge Engineering*, vol. 12, no. 1, pp. 13-20, 2007.
- [10] Ministry of Transportation Ontario, *Ontario Structure Inspection Manual (OSIM)*, St. Catherines, 2018.
- [11] C. Melbourne, "Arch Bridges," in *Proceedings of the 1st International Conference on Arch Bridges*, Bolton, 1995.
- [12] J. A. F. O. Correia and A. M. P. De Jesus, "Structural Integrity," in *Proceedings of the 9th International Conference on Arch Bridges*, Porto, 2019.
- [13] Canadian Standards Association, *S6:19, Canadian Highway Bridge Design Code*, Toronto: CSA Group, 2019.
- [14] L.-Y. Lai, *Thermal Effects on Load Ratings of Reinforced Concrete Arch Bridges*, Pittsburgh: ASCE, 2018.
- [15] Ministry of Transportation Ontario, *Structure Rehabilitation Manual*, St. Catherines, 2007.
- [16] Canadian Standards Association, *Commentary on CSA S6:19, Canadian Highway Bridge Design Code*, Toronto: CSA Group, 2019.
- [17] E. Thuermer, *Widening of a Multi-span Arch bridge on Highway A4 near Hainichen*, Dresden: Technische Universitaet Dresden, 1995.
- [18] Victoria State Government, *Bridge Maintenance and Repair Manual*, Victoria, Australia, 2018.



## 2021 Structural Evaluation Report

---

### Appendix I

2019 Detailed Visual Inspection Reports (by McIntosh Perry)



SUMMARY ACTION REPORT

ADDITIONAL INVESTIGATIONS	Priority	Inspection Date
Investigations, Inspections, Surveys Recommended		
Biennial OSIM	Normal	21/Jul/2022

REPAIR AND REHABILITATION REQUIRED	Priority		Comments
	6-10 Years	1 - 5 Years	
Repair and Rehabilitation Required			
Abutment		X	Rehabilitate
Wingwalls		X	Rehabilitate
Sidewalk (approaches & deck)		X	Rehabilitate
Wearing Surface (approaches & deck)		X	Rehabilitate
Barrier Walls		X	Rehabilitate
Soffit (exterior, ends & interior)		X	Rehabilitate
Expansion Joints		X	Replace
Piers		X	Rehabilitate
Arch Rib, Bottom Chord		X	Rehabilitate
Spandrel Columns		X	Rehabilitate

MAINTENANCE NEEDS	Priority		
	2 Years	1 Year	Urgent
Maintenance Needs			
Signs - Replace		X	
Utilities - Repair ducts		X	
Railing Systems - Repair		X	
Expansion Joints - Bridge Cleaning		X	
Embankments - Tree/vegetation maintenance	X		

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

INVENTORY DATA:			
Structure Name	<u>Lorne Bridge-Arch</u>		
Main Hwy/Road #	Under Structure:		<input checked="" type="checkbox"/> Navigable Water <input type="checkbox"/> Non-Navigable Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Pedestrian <input type="checkbox"/> Other
	On Structure:		<input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Pedestrian <input type="checkbox"/> Other
Road Name:	<u>Colborne Street West</u>		
Structure Location	<u>0.05 km S of Brant Ave</u>		
Latitude	<u>43.137222</u>	Longitude	<u>-80.27</u>
Owner(s)	<u>City of Brantford</u>	Heritage Designation	<input type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
MTO Region	<u>Southwestern</u>	Road Class	<input type="checkbox"/> Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input checked="" type="checkbox"/> Local
MTO District	<u>-</u>	Posted Speed	<u>50 km/h</u> No. of Lanes <u>5</u>
Old County	<u>Brant</u>	AADT	<u>27133</u> % Trucks <u>10</u>
Geographic Twp.	<u>-</u>	Special Routes	<input checked="" type="checkbox"/> Transit <input checked="" type="checkbox"/> Truck <input checked="" type="checkbox"/> School <input type="checkbox"/> Bicycle
Structure Type	<u>Spandrel Arch</u>	Detour Length Around Structure	<u>-</u> (km)
Total Deck Length	<u>130.50</u> (m)	Fill on Structure	<u>-</u> (m)
Overall Str. Width	<u>22.90</u> (m)	Skew Angle	<u>0</u> (Degrees)
Total Deck Area	<u>2988.45</u> (m <sup>2</sup> )	Direction of Structure	<u>E - W</u>
Roadway Width	<u>17.40</u> (m)	No. of Spans	<u>3</u>
Span Lengths	<u>41.7; 46.9; 41.7</u> (m)		
Overall Condition Rating		<u>Fair</u>	
Bridge Condition Index (BCI)		<u>64.9</u>	

HISTORICAL DATA			
Year Built	<u>1924</u>	Last OSIM Inspection	<u>2017</u>
Year of Last Major Rehab.	<u>1980</u>	Last Enhanced OSIM Inspection	<u>7/29/2014</u>
Current Load Limit	<u>-</u> (tonnes)	Last Bridge Master Inspection	<u>7/29/2014</u>
Load Limit By-Law #	<u>-</u>	Last Evaluation	<u>-</u>
By-Law Expiry Date	<u>-</u>	Last Underwater Inspection	<u>7/29/2014</u>
Min. Vertical Clearance	<u>12.5</u> (m)	Last Condition Survey	<u>7/29/2014</u>
<b>Rehabilitation History: (Date / Description)</b>			
<u>12/31/1980: Deck Replacement</u>			



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

<b>Scheduled Improvements:</b>	
Regional Priority Number _____	Programmed Work Year _____
Nature of Program Work:	

<b>Appraisal Indices:</b>		<b>Comments</b>
Fatigue		
Seismic		
Scour		
Flood		
Geometrics		
Barrier		
Curb		
Load Capacity		

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

<b>FIELD INSPECTION INFORMATION</b>	
Date of Inspection:	20-Jul-2020 <span style="float:right">Type of Inspection: <input type="checkbox"/> OSIM <input checked="" type="checkbox"/> Enhanced OSIM</span>
Inspector:	Sabrina Dexter, Transportation Structures Engineer
Others in Party:	Ted Walls, Survey Party Chief & Ali Babaei, Field Survey Technician
Access Equipment Used:	Binoculars, sounding hammer, measuring tape, digital camera, drone
Weather:	Sunny
Temperature:	28°C

ADDITIONAL INVESTIGATION REQUIRED	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:				\$ -
Material Condition Survey				\$ -
Detailed Deck Condition Survey:				\$ -
Non-destructive Delamination Survey of Asphalt- Covered Deck:				\$ -
Concrete Substructure Condition Survey:				\$ -
Detailed Coating Condition Survey:				\$ -
Detailed Timber Investigation:				\$ -
Underwater Investigation:				\$ -
Fatigue Investigation:				\$ -
Seismic Investigation:				\$ -
Structure Evaluation:				\$ -
Monitoring				\$ -
Monitoring of Deformations, Settlement and Movements:				\$ -
Monitoring Crack Widths:		X		By Client
<b>Load Posting – Estimated Load Limit</b>	<b>Total Cost</b>			\$ -
<b>Investigation Notes:</b>				
Continue ongoing annual monitoring of crack widths in piers and arches.				

<b>OVERALL STRUCTURAL NOTES:</b>	
Recommended Work on Structure:	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 Years <input type="checkbox"/> 6 to 10 Years
Overall Comments:	
Overall, structure is in fair condition. Spalls, delamination and wide cracks on abutments, wingwalls, piers, parapet walls, sidewalk, arch rib and spandrels. Potholes and wide unsealed cracks in wearing surface. The structure is recommended to undergo a rehabilitation in 1-5 years. Maintenance work required.	
Date of Next Inspection:	21-Jul-2022

**Suspected Performance Deficiencies**

- |  |  |                              |
|--|--|------------------------------|
| 00 None  | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 01 Load carrying capacity                          | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotation) | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 03 Continuing settlement                           | 09 Rough riding surface                  | 15 Unstable embankments      |
| 04 Continuing movements                            | 10 Surface ponding                       | 16 Other                     |
| 05 Seized bearings                                 | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                               |  |
|--------------------------------------|-------------------------------|--|
| 01 Lift and swing bridge maintenance | 07 Repair of structural steel | 13 Erosion control at bridges            |
| 02 Bridge cleaning                   | 08 Repair of bridge concrete  | 14 Concrete sealing                      |
| 03 Bridge handrail maintenance       | 09 Repair of bridge timber    | 15 Rout and seal                         |
| 04 Painting steel bridge structures  | 10 Bailey bridges maintenance | 16 Bridge deck drainage                  |
| 05 Bridge deck joint repair          | 11 Animal/pest control        | 17 Scaling (loose Concrete or ACR Steel) |
| 06 Bridge bearing maintenance        | 12 Bridge surface repair      | 18 Other                                 |

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Abutment	<b>Length:</b>			
<b>Element Name:</b>	Abutment Walls	<b>Width:</b>	19.51		
<b>Location:</b>	East and West	<b>Height:</b>	10.00		
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>	2		
<b>Element Type:</b>	Conventional Closed	<b>Total Quantity:</b>	390.20		
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	264.20	77.00	49.00
<b>Comments:</b>					
Partially covered with graffiti. Light to severe scaling throughout. Rust staining. Narrow to wide vertical cracks; full length longitudinal crack observed on the arch rib extends down both abutments, full height. Delamination of concrete patches. Severe delamination and spalling on E abutment.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
		<input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None	
Repair poor concrete					
<b>Element Group:</b> Abutment <b>Length:</b> 9.35					
<b>Element Name:</b> Wingwalls <b>Width:</b>					
<b>Location:</b> NE, NW, SE, SW <b>Height:</b> 7.00					
<b>Material:</b> Cast-in-place concrete <b>Count:</b> 4					
<b>Element Type:</b> Reinforced Concrete <b>Total Quantity:</b> 261.80					
<b>Environment:</b> Moderate <b>Limited Inspection:</b> <input type="checkbox"/>					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	193.80	40.00	28.00
<b>Comments:</b>					
Spalls with exposed rebar and delamination at corners of walls. Light to medium scaling. Narrow pattern cracks. Narrow to wide cracks with wet staining and efflorescence. Wide cracks, delamination, and spalls with exposed rebar on patches and at base of NW wingwall.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
		<input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None	
Repair poor concrete					

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Accessories	<b>Length:</b>			
<b>Element Name:</b>	Signs	<b>Width:</b>			
<b>Location:</b>	North and South side of bridge	<b>Height:</b>			
<b>Material:</b>		<b>Count:</b>		9	
<b>Element Type:</b>		<b>Total Quantity:</b>		9.00	
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	5.00	2.00	2.00
<b>Comments:</b> Bridge Ices - 2 (Good); No Diving, Jumping or Swimming Sign - 1 (Good); Regulatory, information and direction signs - 4 (Trucks & Turning Lane in Fair; Parking & Arrow in Good). On NE wingwall - Caution Bikes (Poor); Slow (Poor)					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 18 Other Replace signs on NE WW			
<hr/>					
<b>Element Group:</b>	Accessories	<b>Length:</b>			
<b>Element Name:</b>	Utilities	<b>Width:</b>			
<b>Location:</b>	Bell ducts/Hydro lines below deck	<b>Height:</b>			
<b>Material:</b>	Plastic	<b>Count:</b>		8	
<b>Element Type:</b>		<b>Total Quantity:</b>		8.00	
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	0.00	8.00	0.00
<b>Comments:</b> Some ducts are disconnected and/or broken.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 18 Other Repair ducts			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Accessories	<b>Length:</b>			
<b>Element Name:</b>	Utilities	<b>Width:</b>			
<b>Location:</b>	Light poles on deck level, N/S deck fascia	<b>Height:</b>			
<b>Material:</b>	Steel	<b>Count:</b>		6	
<b>Element Type:</b>		<b>Total Quantity:</b>		6.00	
<b>Environment:</b>	Moderate	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	6.00	0.00	0.00
<b>Comments:</b> Electrical boxes in good condition, one box with narrow ck. Pothole in asphalt filled old box in N sidewalk.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Approaches					
<b>Element Name:</b> Approach Slabs					
<b>Location:</b> East and West					
<b>Material:</b> Cast-in-place concrete					
<b>Element Type:</b>					
<b>Environment:</b> Moderate					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	193.40	15.00	0.00
<b>Comments:</b> Not visible; assumed to be generally in good condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Approaches	<b>Length:</b>			
<b>Element Name:</b>	Drainage	<b>Width:</b>			
<b>Location:</b>	North and South sides of approaches	<b>Height:</b>			
<b>Material:</b>	Steel Post and Panel	<b>Count:</b>			4
<b>Element Type:</b>	Drain Pipes and Basins	<b>Total Quantity:</b>			4.00
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	4.00	0.00	0.00
<b>Comments:</b> Minor surface corrosion.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Approaches	<b>Length:</b>			6.00
<b>Element Name:</b>	Wearing Surface	<b>Width:</b>			17.37
<b>Location:</b>	North and South	<b>Height:</b>			
<b>Material:</b>	Asphalt	<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			208.40
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	133.40	45.00	30.00
<b>Comments:</b> Longitudinal and transver medium to wide sealed and unsealed cracks. Light wheel track rutting. Potholes at joints. W approach wearing surface has 6 full length sealed cracks.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Mill and resurface		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Approaches	<b>Length:</b>			6.00
<b>Element Name:</b>	Sidewalks and Medians	<b>Width:</b>			2.49
<b>Location:</b>	North and South	<b>Height:</b>			0.20
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>			4
<b>Element Type:</b>		<b>Total Quantity:</b>			59.80
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	45.80	10.00	4.00
<b>Comments:</b> Rust staining. Light scaling. Narrow to wide longitudinal and transverse cracks. Spalls and delamination at NW and SW approach.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Barrier					
<b>Element Name:</b> Barrier/Parapet Walls					
<b>Location:</b> North and South, Interior (Road) & Top Face					
<b>Material:</b> Cast-in-place concrete					
<b>Element Type:</b> Parapet wall w/single railing					
<b>Environment:</b> Severe					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	195.80	50.00	25.00
<b>Comments:</b> Length includes approaches. Narrow to wide vertical stained cracks. Severe abrasions on road face of S parapet. Delamination at multiple post locations on S parapet. Light scaling and rust staining throughout. Stained pattern cracks throughout. Longitudinal cracks/delamination at top face. Large spall at SW parapet. Large delamination on S wall @ midspan.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair spalled and delaminated concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Barrier	<b>Length:</b>	142.50		
<b>Element Name:</b>	Barrier/Parapet Walls	<b>Width:</b>			
<b>Location:</b>	North and South, Exterior (Sidewalk)	<b>Height:</b>	0.50		
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>	2		
<b>Element Type:</b>	Parapet wall w/single railing	<b>Total Quantity:</b>	142.50		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	69.50	50.00	23.00
<b>Comments:</b>					
Length includes approaches. Narrow to wide vertical stained cracks. Delamination at multiple post locations on S parapet. Light scaling and rust staining throughout. Stained pattern cracks throughout. Large spall with exposed rebar @ SW.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair spalled and delminated concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Barrier					
<b>Element Name:</b> Railing Systems					
<b>Location:</b> North and South Sidewalk Exterior Railing					
<b>Material:</b> Aluminum					
<b>Element Type:</b> Aluminum Post and Panels					
<b>Environment:</b> Severe					
<b>Protection System:</b> Hot dip galvanizing					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	273.00	7.00	5.00
<b>Comments:</b>					
Length includes approaches. Isolated permanent deformations of spindles. Grout disintegrated at several railing post base plates. Severe deformation and missing spindle at SE.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 03 Bridge handrail maintenance Repair railing			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Barrier	<b>Length:</b>	142.50		
<b>Element Name:</b>	Railing Systems	<b>Width:</b>			
<b>Location:</b>	North and South Railing on top of Parapet	<b>Height:</b>			
<b>Material:</b>	Aluminum	<b>Count:</b>	2		
<b>Element Type:</b>	Aluminum Post and Panels	<b>Total Quantity:</b>	285.00		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>	Hot dip galvanizing				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	0.00	0.00	244.00	35.00	6.00
<b>Comments:</b> Length includes approaches. Abrasions from vehicle impact. Damaged railing splice and weld crack between post and base plate on N parapet railing at NE joint. Loose top rail connection at NE. Missing cap on SE.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 03 Bridge handrail maintenance Repair railing			
<b>Element Group:</b>	Coatings	<b>Length:</b>	142.50		
<b>Element Name:</b>	Railing Systems/Hand Railings	<b>Width:</b>			
<b>Location:</b>	North and South Sidewalk Exterior Railings	<b>Height:</b>	1.07		
<b>Material:</b>	Other	<b>Count:</b>	2		
<b>Element Type:</b>	Hot Dip Galvanizing	<b>Total Quantity:</b>	305.00		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>	Hot Dip Galvanizing				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	265.00	30.00	10.00
<b>Comments:</b> Light abrasions, Light flaking and discolouration of grey to grey-black throughout.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Coatings	<b>Length:</b>			142.50
<b>Element Name:</b>	Railing Systems/Hand Railings	<b>Width:</b>			
<b>Location:</b>	North/South Railings on top of Parapet Walls	<b>Height:</b>			0.60
<b>Material:</b>	Other	<b>Count:</b>			2
<b>Element Type:</b>	Hot Dip Galvanizing	<b>Total Quantity:</b>			171.00
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>	Hot Dip Galvanizing				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	146.00	20.00	5.00
<b>Comments:</b> Light abrasions from vehicle impact and light coating discolouration.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Deck	<b>Length:</b>			130.50
<b>Element Name:</b>	Deck Top	<b>Width:</b>			19.50
<b>Location:</b>	Top of deck	<b>Height:</b>			
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			1
<b>Element Type:</b>	Cast-in-place Concrete on Supports	<b>Total Quantity:</b>			2544.80
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input checked="" type="checkbox"/>
<b>Protection System</b>	Waterproofing and Asphalt				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	2294.80	250.00	0.00
<b>Comments:</b> Not visible. Bottom-up defects such as map cracks and pot holes observed on wearing surface. Assumed to be generally in good condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Deck	<b>Length:</b>			
<b>Element Name:</b>	Drainage System	<b>Width:</b>			
<b>Location:</b>	North and South	<b>Height:</b>			
<b>Material:</b>	Steel	<b>Count:</b>			4
<b>Element Type:</b>	Metal Drain Pipes	<b>Total Quantity:</b>			4.00
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>	Hot dip galvanizing				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	4.00	0.00	0.00
<b>Comments:</b> Light corrosion and loss of protective coating.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Deck	<b>Length:</b>			126.50
<b>Element Name:</b>	Soffit - Thin Slab	<b>Width:</b>			2.74
<b>Location:</b>	Exterior (Overhangs)	<b>Height:</b>			0.31
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			770.40
<b>Environment:</b>	Moderate	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	645.40	75.00	50.00
<b>Comments:</b> Stained and unstained medium to wide cracks, some with efflorescence. Delamination and spalls with exposed rebar. Honeycombing. Wet areas.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Deck	<b>Length:</b>			2.00
<b>Element Name:</b>	Soffit - Thin Slab	<b>Width:</b>			22.86
<b>Location:</b>	Ends	<b>Height:</b>			
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			91.40
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	56.40	20.00	15.00
<b>Comments:</b> Spalls with exposed corroded rebar. Wet and stained due to joints leaking at NE & NW corners of deck. Rust staining on thickened ends of deck soffit.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<hr/>					
<b>Element Group:</b>	Deck	<b>Length:</b>			126.50
<b>Element Name:</b>	Soffit - Thin Slab	<b>Width:</b>			17.37
<b>Location:</b>	Interior	<b>Height:</b>			
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			1
<b>Element Type:</b>		<b>Total Quantity:</b>			2197.30
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	2119.30	60.00	18.00
<b>Comments:</b> Stained hairline cracks. Spalls and delamination.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Deck	<b>Length:</b>			130.50
<b>Element Name:</b>	Wearing Surface	<b>Width:</b>			17.37
<b>Location:</b>	Top of deck	<b>Height:</b>			0.00
<b>Material:</b>	Asphalt	<b>Count:</b>			1
<b>Element Type:</b>		<b>Total Quantity:</b>			2266.80
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	1186.80	600.00	480.00
<b>Comments:</b>					
Medium to wide longitudinal and transverse unsealed cracks throughout. Light raveling. Light wheel track rutting. Light to medium map cracks and potholes at joints.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Patch, waterproof, pave		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Joints	<b>Length:</b>			20.11
<b>Element Name:</b>	Armouring/Retaining Devices	<b>Width:</b>			
<b>Location:</b>	Each End of the Bridge	<b>Height:</b>			
<b>Material:</b>	Steel	<b>Count:</b>			8
<b>Element Type:</b>		<b>Total Quantity:</b>			160.90
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>	Hot dip galvanizing				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	6.90	84.00	70.00
<b>Comments:</b>					
Permanent deformations at eastbound lanes. Light corrosion.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Joints	<b>Length:</b>			17.37
<b>Element Name:</b>	Concrete End Dams	<b>Width:</b>			0.30
<b>Location:</b>	Each End of the Bridge	<b>Height:</b>			
<b>Material:</b>	Concrete	<b>Count:</b>			4
<b>Element Type:</b>		<b>Total Quantity:</b>			20.80
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	6.80	7.00	7.00
<b>Comments:</b> Light to severe scaling throughout. Shallow spalls throughout.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Joints <b>Length:</b> 20.11					
<b>Element Name:</b> Seals/Sealants <b>Width:</b>					
<b>Location:</b> Each End of Bridge <b>Height:</b>					
<b>Material:</b> Other <b>Count:</b> 2					
<b>Element Type:</b> Compressed Seal <b>Total Quantity:</b> 2.00					
<b>Environment:</b> Severe <b>Limited Inspection:</b> <input type="checkbox"/>					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	0.00	2.00	0.00
<b>Comments:</b> Unable to inspect seals for rips and tears due to accumulation of debris. Signs of leakage on substructure indicate that seals are torn in some places and could be in fair to poor condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 02 Bridge cleaning Clean joint seals annually			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Embankments and Streams	<b>Length:</b>			
<b>Element Name:</b>	Embankments	<b>Width:</b>			
<b>Location:</b>	NE, NW, SE, SW	<b>Height:</b>			
<b>Material:</b>		<b>Count:</b>			4
<b>Element Type:</b>		<b>Total Quantity:</b>			4.00
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>	Other				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	2.00	2.00	0.00
<b>Comments:</b> The west embankment slopes are steep, but are generally well protected.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years 18 Other Tree/vegetation maintenance			
<b>Element Group:</b>	Embankments and Streams	<b>Length:</b>			
<b>Element Name:</b>	Slope Protection	<b>Width:</b>			
<b>Location:</b>	All quadrants E/W Abutments	<b>Height:</b>			
<b>Material:</b>		<b>Count:</b>			4
<b>Element Type:</b>		<b>Total Quantity:</b>			4.00
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>	Other				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	0.00	4.00	0.00
<b>Comments:</b> Trees have displaced rocks on W embankments.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Embankments and Streams	<b>Length:</b>			
<b>Element Name:</b>	Streams and Waterways	<b>Width:</b>			
<b>Location:</b>	All	<b>Height:</b>			
<b>Material:</b>		<b>Count:</b>			1
<b>Element Type:</b>		<b>Total Quantity:</b>			1.00
<b>Environment:</b>		<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	All	0.00	1.00	0.00	0.00
<b>Comments:</b>					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Foundations	<b>Length:</b>			
<b>Element Name:</b>	Foundation (Below ground level)	<b>Width:</b>			
<b>Location:</b>	Below Abutments and Piers	<b>Height:</b>			
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			4
<b>Element Type:</b>	Spread	<b>Total Quantity:</b>			4.00
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input checked="" type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	N/A	0.00	0.00	4.00	0.00
<b>Comments:</b>					
Assumed in fair condition based on age of original substructure.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Piers	<b>Length:</b>			3.65
<b>Element Name:</b>	Shafts/Columns/Pile Bents	<b>Width:</b>			16.60
<b>Location:</b>	East and West Pier, Inside Walls	<b>Height:</b>			6.70
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			4
<b>Element Type:</b>	Concrete Shafts, Pier Walls	<b>Total Quantity:</b>			542.70
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	417.70	70.00	55.00
<b>Comments:</b>					
Staining and wet areas. Honeycombing. Severe scaling, delamination and spalling. Medium to wide cracks. Parsons 2014: Engaged columns (or pilaster as referred on the dwg.) were observed to have severe spalls, exposed reinforcement, and medium to wide cracks.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete; seal cracks		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Piers					
<b>Element Name:</b> Shafts/Columns/Pile Bents					
<b>Location:</b> East and West Pier, Outside Walls					
<b>Material:</b> Cast-in-place Concrete					
<b>Element Type:</b> Concrete Shafts, Pier Walls					
<b>Environment:</b> Benign					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	966.50	225.00	200.00
<b>Comments:</b>					
Stained and unstained medium to wide cracks. Medium pattern cracks. Severe delamination and spalls. Disintegration. Patches from previous rehab noted. Light to severe scaling. Honeycombing and wet areas. Longitudinal cracks observed on the arch ribs continue full height on the vertical walls.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete; seal cracks		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Sidewalks /Curbs	<b>Length:</b>			130.50
<b>Element Name:</b>	Sidewalks and Medians	<b>Width:</b>			2.49
<b>Location:</b>	North and South	<b>Height:</b>			0.20
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			649.90
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	519.90	110.00	20.00
<b>Comments:</b> Rust staining. Light scaling. Isolated delamination. Narrow to wide longitudinal and transverse cracks. Trip hazard at NW patched location. Severe delamination on N and S side approx. over centre span and west span.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Trusses/Arches					
<b>Element Name:</b>	Bottom Chords	<b>Length:</b>			128.16
<b>Location:</b>	Arch Rib, Bottom and Exterior Face	<b>Width:</b>			17.38
<b>Material:</b>	Cast-in-place concrete	<b>Height:</b>			1.08
<b>Element Type:</b>		<b>Count:</b>			1
<b>Environment:</b>	Benign	<b>Total Quantity:</b>			2504.20
<b>Protection System</b>		<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	2154.20	190.00	160.00
<b>Comments:</b> Stained and unstained medium to wide cracks, some with efflorescence. Full length longitudinal crack extending down supports. Severe delamination and spalls. Previous patches noted. Light to severe scaling. Honeycombing and wet areas. Crack gauges on all three spans.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete; seal cracks		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 131**

ELEMENT DATA					
<b>Element Group:</b>	Trusses/Arches	<b>Length:</b>			129.36
<b>Element Name:</b>	Bottom Chords	<b>Width:</b>			17.38
<b>Location:</b>	Arch Rib, Top Face	<b>Height:</b>			
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>			1
<b>Element Type:</b>		<b>Total Quantity:</b>			2248.30
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	1638.30	315.00	295.00
<b>Comments:</b>					
Localized poor areas, specifically at the cells near the abutments and piers. Severe scaling, medium to wide cracks, spalls and delamination. Localized exposed rebar. Medium to wide longitudinal crack running almost through entire length of bridge. Narrow to medium pattern, transverse and longitudinal cracks. Spalls and delamination on patches.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete; seal cracks		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Trusses/Arches <b>Length:</b> 0.35					
<b>Element Name:</b> Verticals/Diagonals <b>Width:</b> 17.38					
<b>Location:</b> Spandrel Columns <b>Height:</b> 2.62					
<b>Material:</b> Cast-in-Place Concrete <b>Count:</b> 48					
<b>Element Type:</b> Rectangular Solid <b>Total Quantity:</b> 4459.50					
<b>Environment:</b> Benign <b>Limited Inspection:</b> <input type="checkbox"/>					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	4216.50	128.00	115.00
<b>Comments:</b>					
Covered with graffiti. Spalls and delamination at the bottom of many spandrel column connections with arch rib. Spalls and delamination of patches. Light to severe scaling. Efflorescence staining. Hairline to wide horizontal and vertical cracks. Cracks on arch rib continue vertically on spandrels. Wide cracks/delamination/spall on N & S faces of 3 spandrels in W span.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years Repair poor concrete; seal cracks		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**BRIDGE**

Structure Name: Lorne Bridge-Arch  
 Structure Number: 131

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

Structure ID: 131

Element Group	Element Name	Sub-Element	Unit (Qty.)	Total Element Qty.	Element Qty. in Excellent Condition (1.00)	Element Qty. in Good Condition (0.75)	Element Qty. in Fair Condition (0.4)	Element Qty. in Poor Condition (0)	Element Condition Index	Estimated Life Span	Estimated Remaining Service Life (ERSL)*	Performance Deficiency**	Maintenance Need**
Abutment	Abutment Walls		Sq.m	390.20	0.00	264.20	77.00	49.00	59	40	23	00	00
Accessories	Wingwalls		Sq.m	261.80	0.00	193.80	40.00	28.00	62	40	25	00	00
	Signs		Each	9.00	0.00	5.00	2.00	2.00	N/A	N/A	N/A	00	18
Approaches	Utilities		Each	8.00	0.00	0.00	8.00	0.00	N/A	N/A	N/A	00	18
	Utilities		Each	6.00	0.00	6.00	0.00	0.00	N/A	N/A	N/A	00	00
	Approach Slabs		Sq.m	208.40	0.00	193.40	15.00	0.00	72	25	18	00	00
	Drainage		Each	4.00	0.00	4.00	0.00	0.00	N/A	15	N/A	00	00
Barrier	Wearing Surface		Sq.m	208.40	0.00	133.40	45.00	30.00	57	15	8	00	00
	Sidewalks and Medians		Sq.m	59.80	0.00	45.80	10.00	4.00	64	35	22	00	00
	Barrier/Parapet Walls		Sq.m	270.80	0.00	195.80	50.00	25.00	62	35	22	00	00
	Barrier/Parapet Walls		Sq.m	142.50	0.00	69.50	50.00	23.00	51	35	18	00	00
Coatings	Railing Systems		m	285.00	0.00	273.00	7.00	5.00	73	35	25	00	03
	Railing Systems		m	285.00	0.00	244.00	35.00	6.00	69	35	24	00	03
	Railing Systems/Hand Railings		Sq.m	305.00	0.00	265.00	30.00	10.00	69	20	14	00	00
	Railing Systems/Hand Railings		Sq.m	171.00	0.00	146.00	20.00	5.00	69	20	14	00	00
Deck	Deck Top		Sq.m	2544.80	0.00	2294.80	250.00	0.00	72	25	18	00	00
	Drainage System		Each	4.00	0.00	4.00	0.00	0.00	N/A	15	N/A	00	00
Joints	Soffit - Thin Slab		Sq.m	770.40	0.00	645.40	75.00	50.00	67	50	33	00	00
	Soffit - Thin Slab		Sq.m	91.40	0.00	56.40	20.00	15.00	55	50	28	00	00
	Soffit - Thin Slab		Sq.m	2197.30	0.00	2119.30	60.00	18.00	73	50	37	00	00
	Wearing Surface		Sq.m	2266.80	0.00	1186.80	600.00	480.00	50	15	7	00	00
Embankments and Streams	Armouring/Retaining Devices		m	160.90	0.00	6.90	84.00	70.00	24	25	6	00	00
	Concrete End Dams		Sq.m	20.80	0.00	6.80	7.00	7.00	38	25	9	00	00
Foundations	Seals/Sealants		Each	2.00	0.00	0.00	2.00	0.00	N/A	25	N/A	00	02
	Embankments		Each	4.00	0.00	2.00	2.00	0.00	N/A	N/A	N/A	00	18
	Slope Protection		Each	4.00	0.00	0.00	4.00	0.00	N/A	N/A	N/A	00	00
	Streams and Waterways		All	1.00	0.00	1.00	0.00	0.00	N/A	N/A	N/A	00	00
Piers	Foundation (Below ground level)		N/A	4.00	0.00	4.00	0.00	0.00	N/A	N/A	N/A	00	00
	Shafts/Columns/Pile Bents		Sq.m	542.70	0.00	417.70	70.00	55.00	63	50	31	00	00
Sidewalks /Curbs	Shafts/Columns/Pile Bents		Sq.m	1391.50	0.00	966.50	225.00	200.00	59	50	29	00	00
	Sidewalks and Medians		Sq.m	649.90	0.00	519.90	110.00	20.00	67	35	23	00	00
Trusses/Arches	Bottom Chords		Sq.m	2504.20	0.00	2154.20	190.00	160.00	68	35	24	00	00
	Bottom Chords		Sq.m	2248.30	0.00	1638.30	315.00	295.00	60	35	21	00	00
	Verticals/Diagonals		Sq.m	4459.50	0.00	4216.50	128.00	115.00	72	35	25	00	00

64.9

Condition Index

\*\* OSIM codes



*Photo 1 – North Elevation*



*Photo 2 – South Elevation*



*Photo 3 – Wearing surface, looking West*



*Photo 4 – West Expansion Joint*





*Photo 5 – South Sidewalk, Looking West*



*Photo 6 – East Abutment*



*Photo 7 – NE Wingwall*



*Photo 8 – West Pier, North and East Face*





*Photo 9 – Upstream (North)*



*Photo 10 – Downstream (South)*



*Photo 11 – Exterior Barrier Wall, Spall on Pedestal (Typ)*



*Photo 12 – South Exterior Railing, Impact Damage and Missing Spindle*



*Photo 13 – North Exterior Railing, Typical Spindle Repair*



*Photo 14 – North Sidewalk, Ponding*





*Photo 15 – North Sidewalk, Wide Transverse Cracks(Typ)*



*Photo 16 – Light Rusting of Bolts*



*Photo 17 – Interior Barrier Wall Railing, SW Approach, Impact Damage*



*Photo 18 – South Interior Barrier, SE Approach Expansion Joint, Spall & Delamination*



*Photo 19 – South Interior Barrier Wall, Wide Horizontal & Vertical Stained Cracks, Delaminations and Spalls*



*Photo 20 – South Interior Barrier Wall, Inter Face, Wide Horizontal & Vertical Stained Cracks, Delaminations and Spalls*





*Photo 21 - Regulatory, Info & Direction Signs*



*Photo 22 – East Abutment, NE Corner, Spalls & Delamination*





*Photo 23 - East Abutment, Wide Vertical Crack, Full Height*



*Photo 24 - East Pier, Severe Scaling & Erosion, Cracks with Efflorescence*



*Photo 25 - West Pier, Severe Scaling & Erosion, Cracks with Efflorescence*



*Photo 26 - NW Wingwall, Delamination & Spall*



*Photo 27 - 27. SW Wingwall, Spall with Exposed Rebar*



*Photo 28 - North Overhang, Delaminations & Spalls with Exposed Rebar*



*Photo 29 - Arch Rib, Bottom Face, & East Abutment, SE Corner, Spalls*



*Photo 30 - Arch Rib, Bottom Face, Middle Span, Delaminations*





*Photo 31 - Arch Rib, Bottom Face, East Span, Wide Longitudinal Crack*



*Photo 32 - Utilities @ Southeast, Ducts Disconnected & Broken*



*Photo 33 - Spandrel Column, 2nd from East, SE Corner, Delamination*



*Photo 34 - Centre Span, South Face of Bottom Chord, Spalls & Delaminations*



*Photo 35 - Centre Span, Wide Cracks & Suspected Delamination of Bottom Chord, Top & North Face*



*Photo 36 - East Span, Delamination on West Face of 1st Spandrel, Spalls on West Face of 2nd Spandrel*



*Photo 37 - West Span, Cracks & Suspected Delamination of Bottom Chord, North Face*



*Photo 38 - West Span, Delamination on North Face of Bottom Chord & North Face of Centre Spandrel*





*Photo 39 - West Span, Spalls with Exposed Rebar & Delamination of Bottom Chord, S Face, & Centre 3 Spandrels*



*Photo 40 - Bird Nest, East Pier, South Face*

SUMMARY ACTION REPORT

ADDITIONAL INVESTIGATIONS	Priority	Inspection Date
<b>Investigations, Inspections, Surveys Recommended</b>		
Biennial OSIM	Normal	17-Dec-2021

REPAIR AND REHABILITATION REQUIRED	Priority		Comments
	6-10 Years	1 - 5 Years	
<b>Repair and Rehabilitation Required</b>			
East Abutment		X	Rehabilitate
West Abutment		X	Rehabilitate
Approach Wearing Surface		X	Rehabilitate
Deck top		X	Rehabilitate
Deck Soffit Interior		X	Rehabilitate
Deck Soffit Exterior		X	Rehabilitate
Deck Soffit Ends		X	Rehabilitate
Deck Wearing Surface		X	Rehabilitate
Concrete End Dams		X	Rehabilitate
Armoring/Retaining Device		X	Rehabilitate
Seals/Sealants		X	Replace
Retaining Walls		X	Replace

MAINTENANCE NEEDS	Priority		
	2 Years	1 Year	Urgent
<b>Maintenance Needs</b>			
Utilities - Other - Replace missing bolts	X		

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

INVENTORY DATA:			
Structure Name	<u>Lorne Bridge-Girder</u>		
Main Hwy/Road #	Under Structure:	<input type="checkbox"/> Navigable Water	<input type="checkbox"/> Non-Navigable Water
		<input type="checkbox"/> Rail	<input type="checkbox"/> Road <input checked="" type="checkbox"/> Pedestrian <input type="checkbox"/> Other
Road Name:	On Structure:	<input type="checkbox"/> Rail	<input checked="" type="checkbox"/> Road <input type="checkbox"/> Pedestrian <input type="checkbox"/> Other
	<u>Colborne Street West</u>		
Structure Location	<u>10m S of Brant Ave</u>		
Latitude	<u>43.137847</u>	Longitude	<u>-80.269361</u>
Owner(s)	<u>City of Brantford</u>	Heritage Designation	<input type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig.
			<input type="checkbox"/> Desig./not List <input checked="" type="checkbox"/> Desig. & List
MTO Region	<u>Southwestern</u>	Road Class	<input type="checkbox"/> Freeway <input checked="" type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local
MTO District	<u>-</u>	Posted Speed	<u>50 km/h</u> No. of Lanes <u>5</u>
Old County	<u>Brant</u>	AADT	<u>27133</u> % Trucks <u>10</u>
Geographic Twp.	<u>-</u>	Special Routes	<input checked="" type="checkbox"/> Transit <input type="checkbox"/> Truck <input checked="" type="checkbox"/> School <input type="checkbox"/> Bicycle
Structure Type	<u>Box Beams or Girders</u>	Detour Length Around Structure	<u>5.00</u> (km)
Total Deck Length	<u>19.81</u> (m)	Fill on Structure	<u>0.10</u> (m)
Overall Str. Width	<u>24.17</u> (m)	Skew Angle	<u>0</u> (Degrees)
Total Deck Area	<u>478.81</u> (m2)	Direction of Structure	<u>E - W</u>
Roadway Width	<u>18.66</u> (m)	No. of Spans	<u>1</u>
Span Lengths	<u>19.80</u> (m)		
Overall Condition Rating	<u>Fair</u>		
Bridge Condition Index (BCI)	<u>63.7</u>		

HISTORICAL DATA			
Year Built	<u>1924</u>	Last OSIM Inspection	<u>2017</u>
Year of Last Major Rehab.	<u>1980</u>	Last Enhanced OSIM Inspection	<u>2014</u>
Current Load Limit	<u>-</u> (tonnes)	Last Bridge Master Inspection	<u>-</u>
Load Limit By-Law #	<u>-</u>	Last Evaluation	<u>-</u>
By-Law Expiry Date	<u>-</u>	Last Underwater Inspection	<u>-</u>
Min. Vertical Clearance	<u>-</u> (m)	Last Condition Survey	<u>-</u>
<b>Rehabilitation History: (Date / Description)</b>			
<u>12/31/1980 - Deck Replacement</u>			

Scheduled Improvements:	
Regional Priority Number _____	Programmed Work Year _____
Nature of Program Work:	

Appraisal Indices:	Comments
Fatigue	
Seismic	
Scour	
Flood	
Geometrics	
Barrier	
Curb	
Load Capacity	

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132

FIELD INSPECTION INFORMATION	
Date of Inspection:	17-Dec-2019
Inspector:	Sabrina Dexter, Transportation Structures Engineer
Others in Party:	Akhilesh Prabhu, Transportation Structures Intern
Access Equipment Used:	Binoculars, sounding hammer, measuring tape, digital camera
Weather:	Overcast
Temperature:	-3°C
Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM

ADDITIONAL INVESTIGATION REQUIRED	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:				\$ -
Material Condition Survey				\$ -
Detailed Deck Condition Survey:				\$ -
Non-destructive Delamination Survey of Asphalt- Covered Deck:				\$ -
Concrete Substructure Condition Survey:				\$ -
Detailed Coating Condition Survey:				\$ -
Detailed Timber Investigation:				\$ -
Underwater Investigation:				\$ -
Fatigue Investigation:				\$ -
Seismic Investigation:				\$ -
Structure Evaluation:				\$ -
Monitoring				\$ -
Monitoring of Deformations, Settlement and Movements:				\$ -
Monitoring Crack Widths:				\$ -
<b>Load Posting – Estimated Load Limit</b>			<b>Total Cost</b>	\$ -
<b>Investigation Notes:</b>				

OVERALL STRUCTURAL NOTES:	
Recommended Work on Structure:	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 Years <input type="checkbox"/> 6 to 10 Years
Overall Comments:	
Structure is generally in fair condition, with cracks, delaminations and spalls on the abutment walls, ballast walls, barrier walls, deck soffit and girder ends. Wide sealed and unsealed cracks on the wearing surface and deteriorations on the concrete end dams. The bridge is recommended to undergo rehabilitation in 1-5 years. Concrete patch repair techniques are recommended and the retaining walls that are extensively deteriorated should be replaced.	
Date of Next Inspection:	17-Dec-2021

**Suspected Performance Deficiencies**

- |  |  |                              |
|--|--|------------------------------|
| 00 None  | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 01 Load carrying capacity                          | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotation) | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 03 Continuing settlement                           | 09 Rough riding surface                  | 15 Unstable embankments      |
| 04 Continuing movements                            | 10 Surface ponding                       | 16 Other                     |
| 05 Seized bearings                                 | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                               |  |
|--------------------------------------|-------------------------------|--|
| 01 Lift and swing bridge maintenance | 07 Repair of structural steel | 13 Erosion control at bridges            |
| 02 Bridge cleaning                   | 08 Repair of bridge concrete  | 14 Concrete sealing                      |
| 03 Bridge handrail maintenance       | 09 Repair of bridge timber    | 15 Rout and seal                         |
| 04 Painting steel bridge structures  | 10 Bailey bridges maintenance | 16 Bridge deck drainage                  |
| 05 Bridge deck joint repair          | 11 Animal/pest control        | 17 Scaling (loose Concrete or ACR Steel) |
| 06 Bridge bearing maintenance        | 12 Bridge surface repair      | 18 Other                                 |

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Abutment	<b>Length:</b>	20.59		
<b>Element Name:</b>	Abutment Walls	<b>Width:</b>	0.99		
<b>Location:</b>	East Abutment	<b>Height:</b>	1.38		
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>	1		
<b>Element Type:</b>	Abutment Stem	<b>Total Quantity:</b>	31.00		
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>	<input checked="" type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	21.40	8.10	1.50
<b>Comments:</b>					
Includes area of abutment and bearing pedestal. Inaccessible due to presence of chain link fence. Comments are carried forward from previous inspection. Medium cracks and delamination noted. Medium scaling, honeycombing and wet areas noted. Localized cracks and light scaling of east abutment bearing pedestal. Repair deteriorated concrete and seal cracks.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Abutment	<b>Length:</b>	19.51		
<b>Element Name:</b>	Abutment Walls	<b>Width:</b>	0.99		
<b>Location:</b>	West Abutment	<b>Height:</b>	7.11		
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>	1		
<b>Element Type:</b>	Abutment Stem	<b>Total Quantity:</b>	141.30		
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	117.10	18.10	6.10
<b>Comments:</b>					
Includes area of abutment and bearing pedestal. Medium to wide cracks and delamination with spalls. Light to medium scaling and wet areas. Wide horizontal crack at south west bearing pedestal. Repair deteriorated concrete and seal cracks.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Abutment	<b>Length:</b>	20.59		
<b>Element Name:</b>	Ballast Walls	<b>Width:</b>	0.46		
<b>Location:</b>	East and West	<b>Height:</b>	1.34		
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>	2		
<b>Element Type:</b>		<b>Total Quantity:</b>	53.90		
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>	<input checked="" type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	47.40	5.50	1.00
<b>Comments:</b>					
West Ballast wall was not visible during time of inspection so comment has been carried forward. No visible defects observed. East ballast wall; some unstained and stained medium cracks and wet areas and shallow spall with exposed rebar at north east end.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Abutment <b>Length:</b> 0.00					
<b>Element Name:</b> Bearings <b>Width:</b> 0.00					
<b>Location:</b> East and West <b>Height:</b> 0.00					
<b>Material:</b> Elastomeric Pad <b>Count:</b> 14					
<b>Element Type:</b> <b>Total Quantity:</b> 14.00					
<b>Environment:</b> Benign <b>Limited Inspection:</b> <input checked="" type="checkbox"/>					
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	14.00	0.00	0.00
<b>Comments:</b>					
Not visible. Comments carried forward from previous inspection. Light bulging of bearings of east bearings. Narrow cracks and light bulding of west bearings.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Abutment	<b>Length:</b>	5.72		
<b>Element Name:</b>	Wingwalls	<b>Width:</b>	0.76		
<b>Location:</b>	NE, SE	<b>Height:</b>	0.00		
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>	2		
<b>Element Type:</b>	Reinforced Concrete	<b>Total Quantity:</b>	18.80		
<b>Environment:</b>	Moderate	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	16.70	2.10	0.00
<b>Comments:</b> Medium width cracks and wet areas.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years			
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None			
<b>Element Group:</b>	Accessories	<b>Length:</b>	0.00		
<b>Element Name:</b>	Utilities	<b>Width:</b>	0.00		
<b>Location:</b>	Bell Ducts/Hydro lines, below deck	<b>Height:</b>	0.00		
<b>Material:</b>	Plastic	<b>Count:</b>	2		
<b>Element Type:</b>		<b>Total Quantity:</b>	2.00		
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	0.00	2.00	0.00
<b>Comments:</b> Some ducts are disconnected and/or broken.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years			
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None			



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Accessories	<b>Length:</b>	0.00		
<b>Element Name:</b>	Utilities	<b>Width:</b>	0.00		
<b>Location:</b>	Light poles on deck level, SE and NW	<b>Height:</b>	0.00		
<b>Material:</b>	Steel	<b>Count:</b>	2		
<b>Element Type:</b>		<b>Total Quantity:</b>	2.00		
<b>Environment:</b>	Moderate	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	2.00	0.00	0.00
<b>Comments:</b>					
Comments carried forward from previous inspection as element covered in snow in 2019. Missing bolts on electrical box covers on the north sidewalk. Plywood cover in poor condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years 18 Other			
<b>Element Group:</b> Approaches					
<b>Element Name:</b> Approach Slabs					
<b>Location:</b> East Approach					
<b>Material:</b> Cast-in-place concrete					
<b>Environment:</b> Moderate					
<b>Protection System</b>					
<b>Condition Data:</b>					
	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	208.20	15.00	0.00
<b>Comments:</b>					
Not visible. Condition based on previous inspection and condition of wearing surface.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

ELEMENT DATA					
<b>Element Group:</b>	Approaches	<b>Length:</b>		6.10	
<b>Element Name:</b>	Wearing Surface	<b>Width:</b>		18.60	
<b>Location:</b>	East	<b>Height:</b>		0.00	
<b>Material:</b>	Asphalt	<b>Count:</b>		1	
<b>Element Type:</b>		<b>Total Quantity:</b>		113.46	
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	68.46	30.00	15.00
<b>Comments:</b> Wide unsealed transverse and longitudinal cracks on wearing surface. Potholes noted at ends, with some patched.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
<input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years				00 None	
ELEMENT DATA					
<b>Element Group:</b>	Approaches	<b>Length:</b>		6.00	
<b>Element Name:</b>	Sidewalks and Medians	<b>Width:</b>		2.54	
<b>Location:</b>	North and South	<b>Height:</b>		0.28	
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>		4	
<b>Element Type:</b>		<b>Total Quantity:</b>		67.70	
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	62.70	4.00	1.00
<b>Comments:</b> Light scaling noted. Narrow to medium longitudinal and transverse cracks noted throughout. Shallow spalls noted.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years				00 None	

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

ELEMENT DATA					
<b>Element Group:</b>	Barrier	<b>Length:</b>	20.55		
<b>Element Name:</b>	Barrier/Parapet Walls	<b>Width:</b>	0.20		
<b>Location:</b>	North and South, Exterior	<b>Height:</b>	0.50		
<b>Material:</b>	Cast-in-Place Concrete	<b>Count:</b>	2		
<b>Element Type:</b>		<b>Total Quantity:</b>	20.60		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	14.10	6.00	0.50
<b>Comments:</b>					
Narrow to wide vertical cracks with staining and moisture. Light scaling throughout. Narrow to medium wet map cracks. Shallow spall noted at south west.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years			
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None			
<b>Element Group:</b>	Barrier	<b>Length:</b>	20.55		
<b>Element Name:</b>	Barrier/Parapet Walls	<b>Width:</b>	0.20		
<b>Location:</b>	North and South, Interior	<b>Height:</b>	0.50		
<b>Material:</b>	Cast-in-Place Concrete	<b>Count:</b>	2		
<b>Element Type:</b>		<b>Total Quantity:</b>	28.80		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	22.70	5.70	0.40
<b>Comments:</b>					
Narrow to wide vertical cracks with staining and moisture. Light scaling and rust staining throughout. Wet narrow to medium map cracks. Several spalls with exposed corroded rebar at north east end.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years			
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Barrier	<b>Length:</b>	20.55		
<b>Element Name:</b>	Hand Railings	<b>Width:</b>	0.00		
<b>Location:</b>	North and South	<b>Height:</b>	0.00		
<b>Material:</b>	Aluminium	<b>Count:</b>	2		
<b>Element Type:</b>	Aluminium Post and Aluminium Panels	<b>Total Quantity:</b>	41.10		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	35.10	5.00	1.00
<b>Comments:</b> Abrasions from vehicle impact and localized deformations.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Barrier	<b>Length:</b>	27.13		
<b>Element Name:</b>	Railing Systems	<b>Width:</b>	0.00		
<b>Location:</b>	North and South	<b>Height:</b>	1.07		
<b>Material:</b>	Aluminium	<b>Count:</b>	2		
<b>Element Type:</b>	Aluminium Post and Aluminium Panels	<b>Total Quantity:</b>	54.30		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	54.30	0.00	44.30	5.00
<b>Comments:</b> In good condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132

ELEMENT DATA					
<b>Element Group:</b>	Beams/ MLEs		<b>Length:</b>	16.20	
<b>Element Name:</b>	Girders		<b>Width:</b>	1.22	
<b>Location:</b>	Middle		<b>Height:</b>	0.99	
<b>Material:</b>	Precase Concrete		<b>Count:</b>	7	
<b>Element Type:</b>	Box/Trapezoidal		<b>Total Quantity:</b>	363.00	
<b>Environment:</b>	Benign		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	360.50	1.50	1.00
<b>Comments:</b> Moisture stains noted. Delmination on exterior face of north girder.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b> <input type="checkbox"/> Rehab <input type="checkbox"/> 1 - 5 Years			<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		
<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None					
<b>Element Group:</b>	Beams/ MLEs		<b>Length:</b>	2.00	
<b>Element Name:</b>	Girders		<b>Width:</b>	1.22	
<b>Location:</b>	Ends		<b>Height:</b>	0.99	
<b>Material:</b>	Precast Concrete		<b>Count:</b>	14	
<b>Element Type:</b>	Box/Trapezoidal		<b>Total Quantity:</b>	89.70	
<b>Environment:</b>	Benign		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	86.70	2.00	1.00
<b>Comments:</b> Shallow spalls and wet areas noted. Wide vertical cracks and suspected delamination.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b> <input type="checkbox"/> Rehab <input type="checkbox"/> 1 - 5 Years			<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		
<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None					

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Beams/ MLEs	<b>Length:</b>			2.00
<b>Element Name:</b>	Diaphragms	<b>Width:</b>			0.31
<b>Location:</b>	Between Girders	<b>Height:</b>			0.76
<b>Material:</b>	Cast-in-place-Concrete	<b>Count:</b>			12
<b>Element Type:</b>	Rectangular-solid	<b>Total Quantity:</b>			18.70
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	18.70	0.00	0.00
<b>Comments:</b> In good condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Coatings					
<b>Element Name:</b>	Railing Systems/Hand Railings	<b>Length:</b>			20.55
<b>Location:</b>	North south railings on parapet walls	<b>Width:</b>			0.00
<b>Material:</b>	Other	<b>Height:</b>			0.60
<b>Element Type:</b>		<b>Count:</b>			2
<b>Environment:</b>	Severe	<b>Total Quantity:</b>			24.70
<b>Limited Inspection:</b>					<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	20.70	3.00	1.00
<b>Comments:</b> Abrasion from vehicle impact and light coating discoloration.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Coatings	<b>Length:</b>			27.13
<b>Element Name:</b>	Railing Systems/Hand Railings	<b>Width:</b>			0.00
<b>Location:</b>	North and South sidewalk exterior railings	<b>Height:</b>			1.07
<b>Material:</b>	Other	<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			0.00
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	50.10	6.00	2.00
<b>Comments:</b>					
Light abrasions at some locations. Light flaking and soicoloration of grey to grey-black throughout.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Deck					
<b>Element Name:</b>	Deck Top	<b>Length:</b>			19.81
<b>Location:</b>	Top of Deck	<b>Width:</b>			18.66
<b>Material:</b>	Cast-in-place Concrete	<b>Height:</b>			0.00
<b>Element Type:</b>		<b>Count:</b>			1
<b>Environment:</b>	Moderate	<b>Total Quantity:</b>			369.70
<b>Protection System</b>	Waterproofing and Asphalt				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	324.20	43.00	2.50
<b>Comments:</b>					
Rating based on previous report and age of structure. 2014 Condition survey comments: No defects were revealed from the concrete cores and sawn samples, however bottom-up asphalt defects indicate poor condition due to potholes in asphalt, and fair condition due to wide longitudinal and transverse cracks.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

ELEMENT DATA					
<b>Element Group:</b>	Deck	<b>Length:</b>		2.00	
<b>Element Name:</b>	Soffit - Thin Slab	<b>Width:</b>		15.63	
<b>Location:</b>	East and West ends of Structure	<b>Height:</b>		0.00	
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>		2	
<b>Element Type:</b>		<b>Total Quantity:</b>		62.60	
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	51.60	8.00	3.00
<b>Comments:</b> Spalls, delaminations and wet areas noted on ends.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
<input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years				00 None	
ELEMENT DATA					
<b>Element Group:</b>	Deck	<b>Length:</b>		16.50	
<b>Element Name:</b>	Soffit - Thin Slab	<b>Width:</b>		1.13	
<b>Location:</b>	North and South exterior overhand soffit	<b>Height:</b>		0.00	
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>		2	
<b>Element Type:</b>		<b>Total Quantity:</b>		45.80	
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	32.80	10.00	3.00
<b>Comments:</b> Narrow to medium cracks with efflorescence, spalls, delaminations and wet areas noted. Narrow to medium vertical cracks noted on fascia.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
<input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years				00 None	



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Deck	<b>Length:</b>			16.50
<b>Element Name:</b>	Soffit - Thin Slab	<b>Width:</b>			12.28
<b>Location:</b>	Underside of deck, Interior	<b>Height:</b>			0.00
<b>Material:</b>	Cast-in-place Concrete	<b>Count:</b>			1
<b>Element Type:</b>		<b>Total Quantity:</b>			202.70
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	197.10	3.80	1.80
<b>Comments:</b> Spall/delamination at north west cover by plywood.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Deck	<b>Length:</b>			19.81
<b>Element Name:</b>	Wearing Surface	<b>Width:</b>			18.66
<b>Location:</b>	Top of deck	<b>Height:</b>			0.00
<b>Material:</b>	Asphalt	<b>Count:</b>			1
<b>Element Type:</b>		<b>Total Quantity:</b>			369.70
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	304.70	45.00	20.00
<b>Comments:</b> Unsealed medium to wide transverse, longitudinal, and random cracks noted. Light to medium potholes/patches noted.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

ELEMENT DATA					
<b>Element Group:</b>	Joints	<b>Length:</b>			18.66
<b>Element Name:</b>	Armouring/Retaining Devices	<b>Width:</b>			0.00
<b>Location:</b>	East and West	<b>Height:</b>			0.00
<b>Material:</b>	Steel	<b>Count:</b>			4
<b>Element Type:</b>		<b>Total Quantity:</b>			74.60
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.00	57.60	10.00	7.00
<b>Comments:</b> Permanent deformations of east armoring angles. Light corrosion noted. No armoring on outside edges of end dams.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b>	Joints	<b>Length:</b>			18.66
<b>Element Name:</b>	Concrete End Dams	<b>Width:</b>			0.30
<b>Location:</b>	East and West	<b>Height:</b>			0.00
<b>Material:</b>	Concrete	<b>Count:</b>			4
<b>Element Type:</b>		<b>Total Quantity:</b>			22.40
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	12.40	5.00	5.00
<b>Comments:</b> Narrow to medium cracks and spalls at the edges without armoring. Light to medium scaling throughout. Light to medium spalls.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

<b>ELEMENT DATA</b>					
<b>Element Group:</b>	Joints	<b>Length:</b>			24.20
<b>Element Name:</b>	Seals/Sealants	<b>Width:</b>			0.00
<b>Location:</b>	East and West	<b>Height:</b>			0.00
<b>Material:</b>		<b>Count:</b>			2
<b>Element Type:</b>	Compression seal	<b>Total Quantity:</b>			2.00
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	0.00	1.00	1.00
<b>Comments:</b> Covered with debris. Leakage observed from soffit. Rip/tears visible.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			
<b>Element Group:</b> Embankments and Streams					
<b>Element Name:</b>	Embankments	<b>Length:</b>			-
<b>Location:</b>	NE, NW, SE, SW	<b>Width:</b>			-
<b>Material:</b>	Vegetation / Rip-rap / Gabion	<b>Height:</b>			-
<b>Element Type:</b>		<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			2.00
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.00	2.00	0.00	0.00
<b>Comments:</b> In good condition.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

ELEMENT DATA					
<b>Element Group:</b>	Foundations	<b>Length:</b>			-
<b>Element Name:</b>	Foundation (Below ground level)	<b>Width:</b>			-
<b>Location:</b>		<b>Height:</b>			-
<b>Material:</b>		<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			0.00
<b>Environment:</b>		<b>Limited Inspection:</b>			<input checked="" type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	N/A	0.00	0.00	0.00	0.00
<b>Comments:</b> Not Inspected. No visible deficiencies noted.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None	
<b>Element Group:</b>	Sidewalks / Curbs	<b>Length:</b>			20.55
<b>Element Name:</b>	Sidewalks and Medians	<b>Width:</b>			2.49
<b>Location:</b>	North and South	<b>Height:</b>			0.20
<b>Material:</b>	Cast-in-place concrete	<b>Count:</b>			2
<b>Element Type:</b>		<b>Total Quantity:</b>			110.60
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>			<input type="checkbox"/>
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	97.60	13.00	0.00
<b>Comments:</b> Medium cracks and light scaling noted.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab <input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None	

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 132**

ELEMENT DATA					
<b>Element Group:</b>	Retaining Walls	<b>Length:</b>		334.90	
<b>Element Name:</b>	Walls	<b>Width:</b>		0.00	
<b>Location:</b>		<b>Height:</b>		2.57	
<b>Material:</b>	Cast-in-Place Concrete	<b>Count:</b>		1	
<b>Element Type:</b>	Reinforced Concrete	<b>Total Quantity:</b>		860.70	
<b>Environment:</b>	Moderate	<b>Limited Inspection:</b>		<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.00	528.90	220.00	111.80
<b>Comments:</b>					
Horizontal and vertical medium to wide cracks. Extensive severe delamination and spalls with exposed corroded rebar. Light to severe scaling, honeycombing and wet areas throughout. Large holes in north west wall. Heavy vergetation growth on south west.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
		<input checked="" type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None	

**BRIDGE**

Structure Name: Lorne Bridge-Girder  
 Structure Number: 132

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**Structure ID: 132**

Element Group	Element Name	Sub-Element	Unit (Qty.)	Total Element Qty.	Element Qty. in Excellent Condition (1.00)	Element Qty. in Good Condition (0.75)	Element Qty. in Fair Condition (0.4)	Element Qty. in Poor Condition (0)	Element Condition Index	Estimated Life Span	Estimated Remaining Service Life (ERSL)*	Performance Deficiency**	Maintenance Need**
Abutment	Abutment Walls	East Abutment	Sq.m	31.00	0.00	21.40	8.10	1.50	62	40	25	00	00
	Abutment Walls	West Abutment	Sq.m	141.30	0.00	117.10	18.10	6.10	67	40	27	00	00
Accessories	Ballast Walls		Sq.m	53.90	0.00	47.40	5.50	1.00	70	40	28	00	00
	Bearings		Each	14.00	0.00	14.00	0.00	0.00	75	35	26	00	00
	Wingwalls		Sq.m	18.80	0.00	16.70	2.10	0.00	71	40	28	00	00
	Utilities		Each	2.00	0.00	2.00	0.00	0.00	N/A	N/A	N/A	00	00
Approaches	Utilities		Each	2.00	0.00	2.00	0.00	0.00	N/A	N/A	N/A	00	18
	Approach Slabs		Sq.m	223.20	0.00	208.20	15.00	0.00	73	25	18	00	00
	Wearing Surface		Sq.m	113.46	0.00	68.46	30.00	15.00	56	15	8	00	00
	Sidewalks and Medians		Sq.m	67.70	0.00	62.70	4.00	1.00	72	35	25	00	00
Barrier	Barrier/Parapet Walls		Sq.m	20.60	0.00	14.10	6.00	0.50	63	35	22	00	00
	Barrier/Parapet Walls	Exterior	Sq.m	28.80	0.00	22.70	5.70	0.40	67	35	23	00	00
	Hand Railings	Interior	m	41.10	0.00	35.10	5.00	1.00	69	35	24	00	00
	Hand Railings		m	54.30	0.00	44.30	5.00	5.00	65	35	23	00	00
Beams/ MLEs	Railing Systems		Sq.m	89.70	0.00	86.70	2.00	1.00	73	50	37	00	00
	Girders	Ends	Sq.m	363.00	0.00	360.50	1.50	1.00	75	50	37	00	00
	Girders	Middle	Sq.m	18.70	0.00	18.70	0.00	0.00	N/A	50	00	00	00
	Railing Systems/Hand Railings		Sq.m	24.70	0.00	20.70	3.00	1.00	68	35	24	00	00
Coatings	Railing Systems/Hand Railings		Sq.m	58.10	0.00	50.10	6.00	2.00	69	35	24	00	00
	Deck Top		Sq.m	369.70	0.00	324.20	43.00	2.50	70	25	18	00	00
	Soffit - Thin Slab		Sq.m	62.60	0.00	51.60	8.00	3.00	67	33	33	00	00
	Soffit - Thin Slab		Sq.m	45.80	0.00	32.80	10.00	3.00	62	50	31	00	00
Joints	Soffit - Thin Slab		Sq.m	202.70	0.00	197.10	3.80	1.80	74	50	37	00	00
	Wearing Surface		Sq.m	369.70	0.00	304.70	45.00	20.00	67	15	10	00	00
	Armouring/Retaining Devices		m	74.60	0.00	57.60	10.00	7.00	63	25	16	00	00
	Concrete End Dams		Sq.m	22.40	0.00	12.40	5.00	5.00	50	25	13	00	00
Embankments and Streams	Seals/Sealants		Each	2.00	0.00	0.00	1.00	1.00	N/A	25	N/A	00	00
	Embankments		Each	2.00	0.00	2.00	0.00	0.00	N/A	N/A	N/A	00	00
	Foundation (Below ground level)		N/A	0.00	0.00	0.00	0.00	0.00	N/A	N/A	N/A	00	00
	Sidewalks / Curbs		Sq.m	110.60	0.00	97.60	13.00	0.00	71	35	25	00	00
Retaining Walls		Sq.m	860.70	0.00	528.90	220.00	111.80	56	40	23	00	00	

Condition Index 63.7

\*\* OSIM codes

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



01 North elevation



02 South elevation

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



03 Deck, looking east



04 Deck, looking west





05 Numerous longitudinal and transverse cracks on deck wearing surface



06 Potholes on wearing surface near east expansion joint

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



07 East expansion joint



08 West expansion joint

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



09 Spall on east expansion joint end dam



10 North fascia



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



11 South fascia



12 Vertical crack on north fascia



13 Sign on north fascia



14 Typical soffit



15 South exterior soffit



16 North exterior soffit



17 Cracks and delamination on north exterior soffit at east end



18 Delamination on north exterior soffit





19 Delamination on north exterior soffit



20 Spalls and delamination on south exterior soffit





21 Delamination on south exterior soffit



22 Board covering suspected spall



23 North exterior girder



24 Typical girders



25 Delamination on south exterior girder end



26 Spall on south exterior girder end at west end



27 Vertical cracks on exter girder ends at north east



28 Typical west diaphragm





29 East abutment



30 West abutment



31 Spall with exposed rebar on west abutment



32 Narrow crack on west abutment



33 Minor spall on west abutment



34 Vertical crack on west abutment





35 Delamination on west abutment at north side



36 Crack on concrete pedestal on west abutment at south end





37 Typical north bearing



38 North east wingwall



39 South east wingwall



40 Pattern crack on south east wingwall



41 North ballast wall



42 Delamination and spall on north ballast wall





43 East retaining wall section north of bridge



44 East retaining wall section south of bridge



45 East Retaining wall section under bridge



46 West retaining wall section south of bridge





47 Typical section loss with exposed rebar on east retaining wall



48 Typical section loss with exposed rebar on east retaining wall



49 Typical section loss with exposed rebar on east retaining wall



50 Typical section loss with exposed rebar on west retaining wall





51 Cracks and spalls on east retaining wall on section south of bridge



52 Section loss on east retaining wall



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



53 South sidewalk



55 Transverse crack on north sidewalk (1)

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



55 Transverse crack on north sidewalk (2)



56 South barrier wall



57 North barrier wall



58 Spall on south barrier wall



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



59 South barrier railing system



60 North barrier railing system



61 Impact damage on south handrailing at west end



62 South east guiderail

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



63 North railing



64 South Railing



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 132



65 East approach



66 East approach slab



67 West approach slab



68 Cracks at joint between east approach slab and approach





69 Potholes on end dam of east expansion joint



70 Pothole on east approach slab next to expansion joint



71 Cracks on west approach slab



72 Longitudinal and transverse cracks on east approach slab



73 Exposed rebar on north concrete curb



74 South east embankment





75 Utilites on girder



76 Sign on bridge



77 Plaque on Bridge



78 Plaque on bridge



79 Plaque on Bridge



80 Chain link fence at south side





81 Chain link fence at north east end

SUMMARY ACTION REPORT

ADDITIONAL INVESTIGATIONS	Priority	Inspection Date
Investigations, Inspections, Surveys Recommended		
Biennial OSIM	Normal	17-Dec-2021

REPAIR AND REHABILITATION REQUIRED	Priority		Comments
	6-10 Years	1 - 5 Years	
Repair and Rehabilitation Required			
Barrel	X		Rehabilitate

MAINTENANCE NEEDS	Priority		
	2 Years	1 Year	Urgent
Maintenance Needs			
Utilities - Other - Fix lighting covers	X		
Inlet Components - Repair Bridge Concrete - Fix isolated concrete spall	X		
Retaining Walls - Repair Bridge Concrete - Seal cracks	X		
Wearing Surface - Rout and Seal - Seal cracks on wearing surface	X		

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

INVENTORY DATA:			
Structure Name	<u>Lorne Bridge Pedestrian Underpass</u>		
Main Hwy/Road #	Under Structure:	<input type="checkbox"/> Navigable Water	<input type="checkbox"/> Non-Navigable Water
		<input type="checkbox"/> Rail	<input type="checkbox"/> Road <input checked="" type="checkbox"/> Pedestrian <input type="checkbox"/> Other
Road Name:	<u>Colborne Street West</u>	On Structure:	<input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Pedestrian <input type="checkbox"/> Other
Structure Location	<u>0.3km south of Brant Avenue</u>		
Latitude	<u>43.136886</u>	Longitude	<u>-80.270774</u>
Owner(s)	<u>City of Brantford</u>	Heritage	<input type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig.
		Designation	<input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
MTO Region	<u>Southwestern</u>	Road Class	<input type="checkbox"/> Freeway <input checked="" type="checkbox"/> Arterial <input type="checkbox"/> Collector <input checked="" type="checkbox"/> Local
MTO District	<u>-</u>	Posted Speed	<u>50 km/h</u> No. of Lanes <u>5</u>
Old County	<u>Brant</u>	AADT	<u>27133</u> % Trucks <u>25</u>
Geographic Twp.	<u>-</u>	Special Routes	<input type="checkbox"/> Transit <input type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle
Structure Type	<u>Rigid Frame, Vertical legs</u>	Detour Length Around Structure	<u>8.00</u> (km)
Total Deck Length	<u>4.00</u> (m)	Fill on Structure	<u>2.00</u> (m)
Overall Str. Width	<u>23.80</u> (m)	Skew Angle	<u>-</u> (Degrees)
Total Deck Area	<u>95.20</u> (m <sup>2</sup> )	Direction of Structure	<u>E - W</u>
Roadway Width	<u>13.60</u> (m)	No. of Spans	<u>1</u>
Span Lengths	<u>3.00</u> (m)		
Overall Condition Rating	<u>Fair</u>		
Bridge Condition Index (BCI)	<u>69.0</u>		

HISTORICAL DATA			
Year Built	<u>1980</u>	Last OSIM Inspection	<u>8/16/2017</u>
Year of Last Major Rehab.	<u>-</u>	Last Enhanced OSIM Inspection	<u>-</u>
Current Load Limit	<u>-</u> (tonnes)	Last Bridge Master Inspection	<u>-</u>
Load Limit By-Law #	<u>-</u>	Last Evaluation	<u>-</u>
By-Law Expiry Date	<u>-</u>	Last Underwater Inspection	<u>-</u>
Min. Vertical Clearance	<u>-</u> (m)	Last Condition Survey	<u>-</u>
<b>Rehabilitation History: (Date / Description)</b>			

Scheduled Improvements:	
Regional Priority Number _____	Programmed Work Year _____
Nature of Program Work:	

Appraisal Indices:	Comments
Fatigue	
Seismic	
Scour	
Flood	
Geometrics	
Barrier	
Curb	
Load Capacity	

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

<b>FIELD INSPECTION INFORMATION</b>	
Date of Inspection:	17-Dec-2019 <span style="float:right">Type of Inspection: <input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM</span>
Inspector:	Sabrina Dexter, Transportation Structures Engineer
Others in Party:	Akhilesh Prabhu, Transportation Structures Intern
Access Equipment Used:	Binoculars, sounding hammer, measuring tape, digital camera
Weather:	Overcast
Temperature:	-3°C

<b>ADDITIONAL INVESTIGATION REQUIRED</b>	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:				\$ -
Material Condition Survey				\$ -
Detailed Deck Condition Survey:				\$ -
Non-destructive Delamination Survey of Asphalt- Covered Deck:				\$ -
Concrete Substructure Condition Survey:				\$ -
Detailed Coating Condition Survey:				\$ -
Detailed Timber Investigation:				\$ -
Underwater Investigation:				\$ -
Fatigue Investigation:				\$ -
Seismic Investigation:				\$ -
Structure Evaluation:				\$ -
Monitoring				\$ -
Monitoring of Deformations, Settlement and Movements:				\$ -
Monitoring Crack Widths:				\$ -
<b>Load Posting – Estimated Load Limit</b>	<b>Total Cost</b>			\$ -
<b>Investigation Notes:</b>				

<b>OVERALL STRUCTURAL NOTES:</b>	
Recommended Work on Structure:	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 Years <input checked="" type="checkbox"/> 6 to 10 Years
Overall Comments:	
Overall the structure is in good to fair condition, with lighting covers that need fixing; wide sealed and unsealed cracks on the wearing surface; spalls on the interior and exterior faces of the barrier walls; missing seals, light to medium spalls and leakage at joints; and disintegration of concrete on south headwall. Minor rehabilitation is recommended in 6-10 years.	
Date of Next Inspection:	17-Dec-2021

**Suspected Performance Deficiencies**

- |  |  |                              |
|--|--|------------------------------|
| 00 None  | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces         |
| 01 Load carrying capacity                          | 07 Jammed expansion joint                | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotation) | 08 Pedestrian/vehicular hazard           | 14 Undermining of foundation |
| 03 Continuing settlement                           | 09 Rough riding surface                  | 15 Unstable embankments      |
| 04 Continuing movements                            | 10 Surface ponding                       | 16 Other                     |
| 05 Seized bearings                                 | 11 Deck drainage                         |                              |

**Maintenance Needs**

- |                                      |                               |  |
|--------------------------------------|-------------------------------|--|
| 01 Lift and swing bridge maintenance | 07 Repair of structural steel | 13 Erosion control at bridges            |
| 02 Bridge cleaning                   | 08 Repair of bridge concrete  | 14 Concrete sealing                      |
| 03 Bridge handrail maintenance       | 09 Repair of bridge timber    | 15 Rout and seal                         |
| 04 Painting steel bridge structures  | 10 Bailey bridges maintenance | 16 Bridge deck drainage                  |
| 05 Bridge deck joint repair          | 11 Animal/pest control        | 17 Sealing (loose Concrete or ACR Steel) |
| 06 Bridge bearing maintenance        | 12 Bridge surface repair      | 18 Other                                 |



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

ELEMENT DATA					
<b>Element Group:</b>	Accessories	<b>Length:</b>	0.00		
<b>Element Name:</b>	Utilities	<b>Width:</b>	0.00		
<b>Location:</b>	On Soffit	<b>Height:</b>	0.00		
<b>Material:</b>		<b>Count:</b>	4		
<b>Element Type:</b>	Lighting	<b>Total Quantity:</b>	4.0		
<b>Environment:</b>	Benign	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.0	0.0	1.0	3.0
<b>Comments:</b> 3 of 4 lighting cover broken. Replace the lighting covers.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years 18 Other			
<b>Element Group:</b>	Deck	<b>Length:</b>	3.10		
<b>Element Name:</b>	Wearing Surface	<b>Width:</b>	13.60		
<b>Location:</b>	Top Surface of Road	<b>Height:</b>	0.00		
<b>Material:</b>	Asphalt	<b>Count:</b>	1		
<b>Element Type:</b>		<b>Total Quantity:</b>	42.1		
<b>Environment:</b>	Severe	<b>Limited Inspection:</b>	<input type="checkbox"/>		
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Sq.m	0.0	26.7	10.0	5.4
<b>Comments:</b> Wide sealed and unsealed longitudinal and transverse cracks. Medium alligator cracks on north lane. Light segregation at barriers. Potholes noted.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years 15 Rout and seal			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

ELEMENT DATA					
<b>Element Group:</b>	Barrier		<b>Length:</b>	3.10	
<b>Element Name:</b>	Barrier/Parapet Walls		<b>Width:</b>	0.00	
<b>Location:</b>	Exterior		<b>Height:</b>	0.60	
<b>Material:</b>	Cast-in-place concrete		<b>Count:</b>	2	
<b>Element Type:</b>	Parapet Wall		<b>Total Quantity:</b>	3.7	
<b>Environment:</b>	Severe		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.0	1.1	2.0	0.6
<b>Comments:</b> Medium vertical cracks with moisture. Severe spall at SE.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

<b>Element Group:</b>	Barrier		<b>Length:</b>	3.00	
<b>Element Name:</b>	Barrier/Parapet Walls		<b>Width:</b>	0.25	
<b>Location:</b>	Interior		<b>Height:</b>	0.60	
<b>Material:</b>	Cast-in-place concrete		<b>Count:</b>	2	
<b>Element Type:</b>	Parapet Wall		<b>Total Quantity:</b>	5.1	
<b>Environment:</b>	Severe		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.0	2.1	2.0	1.0
<b>Comments:</b> Medium vertical cracks with moisture. Severe spall at SE.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117

ELEMENT DATA					
Element Group:	Barrier		Length:	0.13	
Element Name:	Posts		Width:	0.13	
Location:			Height:	0.50	
Material:	Steel		Count:	8	
Element Type:	Steel Post		Total Quantity:	8.0	
Environment:	Benign		Limited Inspection:	<input type="checkbox"/>	
Protection System					
Condition Data:	Units	Excellent	Good	Fair	Poor
	Each	0.0	8.0	0.0	0.0
<b>Comments:</b> Light corrosion.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b> <input type="checkbox"/> Rehab. <input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years                     00 None	

Element Group:	Barrier		Length:	2.45	
Element Name:	Hand Railings		Width:	0.00	
Location:	On top of Parapet Wall		Height:	0.00	
Material:	Steel		Count:	3	
Element Type:	Twin Pipe Hand Rail		Total Quantity:	7.3	
Environment:	Moderate		Limited Inspection:	<input type="checkbox"/>	
Protection System					
Condition Data:	Units	Excellent	Good	Fair	Poor
	m	0.0	5.8	1.0	0.5
<b>Comments:</b> Light staining on bottom rail. Impact damage at north west.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b> <input type="checkbox"/> Rehab. <input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years                     00 None	

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

ELEMENT DATA					
<b>Element Group:</b>	Barrier		<b>Length:</b>	3.10	
<b>Element Name:</b>	Railing Systems		<b>Width:</b>	0.00	
<b>Location:</b>	At four corners		<b>Height:</b>	0.00	
<b>Material:</b>	Steel		<b>Count:</b>	2	
<b>Element Type:</b>	Steel Beam on Steel Post		<b>Total Quantity:</b>	6.2	
<b>Environment:</b>	Moderate		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>	Hot dip galvanizing				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m	0.0	6.2	0.0	0.0
<b>Comments:</b> Light staining of bottom rail. Minor dents in spindles.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

<b>Element Group:</b>	Culvert		<b>Length:</b>	23.80	
<b>Element Name:</b>	Barrel		<b>Width:</b>	3.05	
<b>Location:</b>	Soffit + Wall		<b>Height:</b>	2.40	
<b>Material:</b>	Precast Concrete		<b>Count:</b>	1	
<b>Element Type:</b>	Box		<b>Total Quantity:</b>	259.4	
<b>Environment:</b>	Benign		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.0	231.4	16.0	12.0
<b>Comments:</b> Joint seals missing or in poor condition leading to leakage and rust staining. Light to medium spalling at joints. Bottom covered in asphalt with transverse cracks.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input checked="" type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input checked="" type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117

ELEMENT DATA					
Element Group:	Culvert	Length:	3.00		
Element Name:	Outlet Components	Width:	0.00		
Location:	North Headwall	Height:	0.95		
Material:	Cast-in-place concrete	Count:	1		
Element Type:	-	Total Quantity:	2.9		
Environment:	Benign	Limited Inspection:	<input type="checkbox"/>		
Protection System					
Condition Data:	Units	Excellent	Good	Fair	Poor
	m <sup>2</sup>	0.0	1.9	1.0	0.0
<b>Comments:</b> Narrow-medium vertical cracks. Light disintegration at edges.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b> <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

Element Group:	Culvert	Length:	3.00		
Element Name:	Inlet Components	Width:	0.00		
Location:	South Headwall	Height:	0.95		
Material:	Cast-in-place concrete	Count:	1		
Element Type:	-	Total Quantity:	2.9		
Environment:	Benign	Limited Inspection:	<input type="checkbox"/>		
Protection System	None				
Condition Data:	Units	Excellent	Good	Fair	Poor
	m <sup>2</sup>	0.0	0.9	1.0	1.0
<b>Comments:</b> Narrow-medium vertical cracks. Light disintegration at edges. Spalling and disintegration on south headwall.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b> <input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years 08 Repair of bridge concrete			



**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

ELEMENT DATA					
<b>Element Group:</b>	Embankments and Streams		<b>Length:</b>	-	
<b>Element Name:</b>	Embankments		<b>Width:</b>	-	
<b>Location:</b>	NE, NW, SE & SW		<b>Height:</b>	-	
<b>Material:</b>	Vegetation		<b>Count:</b>	4	
<b>Element Type:</b>			<b>Total Quantity:</b>	4.0	
<b>Environment:</b>	Benign		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	Each	0.0	4.0	0.0	0.0
<b>Comments:</b> Stable and vegetated.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None			

<b>Element Group:</b>	Retaining Walls		<b>Length:</b>	14.60	
<b>Element Name:</b>	Barrier Systems on Walls		<b>Width:</b>	0.00	
<b>Location:</b>			<b>Height:</b>	0.00	
<b>Material:</b>	Steel		<b>Count:</b>	2	
<b>Element Type:</b>	Steel Post and Lattice		<b>Total Quantity:</b>	29.2	
<b>Environment:</b>	Benign		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>					
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	All	0.0	29.2	0.0	0.0
<b>Comments:</b> Light corrosion.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace		<b>Maintenance Needs:</b> <input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years	
<input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		00 None			

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

ELEMENT DATA					
<b>Element Group:</b>	Foundations		<b>Length:</b>		
<b>Element Name:</b>	Foundation (Below ground level)		<b>Width:</b>		
<b>Location:</b>			<b>Height:</b>		
<b>Material:</b>			<b>Count:</b>		
<b>Element Type:</b>			<b>Total Quantity:</b>	0.0	
<b>Environment:</b>			<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	N/A	0.0	0.0	0.0	0.0
<b>Comments:</b> No sign of defects during the inspection.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None	
<b>Element Group:</b>	Retaining Walls		<b>Length:</b>	5.80	
<b>Element Name:</b>	Walls		<b>Width:</b>	0.00	
<b>Location:</b>	At four corners		<b>Height:</b>	2.05	
<b>Material:</b>	Cast-in-place Concrete		<b>Count:</b>	4	
<b>Element Type:</b>			<b>Total Quantity:</b>	47.6	
<b>Environment:</b>	Moderate		<b>Limited Inspection:</b>	<input type="checkbox"/>	
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.0	40.6	4.0	3.0
<b>Comments:</b> Full height medium-wide vertical cracks. Mediumwide diagonal cracks. Walls have been coated. Retaining walls are a separate item to inlet and outlet component because this site is categorized as a bridge.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> 1 - 5 Years		<input type="checkbox"/> Replace <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input checked="" type="checkbox"/> 2 Years 08 Repair of bridge concrete	

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**BRIDGE**

**Structure ID: 117**

ELEMENT DATA					
<b>Element Group:</b>	Sidewalks/Curb		<b>Length:</b>		3.00
<b>Element Name:</b>	Sidewalks and Medians		<b>Width:</b>		1.50
<b>Location:</b>	North and South		<b>Height:</b>		0.00
<b>Material:</b>	Cast-in-place Concrete		<b>Count:</b>		2
<b>Element Type:</b>			<b>Total Quantity:</b>		9.0
<b>Environment:</b>	Severe		<b>Limited Inspection:</b>		<input type="checkbox"/>
<b>Protection System</b>	None				
<b>Condition Data:</b>	<b>Units</b>	<b>Excellent</b>	<b>Good</b>	<b>Fair</b>	<b>Poor</b>
	m <sup>2</sup>	0.0	6.0	2.0	1.0
<b>Comments:</b> Medium-wide transverse and longitudinal cracks. New patch noted at utilites.					
<b>Performance Deficiencies:</b> 00 None					
<b>Recommended Work:</b>		<b>Maintenance Needs:</b>			
<input type="checkbox"/> Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> 1 - 5 Years <input type="checkbox"/> 6 - 10 Years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 Year <input type="checkbox"/> 2 Years 00 None			

**BRIDGE**

**ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM**

**Structure ID: 117**

Structure Name: Lorne Bridge Pedestrian Underpass  
 Structure Number: 117

Element Group	Element Name	Sub-Element	Unit (Qty.)	Total Element Qty.	Element Qty. in Excellent Condition (1.00)	Element Qty. in Good Condition (0.75)	Element Qty. in Fair Condition (0.4)	Element Qty. in Poor Condition (0)	Element Condition Index	Estimated Life Span	Estimated Remaining Service Life (ERSL)*	Performance Deficiency**	Maintenance Need**
Accessories	Utilities		Each	4.0	0.00	0.00	1.00	3.00	N/A	N/A	N/A	00	18
Deck	Wearing Surface		Sq.m	42.1	0.00	26.70	10.00	5.40	57	15	9	00	15
Barrier	Barrier/Parapet Walls	Exterior	Sq.m	3.7	0.00	1.10	2.00	0.60	44	3.5	1.5	00	00
	Barrier/Parapet Walls	Interior	Sq.m	5.1	0.00	2.10	2.00	1.00	47	3.5	1.6	00	00
Culvert	Posts		Each	8.0	0.00	8.00	0.00	0.00	75	3.5	2.6	00	00
	Hand Railings		m	7.3	0.00	5.80	1.00	0.50	65	3.5	2.3	00	00
	Railing Systems		m	6.2	0.00	6.20	0.00	0.00	75	3.5	2.6	00	00
	Barrel		Sq.m	259.4	0.00	231.40	16.00	12.00	69	100	69	00	00
Foundations	Outlet Components		Sq.m	2.9	0.00	1.90	1.00	0.00	63	50	31	00	00
	Inlet Components		Sq.m	2.9	0.00	0.90	1.00	1.00	37	50	19	00	08
Embankments and Streams	Embankments		Each	4.0	0.00	4.00	0.00	0.00	N/A	N/A	N/A	00	00
	Foundation (Below ground level)		N/A	0.0	0.00	0.00	0.00	0.00	N/A	N/A	N/A	00	00
Retaining Walls	Walls		Sq.m	47.6	0.00	40.60	4.00	3.00	67	40	27	00	08
	Barrier Systems on Walls		m	29.2	0.00	29.20	0.00	0.00	75	40	30	00	00
Sidewalks/Curb	Sidewalks and Medians		Sq.m	9.0	0.00	6.00	2.00	1.00	59	3.5	2.1	00	00

**Condition Index** 69.0

\*\* OSIM codes

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



01 North Elevation



02 South elevation

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



03 Roadway at top of culvert looking south



04 Transverse and longitudinal sealed and unsealed cracks on wearing surface



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



05 Barrel, looking north



06 Barrel, looking south



07 Typical barrel soffit



08 Barrel east wall

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



09 Barrel west wall



10 Active leakage of construction joints at south



11 Broken lighting cover on soffit



12 Spall on south face





13 Light to medium spalls on joints and active leakage on soffit



14 Active leakage at construction joint at north end on soffit



15 Poor seal condition on construction joints



16 North east retaining wall





17 North west retaining wall



18 South east retaining wall



19 South west retaining wall



20 Vertical crack on south east retaining wall



21 Vertical crack on south west retaining wall



22 Narrow vertical crack on north west retaining wall





23 North barrier wall



24 Typical narrow vertical cracks on north barrier wall

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



25 Spall on south barrier wall



26 North barrier railing



27 Impact damage on North barrier railing



28 North Sidewalk



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



29 Large longitudinal crack on north sidewalk



30 North Railing

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



31 Chain link fence on north face



32 East approach

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



33 West approach



34 Potholes and cracks on west approach



ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



35 North east embankment



36 North west embankment

ONTARIO STRUCTURE INSPECTION MANUAL - INSPECTION FORM

BRIDGE

Structure ID: 117



37 South east embankment



38 South west embankment





39 Plaque on concrete post





## 2021 Structural Evaluation Report


---

### Appendix II Select Historical Structural Drawings







SECTION ALONG B  
 HALF PLAN OF HEADINGS  
 HALF PLAN OF BASEMENTS  
 [Handwritten notes and dimensions]




HALF PLAN OF HEADINGS  
 HALF PLAN OF BASEMENTS  
 [Handwritten notes and dimensions]












ELEVATION OF EAST ABUTMENT




HALF SECTION ON A-A




ELEVATION OF WEST ABUTMENT



HALF PLAN OF EAST ABUTMENT WITH CLOSE SLAB REMOVED



TYPICAL CROSS SECTION AT CENTRE OF ARCH



HALF PLAN OF WEST ABUTMENT WITH CLOSE SLAB


LEWIS BRIDGE	
DETAIL OF ABUTMENTS AND TYPICAL CROSS SECTION	
DATE: 1904	BY: [Name]
SCALE: 1/4" = 1'-0"	NO. 100
DRAWN BY: [Name]	
CHECKED BY: [Name]	
APPROVED BY: [Name]	



# LORNE BRIDGE RECONSTRUCTION

CONTRACT NO. 74-1  
 WORK OF BRIDGE RECONSTRUCTION AND BRIDGE  
 IMPROVEMENTS  
 ROAD NO. 24  
 HIGHWAY NO. 24  
 LOCATION  
 CITY OF BRANTFORD  
 COUNTY OF BRANT  
 DISTRICT OF HAMILTON J.R.C.C. 16-A-1

**J. D. LEE ENGINEERING LTD.**  
 CONSULTING ENGINEERS  
 BRANTFORD, KINGSTON, ONTARIO.



KEY PLAN

SCALE : 1" = 1600'





CONTRACT NO. 74-1











NOTE: TO AVOID THE MIN. CLEARANCE OF 7' ABOVE THE TOP LANE OF TRAFFIC, THE REINFORCEMENT SHALL BE PLACED AS SHOWN TO COMPLY WITH A CLEAR COVER OF 2\"/>



CITY OF BRANTFORD  
 LORNE BRIDGE RECONSTRUCTION  
 LORNE BRIDGE  
 GRAND RIVER STRUCTURE  
 EAST ABUTMENT REINFORCEMENT

FOR BEACON PLAN  
 1/4\"/>

FOR BEACON PLAN  
 1/4\"/>


FOR BEACON PLAN  
 1/4\"/>

FOR BEACON PLAN  
 1/4\"/>


FOR BEACON PLAN  
 1/4\"/>

FOR BEACON PLAN  
 1/4\"/>

FOR BEACON PLAN  
 1/4\"/>



STAKE	1	2	3	4	5	6	7	8	9	10
1	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
2	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
3	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
4	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
5	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
6	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
7	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
8	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
9	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
10	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00	100.00





**CITY OF BRANTFORD**

**BRIDGE RECONSTRUCTION**

**LORNE BRIDGE**


**GRAND RIVER STRUCTURE**

**DECK RENOVALS AND SHORTEL WALL, REMOVALS & DETAILS**


DATE	NO.	BY	CHECKED	APP. BY

2.0 SET (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)

**FOR REDUCED RAIN**




FOR REDUCED RAIN  
 1.0 SET (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)  
 CONSULTING ENGINEER (BRIDGE) (AUTO)



**SCORED ELEVATIONS**

STATION	A	B	C	D	E	F	G
1+00	100.00	100.00	100.00	100.00	100.00	100.00	100.00
1+10	100.00	100.00	100.00	100.00	100.00	100.00	100.00
1+20	100.00	100.00	100.00	100.00	100.00	100.00	100.00
1+30	100.00	100.00	100.00	100.00	100.00	100.00	100.00
1+40	100.00	100.00	100.00	100.00	100.00	100.00	100.00
1+50	100.00	100.00	100.00	100.00	100.00	100.00	100.00



**CITY OF BRANTFORD**


**LORNE BRIDGE RECONSTRUCTION**

**LORNE BRIDGE**

**GRAND RIVER STRUCTURE**

**DECK LAYOUT AND REINFORCEMENT**

DATE: 10/15/10  
 DRAWN BY: [Name]  
 CHECKED BY: [Name]  
 APPROVED BY: [Name]














MARK	NO.	SIZE	LENGTH	NO. OF	MARK	NO.	SIZE	LENGTH	NO. OF	MARK	NO.	SIZE	LENGTH	NO. OF	MARK	NO.	SIZE	LENGTH	NO. OF	MARK	NO.	SIZE	LENGTH	NO. OF
DECK (cont'd)																								
DRONE	4	10	10'-0" WIDE																					
DRONE	5	25	25'-0" WIDE																					
DRONE	6	25	25'-0" WIDE																					
DRONE	7	25	25'-0" WIDE																					
VEGETATION APPROACH																								
DRONE	100	10	10'-0" WIDE																					
DRONE	101	10	10'-0" WIDE																					
DRONE	102	10	10'-0" WIDE																					
DRONE	103	10	10'-0" WIDE																					
DRONE	104	10	10'-0" WIDE																					
DRONE	105	10	10'-0" WIDE																					
LIGHT PILES																								
DRONE	106	10	10'-0" WIDE																					
DRONE	107	10	10'-0" WIDE																					
DRONE	108	10	10'-0" WIDE																					
DRONE	109	10	10'-0" WIDE																					
DRONE	110	10	10'-0" WIDE																					



**TABLE FOR NOTES**

**FOR DESIGN REVIEW**

**NOTE**

1. ALL DIMENSIONS ARE IN FEET AND INCHES.
2. ALL DIMENSIONS ARE TO FACE UNLESS OTHERWISE NOTED.
3. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
4. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
5. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
6. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
7. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
8. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
9. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
10. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
11. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
12. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
13. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
14. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
15. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
16. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
17. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
18. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
19. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
20. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
21. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
22. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
23. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.
24. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.


DESIGNED BY: [Name]  
 DRAWN BY: [Name]

**CITY OF BRANTFORD**  
**LORNE BRIDGE RECONSTRUCTION**  
**GRAND RIVER STRUCTURE**  
**BAR LIST**

J.D. DE WINTER LIMITED  
 CONSULTING ENGINEERING ARCHITECTURE AND  
 INTERIOR DESIGNERS  
 1000 W. GERRARD ST. E. SUITE 100  
 BRANTFORD, ONT. N3S 1Y7  
 TEL: (519) 751-1111  
 FAX: (519) 751-1112  
 WWW: WWW.JDDW.COM

DATE: [Date]  
 SCALE: [Scale]  
 SHEET: [Number] OF [Total]





- NOTES
1. ALL CONCRETE WORK SHALL BE TO STANDARD MIXTURES.
  2. CLASS OF CONCRETE: 3000 PSI.
  3. REINFORCING BARS: #4, #5, #6, #8, #10, #11, #14, #18, #22, #25, #30, #36, #42.
  4. ALL CONCRETE SHALL BE PLACED ABOVE THE FINISHED GRADE.
  5. THE CONTRACTOR IS RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL HEALTH DEPARTMENT AND THE LOCAL WATER SUPPLY DEPARTMENT.
  6. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL HEALTH DEPARTMENT AND THE LOCAL WATER SUPPLY DEPARTMENT.
  7. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL HEALTH DEPARTMENT AND THE LOCAL WATER SUPPLY DEPARTMENT.
  8. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL HEALTH DEPARTMENT AND THE LOCAL WATER SUPPLY DEPARTMENT.
  9. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL HEALTH DEPARTMENT AND THE LOCAL WATER SUPPLY DEPARTMENT.
  10. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE LOCAL HEALTH DEPARTMENT AND THE LOCAL WATER SUPPLY DEPARTMENT.

BY MEYER (A) R. B. S.  
 GEOMETRIC DESIGN  
 NORTH-SOUTH CROSS SECTION OF BRIDGE  
 HOTEL - CUT CORNER OR UNDESIRABLE

CITY OF BRANTFORD	
LORRIE BRIDGE RECONSTRUCTION	
L.E. IN RAILWAY GRADE SEPARATION MILEAGE 211	
GENERAL AGREEMENT	
DATE	1-1-58
SCALE	1" = 10'
PROJECT NO.	42
DESIGNED BY	A.D. LEE, ENGINEER, LIMITED
CHECKED BY	W.M. HARRIS, ARCHITECT, LIMITED
APPROVED BY	W.M. HARRIS, ARCHITECT, LIMITED



PROFILE OF COLBORNE ST. (LEVEL 10)  
 SCALE - 1" = 10'

FOR REDUCED PLAN  
 SCALE - 1" = 10'

CONCRETE DATA, LORRIE BRIDGE  
 1. 10' x 10' x 10'  
 2. 10' x 10' x 10'  
 3. 10' x 10' x 10'  
 4. 10' x 10' x 10'  
 5. 10' x 10' x 10'  
 6. 10' x 10' x 10'  
 7. 10' x 10' x 10'  
 8. 10' x 10' x 10'  
 9. 10' x 10' x 10'  
 10. 10' x 10' x 10'


PLAN  
 SCALE 1" = 10'

ELEVATION  
 SCALE 1" = 10'











SCALE: 1/4" = 1'-0"



SCALE: 1/4" = 1'-0"




SCALE: 1/4" = 1'-0"

**FOR REVISION PLAN**  
 REVISIONS  
 1. REVISION 1  
 2. REVISION 2  
 3. REVISION 3  
 4. REVISION 4  
 5. REVISION 5  
 6. REVISION 6  
 7. REVISION 7  
 8. REVISION 8  
 9. REVISION 9  
 10. REVISION 10

SCALE: 1/4" = 1'-0"





<b>CITY OF BRANTFORD</b>	
LORNE BRIDGE RECONSTRUCTION	
LORNE BRIDGE	
LEAVE RAILWAY GRADE SEPARATION MILEAGE 311	
EAST ABUTMENT REINFORCEMENT	
DATE	NOV 19 1968
SCALE	1/4" = 1'-0"
PROJECT NO.	45
DESIGNED BY	A. S. LEE, ENGINEERING LIMITED
CHECKED BY	CONSTRUCTION DEPARTMENT - CIVIL ENGINEERING UNIT
APPROVED BY	MR. J. H. W. (M. A. S. E.)
DATE	NOV 19 1968



PLAN OF GIRDLERS



HALF ELEVATION OF BOX GIRDLERS




BEARING DETAILS



TYPICAL INTERIOR GIRDER

TYPICAL EXTERIOR GIRDER

GIRDER SECTIONS  
 SECTION A  
 SECTION B  
 SECTION C  
 SECTION D



BEVELLED RECESS AT WEST END OF GIRDER



BEVELLED RECESS AT EAST END OF GIRDER

NOTES

1. SEE DRAWING FOR DIMENSIONS AND MATERIALS.
2. ALL DIMENSIONS ARE IN FEET AND INCHES UNLESS OTHERWISE SPECIFIED.
3. ALL ANGLES ARE TO BE SHOWN UNLESS OTHERWISE SPECIFIED.
4. ALL SURFACES ARE TO BE FINISHED UNLESS OTHERWISE SPECIFIED.
5. ALL SURFACES ARE TO BE PAINTED UNLESS OTHERWISE SPECIFIED.
6. ALL SURFACES ARE TO BE GALVANIZED UNLESS OTHERWISE SPECIFIED.
7. ALL SURFACES ARE TO BE GALVANNEAL UNLESS OTHERWISE SPECIFIED.
8. ALL SURFACES ARE TO BE GALVANIZED UNLESS OTHERWISE SPECIFIED.
9. ALL SURFACES ARE TO BE GALVANNEAL UNLESS OTHERWISE SPECIFIED.
10. ALL SURFACES ARE TO BE GALVANIZED UNLESS OTHERWISE SPECIFIED.



PLAN OF END BLOCK


PROFILES USED  
 1. 12" x 12" x 1/2"  
 2. 12" x 12" x 1/2"  
 3. 12" x 12" x 1/2"  
 4. 12" x 12" x 1/2"



CITY OF BRANTFORD  
 LORNE BRIDGE RECONSTRUCTION  
 LORNE BRIDGE  
 L.E. IN RAILWAY GRADE SEPARATION MILEAGE 211  
 PRESTRESSED BOX GIRDERS AND BEARINGS

L.E. INC. ENGINEERING LIMITED  
 CONSULTING ENGINEERS ARCHITECTS INC.  
 1111 GERRARD ST. E. TORONTO, ONT. M5C 1H5  
 TEL: (416) 491-1111 FAX: (416) 491-1112  
 1987 40

FOR REDUCED PLAN  
 SEE DRAWING FOR DIMENSIONS  
 ALL DIMENSIONS ARE IN FEET AND INCHES UNLESS OTHERWISE SPECIFIED.



**SPEED ELEVATIONS**

STATION	A	B	C
1+00	495.00	495.11	495.22
2+00	495.00	495.11	495.22
3+00	495.00	495.11	495.22
4+00	495.00	495.11	495.22
5+00	495.00	495.11	495.22
6+00	495.00	495.11	495.22
7+00	495.00	495.11	495.22
8+00	495.00	495.11	495.22
9+00	495.00	495.11	495.22
10+00	495.00	495.11	495.22

GRADE ELEVATION SHOWN AT TOP OF CONCRETE AND SHOULD BE ADJUSTED FOR DRIFT AND SETTLEMENT. GRADES SHOULD BE TO BE ADJUSTED UPWARD FOR UNUSUAL REFLECTIONS.

**CITY OF BRANTFORD**  
**LORINE BRIDGE RECONSTRUCTION**  
 LORINE BRIDGE  
 1.1 MI. RAILWAY GRADE SEPARATION MILEAGE 25+1  
 DECK AND APPROACH SLAB LAYOUT

U.S. ICE ENGINEERING, LIMITED  
 CONSULTING ENGINEERS  
 1000 WEST 12TH AVENUE  
 WINDSOR, ONT. N9A 7K2  
 TEL. 519-253-1111  
 FAX 519-253-1112

DATE: 10/15/00  
 DRAWN BY: J. L. B. (10/15/00)  
 CHECKED BY: J. L. B. (10/15/00)  
 SCALE: AS SHOWN



**FOR REVISION PLAN**  
 NO. 10000  
 J. L. B. (10/15/00)

**PLAN**  
 SCALE 1/4" = 1'-0"  
 NOTE: ELEVATIONS ARE TO TOP OF CONCRETE

**COORDINATES - SOUTH GRID LINE**  
 B.C. = 974.0+00.00  
 C.C. = 974.0+00.00  
 D.C. = 974.0+00.00  
 A = 974.0+00.00  
 B = 974.0+00.00  
 C = 974.0+00.00  
 D = 974.0+00.00  
 E = 974.0+00.00  
 F = 974.0+00.00  
 G = 974.0+00.00  
 H = 974.0+00.00  
 I = 974.0+00.00  
 J = 974.0+00.00

**TOP OF CONCRETE ELEVATIONS**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**


**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**


**SCALE 1/4" = 1'-0"**

**SCALE 1/4" = 1'-0"**


**SCALE 1/4" = 1'-0"**



PLAN  
SCALE 1/8" = 1'-0"




SCALE 1/8" = 1'-0"



SCALE 1/4" = 1'-0"

SCALE 1/4" = 1'-0"



SCALE 1/4" = 1'-0"

NOTE: TO ACHIEVE MINIMUM SLAB COVER, 2#5 REINFORCING BARS SHALL BE PLACED ON TOP OF CONCRETE WITH A CLEARANCE OF 2" ± 1/4" TOLERANCE.

CITY OF BRANTFORD	
LORNE BRIDGE RECONSTRUCTION	
LORNE BRIDGE	
L.E. ON RAILWAY GRADE SEPARATION RELEASE 211	
DECK AND APPROACH SLAB REINFORCEMENT	
DATE	NOV 2010
SCALE	AS SHOWN
PROJECT NO.	100-100-100
DESIGNER	MR. J. W. BROWN
CHECKED	MR. J. W. BROWN
APPROVED	MR. J. W. BROWN




FOR REDUCED PLAN







MARK	NO	SIZE	LENGTH	TYPE	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z	MARK					
ASPH	1	18"	11.75	11.75	11.75																															
CONC	2	18"	11.75	11.75	11.75																															
STEEL	3	18"	11.75	11.75	11.75																															
WOOD	4	18"	11.75	11.75	11.75																															
BRICK	5	18"	11.75	11.75	11.75																															
...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...



**NOTES**  
 1. ALL DIMENSIONS ARE IN FEET AND INCHES.  
 2. ALL DIMENSIONS ARE TO FACE UNLESS OTHERWISE NOTED.  
 3. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 4. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 5. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 6. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 7. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 8. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 9. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.  
 10. ALL DIMENSIONS ARE TO CENTERLINE UNLESS OTHERWISE NOTED.



LEGEND  
 BRIDGE WITH 2 SPANS 12' SPAN E - 10' FOR  
 BRIDGE WITH 2 SPANS 12' SPAN E - 10' FOR

CITY OF BRANTFORD	
LORNE BRIDGE RECONSTRUCTION	
LORNE BRIDGE	
LE IN RAILWAY GRADE SEPARATION MILEAGE 211	
BAR LIST	
DATE	NO. OF SHEETS
1977	93









Prepared By:



City of Brantford

# Brant's Crossing Bridge (Structure 104) Structural Evaluation Report

**GMBP File: 119104**  
**May 2021**



## **TABLE OF CONTENTS**

<b>1.</b>	<b>INTRODUCTION.....</b>	<b>1</b>
<b>2.</b>	<b>BACKGROUND INFORMATION .....</b>	<b>1</b>
2.1	Existing Structure .....	1
2.2	2018 Structural Inspection .....	1
<b>3.</b>	<b>NOMENCLATURE.....</b>	<b>2</b>
<b>4.</b>	<b>METHODOLOGY.....</b>	<b>4</b>
4.1	Existing Conditions.....	4
4.2	Evaluation Procedure.....	5
4.2.1	Dead Loads.....	5
4.2.2	Live Loads.....	5
4.2.3	Load Factors .....	6
<b>5.</b>	<b>LOAD LIMIT EVALUATION .....</b>	<b>6</b>
<b>6.</b>	<b>CONCLUSION AND RECOMMENDATIONS .....</b>	<b>7</b>
<b>7.</b>	<b>LIMITATIONS .....</b>	<b>10</b>
<b>8.</b>	<b>BIBLIOGRAPHY.....</b>	<b>11</b>

## **APPENDICES**

**APPENDIX I: HISTORICAL DRAWINGS**

**APPENDIX II: 2018 ENHANCED OSIM SUMMARY REPORT**

**APPENDIX III: SUMMARY OF LOAD FACTORS USED IN EVALUATION**

---

## BRANT'S CROSSING BRIDGE (STRUCTURE 104) STRUCTURAL EVALUATION REPORT

CITY OF BRANTFORD

MAY 2021

GMBP FILE: 119104

---

### 1. INTRODUCTION

**GM BluePlan Engineering Limited** (GMBP) was retained by the City of Brantford (City) to complete a load limit evaluation of the Brant's Crossing Bridge (Structure 104), located south of Colborne Street West and spanning the Grand River in the City of Brantford. As a part of this assignment, the existing structure was inspected within an arm's reach and analyzed for the purposes of determining the current load limit and to identify and assess the various rehabilitation and replacement options as part of the Municipal Class Environmental Assessment (MCEA) process.

### 2. BACKGROUND INFORMATION

#### 2.1 Existing Structure

Structure 104 is a four-span bridge that was originally designed to convey railway traffic but has since been converted to a pedestrian bridge to carry pedestrian traffic and a utility crossing across the Grand River. Based on discussions with City staff, the utility crossing is no longer in active service. Numerous historical drawings were provided by the City. Due to the number of drawings provided for Structure 104, only relevant drawings for this evaluation have been included in the **Appendix I**.

The superstructure consists of two through truss spans (Spans 2 & 3) and two plate girder spans (Spans 1 & 4). Historical drawings, dated 1911 and 1912, indicate the piers and abutments are founded on bedrock using spread footings. It should be noted that the west pier is the abutment of a former bridge in this location that was repurposed as a pier. City staff have indicated that this bridge was converted to a pedestrian bridge in approximately 1997.

#### 2.2 2018 Structural Inspection

Following an ice jam event in the Grand River on February 21, 2018, the structure was subject to a detailed structural inspection in accordance with the Ontario Structure Inspection Manual (OSIM). In order to safely assess all elements of the bridge within an arm's reach, ASI Group Ltd. (ASI) was retained to perform an underwater inspection of the abutment and pier footings and Acuren Group Ltd. (Acuren) was retained to perform a ropes access inspection of all other elements beyond an arm's reach, which included the underside of the structure and top members of the trusses. The ropes access inspection occurred over a period of 4 days from May 28, 2018, to May 31, 2018, and the underwater inspection occurred on June 22, 2018. Structure 104 has been closed since the flooding and ice jam event in February 2018.


The complete Enhanced OSIM Summary Report for Structure 143 is provided in **Appendix II**.

Within the Enhanced OSIM Summary Report, both major and minor deficiencies were noted. Major deficiencies are considered to be critical and should be addressed in the next 1-5 years to maintain the structural integrity of the bridge. Minor deficiencies are not classified as urgent and can be addressed at a later time; however, consideration should be given to addressing all deficiencies under one project.


Critical deficiencies are included in **Table 4** and **Table 5** at the end of this report.

### 3. NOMENCLATURE


Steel members in each span of Structure 104 generally consist of built-up steel sections. Refer to **Figure 1** below for the standard terminology used for these built-up sections. Refer to **Figure 2 and 3** for standard terminology used for the structural elements in the bridge. Note that Figure 2 and 3 is provided for glossary of terms only; it is not representative of the actual dimensions of Structure 104. Refer to **Figure 4** for a cross section of the pedestrian platform installed in approximately 1997.



**Figure 1: Cross Sections of Typical Built-Up Sections**



**Figure 2: Typical Elements of Through Plate Girder Bridge**



**Figure 3: Typical Elements of Steel Truss Bridge**






Figure 4: Existing Pedestrian Platform

## 4. METHODOLOGY

The structural evaluation was made in accordance with Section 14 of the CSA S6-19 Canadian Highway Bridge Design Code (CHBDC). Provided below is a detailed description of the methodology used for this evaluation. It should be noted that our evaluation refers to the capacity of superstructure elements only. Section 14 of the CHBDC does not refer to the evaluation of the substructure. Based on the defects noted during the site visit completed by GMBP, we do not believe that the substructure elements are a limiting factor in the capacity of the evaluated structure.

### 4.1 Existing Conditions

The historical drawings do not provide details regarding the structural steel sections used to construct Structure 104. Therefore, the structural steel sections for load rating individual elements were derived based on dimensions taken during the Enhanced OSIM inspection. All recorded element dimensions were taken using tape measure and Vernier caliper.

Structural steel strength was determined in accordance with Table 14.1 in Section 14 of the CHBDC, using construction year dating between 1905 and 1932. Based on the table, the existing steel was evaluated using a yield and tensile strength of 210 MPa and 420MPa respectively.

Wood deck strength was determined in accordance with Section 9 of the CHBDC using Red Pine, as specified on the 2006 rehabilitation drawings.

## 4.2 Evaluation Procedure

### 4.2.1 Dead Loads

Dead loads, such as the self-weight of all bridge components, were calculated in accordance with the CHBDC Table 3.4 and Clause 14.8 “Permanent Loads”. The weights of materials used for the evaluation of each structure (where applicable) are summarized in **Table 1**.

**Table 1: Summary of Dead Loads for Evaluations**

Material	Weight
Steel	77.0 kN/m <sup>3</sup>
Timber (Rail Ties)	9.5 kN/m <sup>3</sup>
Wood Planks (Deck)	6.0 kN/m <sup>3</sup>

Dead loads are apportioned into three categories: D1 (factory produced products, cast-in-place concrete – excluding decks), D2 (cast-in-place concrete decks, wood, field-measured asphalt, non-structural components), and D3 (asphalt, where the thickness is assumed to be 90 mm). In general, where the geometry could not be verified by field measurement the dead load was considered to be categorized as a D3 dead load.

For Structure 104, dead loads include the self weight of all steel elements, 305x203mm (12"x8") rail ties spaced at 355mm (14"), 76x152mm (3"x6") wood deck, supporting 150x200mm (6"x8") timber sleepers, and steel rail track.

### 4.2.2 Live Loads

Two distinct live loads were considered in the load rating evaluation. First, the pedestrian load specified in Clause 3.8.12 of the CHBDC 4.0 kPa was applied to the entire original railway bridge deck width of 4.2m, not the current raised pedestrian sidewalk that has a width of 2.5m. The entire deck width was considered to allow for potential future widening of the pedestrian platform.

The second live load considered was the maintenance vehicle load specified in Clause 3.8.12 of the CHBDC with a gross weight of 80 kN (approximately 18,000 lbs). However, per Clause 3.8.11 of the CHBDC, the maintenance vehicle load only needs to be considered if the sidewalk or pedestrian bridge width is greater than 3.0m. As noted above, the current pedestrian sidewalk has a width of 2.5m; and therefore, the maintenance vehicle does not need to be considered in the load rating. However, to allow for potential future widening of the pedestrian platform, the maintenance vehicle has been considered for the purposes of this report.

As per Clause 3.8.11 of the CHBDC, the maintenance vehicle and pedestrian load were not considered to act simultaneously.

The Live Load Capacity Factor, F, for Ultimate Limit State was calculated to determine the residual strength in the structural elements that is available to resist applied live loads once all permanent loads (i.e., dead loads) have been accounted for by the member's strength. As per Clause 14.17.2 of the CHBDC, F factors greater than or equal to 1, do not require a load posting, meaning the evaluated bridge is capable of supporting loads used to derive the F factors. The overall bridge posting is determined based on the smallest value of F derived for each individual bridge element.

### 4.2.3 Load Factors

Reliability Indices were used to determine the appropriate load factors for dead and live loads. These indices were dependent upon the element being analyzed, and its system behaviour, element behaviour and inspection level as outlined below:

- System behaviour, classified as one of the following:
  - (S1) Element failure will lead to total collapse
  - (S2) Element failure will likely not lead to total collapse
  - (S3) Element failure will lead to local failure only
- Element behaviour, classified as one of the following:
  - (E1) Element is subject to a sudden loss of capacity with little or no warning
  - (E2) Element is subject to a sudden loss of capacity with little or no warning but will retain post-failure capacity
  - (E3) Element is subject to gradual failure with warning of probably failure
- Inspection level, classified as one of the following:
  - (INSP1) Element is not accessible for inspection
  - (INSP2) Element is accessible for inspection to the satisfaction of the evaluator
  - (INSP3) Element is accessible for inspection and inspection is directed by the evaluator

Once the system behaviour, element behaviour and inspection level have been determined for the failure mode of each element being evaluated, a Reliability Index can be used to determine the appropriate dead and live load factors. It should be noted that a single element may have different load factors depending on the mode of failure being analyzed (i.e., a concrete beam analyzed for shear may have different load factors for analysis than the same beam analyzed for bending). For the purpose of this evaluation, pedestrian live load factors were assigned based on Table 3.1 in Section 3 of the CHBDC ( $\alpha_L = 1.7$ ). The target reliability index, a measure of the level of safety of a component(s), used during the evaluation of various elements, and respective live and dead load factors are summarized the table in **Appendix III**.

In addition to the live load factor,  $\alpha_L$ , no Dynamic Load Allowance (DLA) was considered for maintenance vehicle loading. According to Clause 3.8.4.5.1 of the CHBDC, maintenance vehicle load of 80 kN includes an allowance for dynamic effect.

## 5. LOAD LIMIT EVALUATION

Both hand calculations and finite element model analysis were completed to determine the member-by-member shear forces and bending moments as per the CHBDC. The finite element model analysis was completed using a 2D model in S-Frame Version 11 software.

Resistance of steel structural components and the wood deck was determined using Section 9 and 10 of the CHBDC, respectively. To account for an overall light to medium corrosion, an average 15% steel thickness reduction was applied to all steel members. An additional 5% reduction in steel thickness was used to account for potential future steel corrosion that may take place before the next bridge evaluation. As a result, the resistance of steel members was based on 80% of the steel thickness measured in the field. Additionally, some steel members were measured to have less than 80% of the steel thickness remaining. For these steel members with additional section loss, a resistance associated to the remaining section of the member was individually applied. To account for the isolated severe cracking and splintering noted in the wood deck, an average resistance adjustment factor of 0.8 was applied to wood elements.

The existing pedestrian platform is rated for an unfactored 4.8 kPa pedestrian load per the 1996 PMA Landscape Architects drawings for the Brantford Waterfront project.

See **Table 2** and **Table 3** below for the summary of F factors for individual elements.

**Table 2: Load Posting Summary for Plate Girder Spans**

Element	Pedestrian Live Load Capacity Factor, F	Maintenance Vehicle Live Load Capacity Factor, F	Load Posting
Stringer	> 1.0	< 1.0	Required *1
Floor Beam	> 1.0	> 1.0	Not Required
Plate Girder	> 1.0	> 1.0	Not Required

\*1 Load Posting required only for maintenance vehicle (No load rating required for pedestrian loading)

**Table 3: Load Posting Summary for Truss Spans**

Element	Pedestrian Live Load Capacity Factor, F	Maintenance Vehicle Live Load Capacity Factor, F	Load Posting
Stringer	> 1.0	> 1.0	Not Required
Floor Beam	> 1.0	> 1.0	Not Required
Plate Girder	> 1.0	> 1.0	Not Required
Top Chord	> 1.0	> 1.0	Not Required
Bottom Chord	> 1.0	> 1.0	Not Required
Vertical	> 1.0	> 1.0	Not Required
Diagonal	> 1.0	> 1.0	Not Required

\*1 Load Posting required only for maintenance vehicle (No load rating required for pedestrian loading)

Upon completion of the structural analysis, it was determined that all structural elements have a Load Capacity Factor, F, larger than 1.0 for the pedestrian load. Therefore, no load limit is required in reference to pedestrian loading.

It was determined that all structural elements, with the exception of existing pedestrian platform and plate girder span stringers, have a Load Capacity Factor, F, larger than 1.0 for the CHBDC 80 kN maintenance vehicle.

As noted in Section 4.2.2, the existing pedestrian platform is 2.5 m wide and therefore the analysis does not need to consider the CHBDC Maintenance vehicle. It is recommended that if a custom City of Brantford maintenance vehicle is currently being utilized, or plans to be utilized, that it be limited to a maximum axle loading of 2.3 kN. Should the pedestrian platform be widened or modified, considerations for the CHBDC maintenance vehicle loading should be considered.

## 6. CONCLUSION AND RECOMMENDATIONS

Based on the load rating and deficiencies stated in this report, the existing bridge does not require a load posting, provided it is only subject to maintenance vehicle loading with a maximum axle loading of 2.3kN (235kg) or pedestrian loading. If the bridge was maintained by a maintenance vehicle with a maximum gross weight in excess of that stated above, or the CHBDC maintenance vehicle of 80 kN (approximately 8,155kg) as specified in Clause 3.8.11 of the CHBDC, we recommend that the existing pedestrian platform be modified or fully replaced, and all lower shelf angles and web in the stringers listed in **Table 4** be reinforced with additional steel plates and angles.

In addition to the repairs required to increase the load limit, outlined above, there are several other deficiencies identified in the 2018 Enhanced OSIM that should be addressed as part of a capital project in the next 1-5

years to maintain the structure in working order. A summary of the recommended rehabilitation work for Structure 104 is provided in **Table 4** and **Table 5** below. Please refer to Appendix A of the 2018 Enhanced OSIM Summary Report included in **Appendix II** of this report for a diagram describing node locations referenced in the tables below.

Note that replacement of bearing anchor pins is included in the rehabilitation scope of work provided in **Table 4** and **Table 5**. Until the anchor pins are replaced, the bridge is prone to lateral shifting if the watercourse level was to rise above the underside of the structure, similar to the ice jam in 2018.

Please note that the inspection completed was at a single point in time. To our knowledge, this is the first Enhanced OSIM completed on this structure. Therefore, there is no reference benchmark to help assess the rate of deterioration of steel elements. The recommended work implementation timeframes and extension of service life may vary depending on the actual rate of deterioration. Please note that the use of salt to maintain this structure in the winter months is expected to result in accelerated deterioration of the structure. It is therefore recommended that winter maintenance of this structure avoid the use of salt.

In accordance with the 2018 Ontario Structure Inspection Manual (OSIM), with structures greater than 30 years old with critical components in poor condition, it is recommended that an Enhanced OSIM inspection be completed every 6 years in order to monitor member deterioration, until such time that a major rehabilitation is completed to address the poor condition members. The last Enhanced inspection was completed in spring of 2018. Prior to detailed design of major rehabilitation work, it is recommended that an additional Enhanced OSIM take place to confirm the scope of the major rehabilitation work.



**Table 4: Option 1 – Rehabilitation Works Required for an Estimated 15 to 30 Year Service Life**

Item	Rehabilitation Work	Location
1.0	Reinforce lower shelf angles and web of stringers	<ul style="list-style-type: none"> <li>All stringers in west plate girder span</li> </ul>
2.0	Concrete repair work	<ul style="list-style-type: none"> <li>East and west abutment</li> <li>East, central, and west piers</li> <li>All bearing seats, wingwalls and ballast walls</li> <li>Underpinning of West Pier</li> </ul>
3.0	Replace bearing anchor pins	<ul style="list-style-type: none"> <li>North and south bearings for each span at:               <ul style="list-style-type: none"> <li>east abutment (2)</li> <li>east pier (4)</li> <li>central pier (4)</li> <li>west pier (4)</li> <li>west abutment (2)</li> </ul> </li> </ul>
4.0	Replace all roller bearings of truss spans	<ul style="list-style-type: none"> <li>East truss span at east pier, two bearings</li> <li>West truss span at west pier, two bearings</li> </ul>
5.0	Reinforce lower shelf angle of plate girders	<ul style="list-style-type: none"> <li>West span, north girder, inside lower shelf angle in first two bays from the west</li> </ul>
6.0	Reinforce or replace deficient bottom lateral bracing	<ul style="list-style-type: none"> <li>Lateral braces in east plate girder span between nodes: A21 to D22, A22 to D21, A24 to D23, A25 to D26, and A26 to D25</li> <li>Lateral braces in west plate girder span between nodes: A1 to D2, A4 to D5, A5 to D6, and A6 to D5</li> <li>Lateral braces in east truss span between nodes: A14 to D15, A15 to D16, and D15 to A16</li> </ul>
7.0	Reinforce or replace deficient lateral connection plates	<ul style="list-style-type: none"> <li>Lateral brace plate connections in east plate girder span at nodes: A21, D21, A25, D25, A26, D26</li> <li>Lateral brace plate connections in west plate girder span at nodes: D1, D5, D6</li> <li>Lateral brace plate connections in east truss span at nodes: A14, D14, A20, and D20</li> <li>Lateral brace plate connections in west truss span at nodes: A7, D7, A12, A13, and D13</li> </ul>
8.0	Repair Truss Bottom Chords	<ul style="list-style-type: none"> <li>Lower shelf angles above all truss span bearings</li> <li>Lower shelf angles at lateral brace connections</li> <li>Lower web member of bottom chord at nodes: A8, D8, D10, and D12</li> </ul>
9.0	Repair Floor Beam	<ul style="list-style-type: none"> <li>West Truss span node A16 to D16.</li> </ul>
10.0	Remove debris from steel members	<ul style="list-style-type: none"> <li>All four spans, on top of horizontal surfaces such as shelf angles</li> </ul>

**Table 5: Option 2 – Rehabilitation Works Required for an Estimated 10 to 20 Year Service Life**

Item	Rehabilitation Work	Location
1.0	Reinforce lower shelf angles and web of stringers* <sup>1</sup>	<ul style="list-style-type: none"> <li>• All stringers in west plate girder span</li> </ul>
2.0	Concrete repair work	<ul style="list-style-type: none"> <li>• Bearing seats at top of abutments and piers</li> </ul>
3.0	Replace bearing anchor pins	<ul style="list-style-type: none"> <li>• North and south bearings for each span at:               <ul style="list-style-type: none"> <li>○ east abutment (2)</li> <li>○ east pier (4)</li> <li>○ central pier (4)</li> <li>○ west pier (4)</li> <li>○ west abutment (2)</li> </ul> </li> </ul>
4.0	Replace all roller bearings of truss spans	<ul style="list-style-type: none"> <li>• East truss span at east pier, two bearings</li> <li>• West truss span at west pier, two bearings</li> </ul>
5.0	Reinforce lower shelf angle of plate girders	<ul style="list-style-type: none"> <li>• West span, north girder, inside lower shelf angle in first two bays from the west</li> </ul>
6.0	Repair floor beam	<ul style="list-style-type: none"> <li>• West Truss span node A16 to D16.</li> </ul>
7.0	Remove debris from steel members	<ul style="list-style-type: none"> <li>• All four spans, on top of horizontal surfaces such as shelf angles</li> </ul>

*\*<sup>1</sup> Rehabilitation work required if bridge is to be reopened to maintenance vehicle specified in Clause 3.8.11. of the CHBDC*

Further to the recommendations provided above, we strongly suggest that the City ensures the following maintenance procedures are implemented or continued:

- Avoid use of de-icing chemicals, using sand as an alternative
- Regularly cut back and maintain vegetation around the abutments and deck of the structure
- Regularly clean structure of accumulated debris

## 7. LIMITATIONS

The following limitations are applicable to this load limit evaluation report:

- This report is intended exclusively for the Client(s) named in the report. The material in it reflects our best judgment in light of the information reviewed by GM BluePlan Engineering Limited at the time of preparation. Unless otherwise agreed in writing by GM BluePlan Engineering Limited, this report shall not be used to imply warranty as to the fitness of the property for a particular purpose. This report is not a certification of compliance with past or present regulations. No portion of this report may be used as a separate entity, it is written to be read in its entirety.
- Only the specific information identified has been reviewed. GM BluePlan Engineering Limited is not obligated to identify mistakes or insufficiencies in the information obtained from the various sources or to verify the accuracy of the information. GM BluePlan Engineering Limited may use such specific information obtained in performing its services and is entitled to rely upon the accuracy and completeness thereof.
- This assessment does not wholly eliminate uncertainty regarding the potential for existing or future losses in connection with a property. No physical or destructive testing has been performed unless specifically recorded. Conditions existing, but not recorded, were not apparent given the level of study undertaken. We can perform further investigation on items of concern, if so required.

## 8. BIBLIOGRAPHY

1. The Canadian Highway Bridge Design Code, CSA S6-19 (CHBDC)
2. Bakht, B. and Jaeger, L.G (1988). Document SRR-88-04 "Bridge Testing – A Surprise Every Time." The Research and Development Branch, Ministry of Transportation of Ontario

We thank you for engaging in the services of GM BluePlan Engineering Limited, and trust that this report provides the information that you require at this time. If you have any questions, or if we may be of further assistance, please do not hesitate to contact us.

Your truly,

GM BLUEPLAN ENGINEERING LIMITED

Per:



Adam Galezowski, P.Eng.

Per:



Jens Hummel, P.Eng.



## 2021 Structural Evaluation Report

---

### Appendix I Historical Drawings





NO. 100100


NO. 100100

WESTERLY


EASTERLY



SIDE ELEVATION PIER No. 3




PIER No. 3.




PIER No. 2.




PLAN PIER No. 3.



PLAN PIER No. 2.



PLAN PIER No. 1.



SECTION PIER No. 1.

SCALE 1" = 10'

CANADIAN NATIONAL RAILWAYS  
CENTRAL REGION  
LONDON DIV'N. BURFORD SUBDIV.

BRIDGE M.P. 28 9.5  
OVER GRAND RIVER  
AT BRANTFORD


INFORMATION FROM INSPECTION BY DIVING  
CREW MAY 25<sup>th</sup> 1934

Drawn by H.P.


J. Williams  
Inspector

9576






ELEVATION A/B



PLAN A/B




NO.	DATE	REVISION
1	10/15/11	ISSUE FOR PERMIT

PMA  
Professional Mechanical Association  
1000 N. W. 10th St.  
Fort Lauderdale, FL 33304  
Tel: 954.333.1111  
Fax: 954.333.1112  
www.pma.org


Brantford  
Waterfront  
Barbours, Oh.  
Trestle Bridge  
East Side  
Scale: 1/8" = 1'-0"  
Date: 10/15/11  
Sheet No: 11

95053  
1/1




The contractor is to provide all materials and labor for the construction of the bridge. The contractor is to provide all materials and labor for the construction of the bridge. The contractor is to provide all materials and labor for the construction of the bridge.

BRANTFORD WATERFRONT  
BARBOURS, OH.  
TRESTLE BRIDGE  
EAST SIDE  
SCALE: 1/8" = 1'-0"  
DATE: 10/15/11  
SHEET NO: 11



ELEVATION C/D



PLAN C/D



THE INFORMATION CONTAINED HEREIN IS FOR THE USE OF THE CLIENT ONLY. IT IS NOT TO BE USED FOR ANY OTHER PURPOSE. THE ENGINEER ASSUMES NO LIABILITY FOR ANY DAMAGE OR INJURY RESULTING FROM THE USE OF THIS INFORMATION. THE CLIENT ASSUMES ALL LIABILITY FOR ANY DAMAGE OR INJURY RESULTING FROM THE USE OF THIS INFORMATION.

DATE: 08/14/12  
 DRAWN BY: J. J. [unreadable]  
 CHECKED BY: [unreadable]  
 APPROVED BY: [unreadable]

NO.	DESCRIPTION	DATE
1	ISSUED FOR PERMIT	08/14/12

WMA  
 WATERWAY  
 MAINTENANCE  
 DISTRICT

Brantford  
 Waterfront  
 Brantford, On

Trestle Bridge  
 West Side

Scale: 1" = 10'  
 Date: 08/14/12  
 Sheet No: 1 of 1


L-2






THESE DRAWINGS AND SPECIFICATIONS ARE PREPARED BY THE MISSOURI DEPARTMENT OF TRANSPORTATION. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE APPROPRIATE AGENCIES. THE CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE APPROPRIATE AGENCIES.


NOTES:  
 1. ALL DIMENSIONS UNLESS OTHERWISE NOTED ARE IN FEET AND INCHES.  
 2. ALL DIMENSIONS UNLESS OTHERWISE NOTED ARE IN FEET AND INCHES.




Section V Elevation E (Typ. for Section/ Elevation F) - Closure Panel  
 Scale: 1/8" = 1'-0"




elevation - weathering steel panels  
 Scale: 1/8" = 1'-0"



steel slanchion at weathering steel panels  
 Scale: 1/8" = 1'-0"



Elevation - Front elevation of lookout, looking north  
 Scale: 1/8" = 1'-0"



Section D - Section thru walkway at lookout, looking south  
 Scale: 1/8" = 1'-0"

NO.	DESCRIPTION	DATE
1	ISSUED FOR PERMIT	11/14/18
2		
3		
4		
5		
6		
7		
8		
9		
10		

ALL DIMENSIONS UNLESS OTHERWISE NOTED ARE IN FEET AND INCHES.  
 CONTRACTOR SHALL BE RESPONSIBLE FOR OBTAINING ALL NECESSARY PERMITS AND APPROVALS FROM THE APPROPRIATE AGENCIES.

MMA  
 MISSOURI  
 MISSOURI  
 MISSOURI

**Brentford Waterfront**  
 Trestle Bridge Details  
 Brentford, OH

DATE: 11/14/18  
 DRAWING NO.: 95053  
 SHEET NO.: L-5



BRANTFORD BRIDGE  
 BRANTFORD, ONTARIO  
 BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY  
 BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY

NOTE:  
 ALL DIMENSIONS TO BE AS SHOWN UNLESS OTHERWISE NOTED ON DRAWING.

NO.	DATE	DESCRIPTION
1	1988-07-20	ISSUED FOR TENDER
2	1988-08-10	ISSUED FOR CONSTRUCTION

BRANTFORD BRIDGE  
 BRANTFORD, ONTARIO  
 BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY





PREPARED BY  
 TMA  
 ARCHITECTS  
 BRANTFORD, ONTARIO

BRANTFORD BRIDGE  
 BRANTFORD, ONTARIO  
 BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY

BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY

BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY

BRIDGE NO. 1000  
 BRIDGE OVER THE CANADIAN PACIFIC RAILWAY



NOTE:  
 1. ALL DIMENSIONS TO BE AS SHOWN UNLESS OTHERWISE NOTED ON DRAWING.  
 2. ALL DIMENSIONS TO BE AS SHOWN UNLESS OTHERWISE NOTED ON DRAWING.  
 3. ALL DIMENSIONS TO BE AS SHOWN UNLESS OTHERWISE NOTED ON DRAWING.

THESE DRAWINGS ARE THE PROPERTY OF THE BRANTFORD WATERFRONT DEVELOPMENT AUTHORITY. THEY ARE TO BE USED ONLY FOR THE PROJECT AND SITE SPECIFICALLY IDENTIFIED HEREIN. ANY REUSE OR MODIFICATION OF THESE DRAWINGS WITHOUT THE WRITTEN CONSENT OF THE BRANTFORD WATERFRONT DEVELOPMENT AUTHORITY IS STRICTLY PROHIBITED. THE BRANTFORD WATERFRONT DEVELOPMENT AUTHORITY ACCEPTS NO LIABILITY FOR ANY ERRORS OR OMISSIONS IN THESE DRAWINGS.

DATE	DESCRIPTION	BY	CHK
1	ISSUE FOR PERMIT	JL	JK




PROJECT: BRANTFORD WATERFRONT DEVELOPMENT  
 SITE: BRANTFORD WATERFRONT DEVELOPMENT, BRANTFORD, ONTARIO  
 DRAWING NO: BR-101

PREPARED BY: J. L. [Name]  
 CHECKED BY: J. K. [Name]  
 DATE: [Date]

BRANTFORD WATERFRONT DEVELOPMENT AUTHORITY  
 BRANTFORD, ONTARIO

TRUCKLE BRIDGE  
 DETAILS

95053  
 1/24/08  
 L-7




NOTE:  
 LIVE LOAD = 8 kPa, MAX. OFF-LADE ECL. INTENSITY 61 kPa  
 DESIGN ALL HEADRAYS AND STANCHION CONNECTIONS FOR  
 HORIZONTAL LOAD OF 20 kN/m. ACTING AT TOP OF HEADRAYS.  
 DESIGN ALL STEEL WITH LIVE LOAD OF 12 kPa PER THE COMPANY  
 BUILDING CODE.

Plan  
 Scale 1:24


wood bench  
 scale 1:12

This bridge will span across a 40-foot wide waterway. The bridge will be constructed of steel and concrete. The bridge will be constructed in accordance with the specifications of the Illinois Department of Transportation. The bridge will be constructed in accordance with the specifications of the Illinois Department of Transportation. The bridge will be constructed in accordance with the specifications of the Illinois Department of Transportation.


**NOTE:**  
 ALL DIMENSIONS ARE TO FACE UNLESS OTHERWISE SPECIFIED.




SECTION-ELEVATION  
 sonotube footing at independent abutment  
 1-2




SECTION-ELEVATION  
 metal handrail  
 1-3




fabricated frame - view of typical walkway bay  
 MAIN 118



expansion joint and deck spacing  
 1-4



SECTION-ELEVATION  
 sonotube footing at channel  
 1-5



SECTION-ELEVATION  
 light rail at channel  
 1-6

NO.	DESCRIPTION	DATE
1	ISSUED FOR PERMITS	11/14/18
2	ISSUED FOR PERMITS	11/14/18
3	ISSUED FOR PERMITS	11/14/18
4	ISSUED FOR PERMITS	11/14/18
5	ISSUED FOR PERMITS	11/14/18
6	ISSUED FOR PERMITS	11/14/18
7	ISSUED FOR PERMITS	11/14/18
8	ISSUED FOR PERMITS	11/14/18
9	ISSUED FOR PERMITS	11/14/18
10	ISSUED FOR PERMITS	11/14/18

**PMA**  
 PROFESSIONAL ENGINEER  
 No. 001-00000000  
 State of Illinois  
 11/14/18

**Brantford Waterfront**  
 Brantford, OH  
**Trestle Bridge**  
 Details  
 85053  
 11/14/18











## 2021 Structural Evaluation Report

---

### Appendix II 2018 Enhanced OSIM Summary Report



Prepared By:



City of Brantford

# Brant's Crossing Bridge (Structure 104) Enhanced OSIM Summary Report

**GMBP File: 118074**

**December 2018**





## TABLE OF CONTENTS

<b>1. INTRODUCTION .....</b>	<b>1</b>
1.1 Background .....	1
1.2 Nomenclature .....	2
<b>2. INSPECTION SUMMARY .....</b>	<b>2</b>
<b>3. DEFICIENCIES AND CONCERNS .....</b>	<b>7</b>
<b>4. EVALUATION OF ALTERNATIVES .....</b>	<b>7</b>
4.1 Alternative 1: Rehabilitation.....	7
4.2 Alternative 2: Replacement.....	8
4.3 Alternative 3: Removal/Permanent Closure .....	9
4.4 Other Considerations .....	9
4.5 Cost Estimates .....	10
<b>5. SUMMARY AND RECOMMENDATIONS .....</b>	<b>10</b>

## APPENDICES

- APPENDIX A: STRUCTURE 104 SKETCH - NAMING CONVENTION
- APPENDIX B: GLOSSARY OF TECHNICAL TERMS
- APPENDIX C: INSPECTION PHOTOS
- APPENDIX D: COST ESTIMATES

---

## BRANT'S CROSSING BRIDGE (STRUCTURE 104) ENHANCED OSIM SUMMARY REPORT

CITY OF BRANTFORD

DECEMBER 2018

GMBP FILE: 118074

---

### 1. INTRODUCTION

**GM BluePlan Engineering Limited (GMBP)** was retained by the City of Brantford (City) to complete an Enhanced OSIM inspection and summary report of the Brant's Crossing Bridge (Structure 104), located south of Colborne Street West and spanning the Grand River in the City of Brantford. The City requested this inspection in response to flooding and ice jamming events in February of 2018 in order to obtain a more detailed understanding of the condition of the bridge and to estimate costs for rehabilitation or replacement options.

The following is a summary description of the structure based on the results of our Enhanced OSIM inspection. The recommended capital works for rehabilitation and superstructure replacement are summarized below, complete with cost estimates attached. Capital costs have been estimated based on our recent experience in similar bridge construction projects, including recent tender prices received by GMBP, and discussions with suppliers and contractors. The capital cost estimates are presented in 2018 dollar values and do not include HST; however, cost estimates do include associated costs such as engineering design and contingencies. The estimated costs contained in this report should be considered as preliminary, as no pre-design work has been completed that may influence costs of items such as environmental considerations, transportation requirements, geotechnical conditions, regulatory authority requirements, as well as any ancillary work beyond the limits of the bridge.

It should also be noted that projects involving railway bridges converted to pedestrian bridges are quite unique, and can often be difficult to accurately estimate.


#### 1.1 Background

Structure 104 is a four span bridge that was originally designed to convey railway traffic, but has since been converted to a pedestrian bridge to carry pedestrian traffic and a utility crossing across the Grand River. Based on discussions with City staff, the utility crossing is no longer in active service. The superstructure consists of two through truss spans (Spans 2 & 3) and two plate girder spans (Spans 1 & 4). There are no drawings of the superstructure; however, the City provided drawings for the substructure that indicate the piers and abutments are founded on rock using spread footings. The drawings are dated as 1911 and 1912. It should be noted that the west pier is the abutment of a former bridge in this location that was repurposed as a pier. City staff have indicated that this bridge was converted to a pedestrian bridge in approximately 1997.

An ice jam event in the Grand River on February 21, 2018, prompted a preliminary visual inspection that was completed by GMBP. Based on the findings of the preliminary visual inspection, it was recommended that additional inspections be completed in the form of an Enhanced OSIM inspection in order to properly assess the condition of Structure 104 and that the structure be closed due to suspected movements of the superstructure. In order to safely assess all elements of the bridge within an arm's reach, ASI Group Ltd. (ASI) was retained to perform an underwater inspection of the abutment and pier footings and Acuren Group Ltd. (Acuren) was retained to perform a ropes access inspection of all other elements beyond an arm's reach, which included the underside of the structure and top members of the trusses. The ropes access inspection occurred over a period of 4 days from May 28, 2018, to May 31, 2018, and the underwater inspection occurred on June 22, 2018. All inspections were completed under the supervision of Adam Galewski, P.Eng., of GMBP. Copies of the ASI and Acuren reports are provided in **Appendix A**.

## 1.2 Nomenclature

For the purpose of this report, all bridge elements have followed a naming convention to inform their location. A sketch of Structure 104 that has adopted this naming convention has been included in **Appendix B**. For definitions of some of the technical terms used in this report refer to **Appendix C**. Steel members in each span generally consist of built-up sections. Refer to **Figure 1** below for the standard terminology used for these built-up sections.



**Figure 1: Cross Sections of Typical Built-Up Sections in Structure 104**

## 2. INSPECTION SUMMARY

**Table 1** and **Table 2** include a summary of deficiencies observed during the 2018 Enhanced OSIM inspection for the plate girder spans and the truss spans, respectively. The deficiencies have been summarized based on inspection reports provided by ASI and Acuren, as well as our inspector's observations and have been categorized as being major or minor depending on our opinion of their structural significance. Major deficiencies are considered to be critical and should be addressed in the next 1-5 years to maintain the structural integrity of the bridge. Minor deficiencies are not classified as urgent and can be addressed at a later time, though consideration should be given to addressing all deficiencies under one project. Refer to **Appendix D** for photos referenced in the tables below.



**Table 1: Plate Girder Spans - Summary of Deficiencies**

Structure Element	Observations	Photo Ref#
<b>Abutments/ Wingwalls</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Light to severe cracking, spalling and delamination throughout.</li> </ul>	G2
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Minor erosion at water level.</li> </ul>	G2
	<ul style="list-style-type: none"> <li>Wood blocking beneath floor beam on east abutment.</li> </ul>	G3
<b>Abutment Bearings</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>All bearings appear to be seized.</li> <li>Bearings located on each abutment appear to have shifted as follows:               <ul style="list-style-type: none"> <li>East Abutment – North Bearing: 25mm west</li> <li>East Abutment – South Bearing: 25mm north</li> <li>West Abutment – North Bearing: 40mm south</li> <li>West Abutment – South Bearing: 40mm south</li> </ul> </li> </ul> <p>Note: In the absence of previous monitoring data, the above bearing movements were determined based on measured deflections of the bearing anchor bolts.</p>	G4-G5
	<ul style="list-style-type: none"> <li>Anchor bolts have severe material loss ranging between 10% - 100% at the base of the bolt. Complete section loss of bolts was noted at the west abutment.</li> </ul>	G4
		G4-G6
<b>Stringers</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Very severe isolated corrosion with 40-100% material loss noted in web above lower shelf angles. The very severe material loss is isolated on stringers in Bay 5.</li> <li>Severe corrosion with 40-60% material loss noted in web above lower shelf angles throughout stringers in Bays 1-4.</li> <li>Isolated severe corrosion and impact damage on the interior lower shelf angle leg of the north stringer in Bay 5.</li> </ul>	G11
		-
		G12
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Stringer stiffeners have 100% material loss isolated at the base of the member. On average, the material loss extends up to 150mm above the lower shelf angle legs.</li> <li>Overall medium to severe corrosion noted throughout upper and lower shelf angles with up to 10% and 30% material loss respectively.</li> </ul>	G11- G12
	G11- G12	

Structure Element	Observations	Photo Ref#
<b>Girders</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Very severe isolated corrosion 50-100% material loss noted in web above lower interior shelf angle. The very severe material loss is isolated in the northern girder of the west span in Bay 6 and 7 and measures up to 75mm in height.</li> </ul>	G7
	<ul style="list-style-type: none"> <li>Severe isolated corrosion with up to 40% material loss noted in the web above lower interior shelf angle in Bay 22.</li> </ul>	G8
	<ul style="list-style-type: none"> <li>Severe isolated corrosion with up to 100% material loss noted in lower interior shelf angle on girders in the east span, isolated near the abutment. The isolated material loss extends for approximately 600mm from the east abutment bearings.</li> </ul>	G9
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Approximately 60% of exterior girder stiffeners have isolated 100% material loss at the base of the member. The 100% material loss extends up to 150mm above the lower shelf angles.</li> </ul>	G10
	<ul style="list-style-type: none"> <li>Severe isolated corrosion with up to 100% material loss noted in the web at the connection with the upper and lower shelf angles of the floor beams in both spans.</li> </ul>	G15
	<ul style="list-style-type: none"> <li>Overall medium to severe corrosion throughout girders with 10-20% material loss noted in upper and lower shelf angles and their connection rivets.</li> </ul>	G7-G10
<b>Floor Beams</b>	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Overall medium to severe corrosion throughout with 10-20% material loss isolated on upper and lower shelf angle legs.</li> </ul>	-
<b>Intermediate Diaphragms</b>	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Overall light to medium corrosion throughout with up to 10% material loss.</li> </ul>	-
<b>Lateral Bracing</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Medium to severe corrosion throughout with 100% isolated material loss noted in 9 members in both spans.</li> </ul>	G13
	<ul style="list-style-type: none"> <li>Medium to severe corrosion with significant areas of 100% material loss noted in 12 connection plates in both spans.</li> </ul>	G14

**Table 2: Truss Spans - Summary of Deficiencies**

Structure Element	Observations	Photo Ref#
<b>Piers</b>	<p><u>Minor Deficiencies</u></p> <ul style="list-style-type: none"> <li>• Light to severe delamination on faces of all piers.</li> <li>• Severe erosion throughout faces of pier footings and isolated areas of severe erosion at the interface of pier footings and pier shaft.</li> <li>• Undermining of the west pier footing for up to 4m on the east face and the entire west face. The maximum depth of scour was 0.7m and 0.4m on the east and west faces, respectively.               <ul style="list-style-type: none"> <li>○ Based on a review of drawings provided by the City, the west pier is founded on bedrock. It appears the bedrock has eroded in this location.</li> </ul> </li> </ul>	<p>T2</p> <p>T2</p> <p>-</p>
<b>Pier Bearings</b>	<p><u>Major Deficiencies</u></p> <ul style="list-style-type: none"> <li>• All bearings appear to be seized.</li> <li>• Roller bearings located on the east pier appear to have shifted as follows:               <ul style="list-style-type: none"> <li>○ East Pier – North Bearing: 65mm south</li> <li>○ East Pier – South Bearing: 75mm south</li> </ul> </li> </ul> <p>Note: In the absence of previous monitoring data, the above bearing movements were determined based on measured deflections of the bearing anchor bolts.</p>	<p>T3-T4, T7</p> <p>T3-T4</p>
	<p><u>Minor Deficiencies</u></p> <ul style="list-style-type: none"> <li>• Severe corrosion with complete isolated material loss of vertical plates enclosing all roller bearings.</li> </ul>	<p>T4</p>
	<ul style="list-style-type: none"> <li>• Severe corrosion with 20-30% material loss noted at the base of all bearing anchor bolts in west span.</li> </ul>	<p>T3-T4</p>
<b>Bottom Chords</b>	<p><u>Major Deficiencies</u></p> <ul style="list-style-type: none"> <li>• Very severe corrosion with up to 100% material loss isolated on legs of interior and exterior shelf angles near the lateral brace connections.</li> <li>• Severe corrosion with up to 100% material loss noted in lower shelf angle legs above bearings.</li> <li>• Severe corrosion with up to 100% material loss isolated at the lower web (locations: A8 in Bay 6, D8 in Bay 6, D12 in Bay 10, D12 in Bay 11, and D10 in Bay 11).</li> </ul>	<p>T5</p> <p>T6</p> <p>T7-T9</p>

Structure Element	Observations	Photo Ref#
<b>Verticals</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Light to medium corrosion throughout and severe corrosion with 100% material loss isolated at the bottom 200mm of all vertical members.</li> </ul>	T8
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Overall light to medium corrosion with severe corrosion with up to 20% material loss isolated at the bottom inside face of all vertical connection plates, connecting vertical members with bottom chords.</li> </ul>	-
<b>Stringers</b>	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Very isolated severe corrosion with 100% material loss noted in web above lower shelf angles. The severe corrosion and material loss is isolated to the south stringer in the east span.</li> </ul>	T10
	<ul style="list-style-type: none"> <li>Overall light to medium corrosion throughout with 10–30% material loss noted in lower shelf angle legs.</li> </ul>	T10
	<ul style="list-style-type: none"> <li>Stringer stiffeners have 100% material loss isolated at the base of the member. On average, the material loss extends up to 200mm above the lower shelf angle legs.</li> </ul>	T10
<b>Floor Beams</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Severe corrosion with up to 60% and 100% material loss noted in the entire lower shelf angle, throughout the full length of the floor beam from A16 to D16.</li> </ul>	T11
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Overall light to severe corrosion with up to 30% overall material loss noted throughout all floor beams. Isolated severe corrosion with up to 40% material loss noted in the lower shelf angle legs near the lateral brace plate connections.</li> </ul>	-
<b>Intermediate Diaphragms</b>	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Light to medium corrosion throughout with isolated 100% material loss noted in bottom chords at the connections to the stringers.</li> </ul>	T12
<b>Lateral Bracing</b>	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Medium to severe corrosion with significant areas of 100% material loss noted in 10 connection plates in both spans.</li> </ul>	-
	<ul style="list-style-type: none"> <li>Medium to severe corrosion throughout with 100% isolated material loss noted in 3 members in both spans.</li> </ul>	T13
	<ul style="list-style-type: none"> <li>Rust packing of up to 50mm between vertical legs of angles.</li> </ul>	T14

### 3. DEFICIENCIES AND CONCERNS

Severe corrosion and material loss was noted throughout steel members of Structure 104. Generally, the areas of severe corrosion noted were located in areas that have a higher exposure to water and chlorides, particularly horizontal surfaces where water and debris is able to sit and accumulate. This is a common issue for steel structures of this design, particularly considering the age of Structure 104. In areas where severe corrosion and material loss is present, a reduction in the capacity of the member is expected. Material loss in main structural members such as girders, stringers, floor beams, verticals and bottom chords are considered to be a major deficiency. Other steel members experiencing severe corrosion and material loss such as intermediate diaphragms and lateral bracing are considered to be secondary structural members. Therefore, we have considered these deficiencies as minor.

We note that Structure 104 was originally designed to convey railway traffic, but has since been converted to a pedestrian bridge that carries pedestrian traffic and a decommissioned utility crossing. Based on preliminary estimates, we anticipate the applied live load has been substantially reduced as compared to the estimated original design live load (assuming Cooper E-40 railway design loading). Conversely, the dead load on the structure has increased since its conversion to a pedestrian bridge with the addition of the pedestrian boardwalk and utility crossing, which were placed on top of the railway track and deck ties. Additionally, the loading effects of maintenance vehicles such as the trackless snow clearing equipment currently used by the City would need to be considered. Without completing a full load limit evaluation for the structure, it is difficult to determine the remaining capacity of each structural element.

Overall, Structure 104 is in fair to poor condition with numerous major deficiencies that should be addressed in 1-5 years. Except for the movement observed in the bearings on the east pier, it does not appear that any of the deficiencies noted were caused by the ice jam events in February of 2018.

To our knowledge, this is the first detailed inspection of Structure 104 since it was converted to a pedestrian bridge in approximately 1997. Therefore, it is difficult to determine the rate of deterioration of the bridge, and its remaining useful service life. Increased frequency of inspections may be warranted to better understand the performance of the structure.

### 4. EVALUATION OF ALTERNATIVES

We recommend the structure be rehabilitated, replaced or permanently closed in the next 1-5 years to address all major deficiencies. Provided below are additional considerations for the City prior to determining what to do regarding this structure:

- If rehabilitation is preferred, a load limit analysis is recommended to be completed to assess which elements and connections require rehabilitation to support the current pedestrian use of the structure. Based on the results of the analysis, the scope and cost of the rehabilitation may be refined. This may result in a reduced or increased rehabilitation cost estimate. The cost for a load limit analysis is estimated to be approximately \$50,000 to \$100,000.
- Given the significant capital cost required to rehabilitate, replace or permanently close Structure 104, we recommend the City complete a Schedule 'B' or 'C' Municipal Class Environmental Assessment (MCEA) to determine the most appropriate alternative for the City to pursue. This is estimated to cost approximately \$50,000 to \$100,000, and would include, at a minimum, a cultural heritage evaluation report (CHER), heritage impact assessment (HIA), archeological assessment, environmental impact study and hydraulic assessment.

The following summarizes rehabilitation, replacement and removal alternatives for Structure 104. Pre-engineering cost estimates for each alternative have been prepared and presented at the end of this section. Itemized cost estimates are provided in **Appendix D**.

#### 4.1 Alternative 1: Rehabilitation

In this alternative, all major and minor deficiencies would be addressed. Given the limited access to Structure 104, it is expected that the cost to construct temporary work platforms will be substantial as defects are noted throughout the



underside of the superstructure. Therefore, although the minor deficiencies do not need to be addressed in the next 1-5 years, we recommend all deficiencies be addressed under one capital works project.

Bearings would likely be replaced with elastomeric bearings similar to Structure 143 (TH&B Pedestrian Crossing) downstream of Structure 104. As shown in the photo below, a cast-in-place concrete bearing seat may be required to compensate for the difference in height of the new bearings. A hydraulic assessment could be considered to determine whether the superstructure should be raised to increase hydraulic capacity. The costs to complete a hydraulic assessment, raise the bridge, potential modifications to the abutment walls and wingwalls, and potential modifications to the approach pathways have not been included in the cost estimate provided in **Appendix D**. We estimate that raising the existing superstructure would greatly increase the complexity and cost of rehabilitation.



**Figure 2: Replaced abutment bearing on Bridge 143**

Deficient steel members would be reinforced or replaced, where applicable. Prior to the rehabilitation, the City may wish to complete coupon sampling to determine weldability and existing steel strength. The results of the analysis would determine whether reinforcing plates could be welded to the existing steel, or if plates would have to be bolted.

Concrete patch repairs to the abutments and piers have also been included in the scope of work.

The pre-engineering cost estimate provided in **Appendix D** accounts for the rehabilitation of all known minor and major defects. Upon completion of a load limit analysis for the structure, there may be opportunities to reduce the scope and capital cost of rehabilitation.

Based on our experience, a change in hydraulic capacity of the bridge structure would necessitate the completion of a MCEA.

## **4.2 Alternative 2: Replacement**

In this alternative, the existing superstructure would be removed and replaced. To complete removals, construction of temporary pads and access roads to staging areas within the Grand River may be required. For the purposes of this report we have considered the replacement structure to be four prefabricated steel truss bridge spans. The truss bridge spans could bear on existing piers and abutments, provided that concrete patch repairs are completed as required.

A hydraulic assessment should be considered to determine the capacity of the replacement structure and its bearing elevations. One of the benefits of the prefabricated truss system shown in **Figure 3** below is that the underside of the superstructure would be raised by approximately 1.0 m in comparison to the existing structure while maintaining the

same deck elevation. Therefore, the bearing elevation would need to increase just to maintain the existing deck elevation. This could be accomplished using similar construction details to those provided in **Figure 2** above. If the hydraulic assessment determines that the deck elevation is to be raised above the current elevations, additional modifications to the abutment walls, wingwalls, and the approach pathways would be required. The costs of these additional modifications have not been included in the pre-engineering cost estimate provided in **Appendix D**.

Based on our experience, a change in hydraulic capacity of the bridge structure would necessitate the completion of a MCEA.

It should be noted that the replacement superstructure types assumed for our estimated capital costs would not represent a sympathetic or replica replacement structure type. Replacement superstructures would be similar to a typical pre-fabricated steel truss structure, similar to the WGP Overhead Trail Bridge (Structure 152) shown below.



**Figure 3: Prefabricated steel truss superstructure (Structure 152)**

### 4.3 Alternative 3: Removal/Permanent Closure

In this alternative, the crossing would be closed permanently. The existing superstructure would either remain or be removed. The piers and abutments may also be removed; however, these could possibly be left in place as an indication that a structure once stood there and to mitigate the impacts to the environment from removal activities.

Should the crossing have heritage significance, various options would be considered including, but not limited to, removal of the superstructure for relocation to an adjacent location for a monument or commemorative display at the existing location.

Based on our experience, removal of a bridge would necessitate the completion of a MCEA.

The pre-engineering cost estimate provided in **Appendix D** accounts for the removal of the superstructure; however, it was assumed that the abutments and piers would remain and a commemorative plaque/display would be installed on both sides of the Grand River.

### 4.4 Other Considerations

Given the proposed scope of work for both rehabilitation and superstructure replacement, the potential change in the hydraulic capacity from superstructure modification and the potential heritage significance of the bridge, the City may wish to consider a MCEA to determine the appropriate means for addressing the deteriorated state of Structure 104 to inform which alternative to move forward to design and construction. We have accounted for a Schedule 'B' MCEA as part of our cost estimates. We note that the ultimate decision on schedule should be reviewed as part of the MCEA process.

We have not completed a cultural heritage evaluation of Structure 104; however, we believe there is a strong possibility that the structure has heritage value due to its age, superstructure types, location and views. As part of a MCEA, a Cultural Heritage Evaluation Report will be required to determine whether the structure has any heritage significance.

#### 4.5 Cost Estimates

**Table 3** includes a breakdown of the pre-design cost estimate for each alternative listed above. The prices listed below are presented in 2018 dollars and exclude HST, but include engineering at approximately 15% of construction costs and a 25% contingency. A breakdown of each cost can be found attached to this report.

**Table 3: Summary of Cost Estimates for Alternatives**

Description	Estimated Capital Costs (2018 Dollars)	Estimated Remaining Life Upon Completion of Work
Alternative 1: Rehabilitation	\$2,100,000	15-25 years
Alternative 2: Replacement	\$2,600,000	75 years
Alternative 3: Removal	\$1,100,000	Not Applicable

We note that the estimated cost for rehabilitation listed above is higher than previous estimates provided to the City in our letter dated April 13, 2018. The increase in the cost estimate for rehabilitation can be attributed to the advanced deterioration discovered in numerous elements of the superstructure, which were identified a result of the enhanced OSIM inspection. In comparison to the previous rehabilitation estimate, the following works have been revised or added to the scope of work recommended for rehabilitation:

- Replacement of all bearings;
- Concrete patch repairs to abutment walls, wingwalls and piers;
- Reinforcing or replacement of numerous steel members on the underside of the structure; and,
- Non-construction costs including a MCEA, engineering design and construction administration.

Please note that no design work has been completed that may influence costs of items such as environmental considerations, transportation requirements, geotechnical conditions, regulatory authority requirements, as well as any ancillary work beyond the limits of the bridge.

### 5. SUMMARY AND RECOMMENDATIONS

GMBP supervised an arm's length inspection of the Brant's Crossing Bridge (Structure 104). This inspection involved ropes access to inspect the superstructure and above-water substructure elements, as well as an underwater investigation to inspect the exposed footings of the abutments and piers. The results of this inspection determined that Structure 104 is in fair to poor condition, and in need of rehabilitative work in order to re-open for pedestrian use.

To re-open the bridge, we recommend that the City consider Alternative 1 or Alternative 2, described above. Given the significant capital cost required to rehabilitate and maintain Structure 104, we recommend the City consider a MCEA to determine the long-term plan for the structure. A load limit evaluation should be included as part of the MCEA to properly assess the scope of work required for rehabilitation.

Further to the recommendations provided above, we strongly suggest that the City ensures the following maintenance procedures are implemented or continued:


- Avoid use of de-icing chemicals, using sand as an alternative
- Regularly cut back and maintain vegetation around the abutments and deck of the structure
- Regularly clean structure of accumulated debris

We thank you for engaging in the services of GM BluePlan Engineering Limited, and trust that this report provides the information that you require at this time. If you have any questions, or if we may be of further assistance, please do not hesitate to contact us.

All of which is respectfully submitted,

GM BLUEPLAN ENGINEERING LIMITED

Per:



Adam Galezowski, P.Eng.

Per:




Jack Turner, P.Eng.

**APPENDIX A:**  
Structure 104 Sketch - Naming Convention



# Structure 104



**APPENDIX B:**  
Glossary of Technical Terms

## GLOSSARY OF TECHNICAL TERMS

### Concrete Deficiencies

---

**Delamination:** A discontinuity of the surface concrete which is substantially separated but not completely detached from concrete below or above it

**Spalling:** A continuation of the delamination process whereby the actions of external loads, pressures exerted by the corrosion of reinforcement or by the formation of ice in the delaminated area results in the breaking off of the delaminated concrete

### Steel Deficiencies

---

**Corrosion:** The deterioration of steel by chemical or electro-chemical reaction resulting from exposure to air, moisture, de-icing salts, industrial fumes and other chemicals and contaminants in the environment in which it is placed, also referred to as rust

**Material loss:** A continuation of corrosion, material loss refers to the percentage of cross sectional area that has corroded away

### General Deficiencies

---

**Scour:** The removal of material from the stream bed or bank due to the erosive action of moving water in the stream.

**Undermining:** The loss in support at the base of a foundation as a result of scour.

**APPENDIX C:**  
Inspection Photos



**Photograph G1: North elevation**



**Photograph G2: East Abutment**





**Photograph G3:** East abutment



**Photograph G4:** East abutment, north bearing anchor bolt



**Photograph G5:** West abutment, south bearing



**Photograph G6:** West abutment, north bearing anchor bolt






**Photograph G7:** West span, north girder



**Photograph G8:** East span, north girder interior



**Photograph G9:** East span, south girder at east abutment



**Photograph G10:** East span, north girder exterior





**Photograph G11:** West span, south stringer



**Photograph G12:** West span, north stringer




**Photograph G13:** East span, underside



**Photograph G14:** East span, typical lateral bracing connection plate






**Photograph G15:** East span, girder web at top of floor beam



**Photograph G16:** West span underside



**Photograph T1:** Truss bridge span, south elevation



Light to severe  
cracking, spalling and  
delamination

Erosion at water level

**Photograph T2:** West pier





**Photograph T3:** East pier, north roller bearing



**Photograph T4:** West pier, north roller bearing



**Photograph T5:** East truss, bottom chord at lateral brace connection



**Photograph T6:** Centre pier, southeast bearing



**Photograph T7:** West truss, north bottom chord (typical material loss)




**Photograph T8:** Typical vertical connection at bottom chord





**Photograph T9:** West truss, bottom chord



**Photograph T10:** East truss, south stringer





**Photograph T11: East truss (Floor beam #10)**



**Photograph T12: East truss, underside**



**Photograph T13:** East truss, lateral bracing



**Photograph T14:** West truss, lateral bracing

**APPENDIX D:**  
Cost Estimates

**STRUCTURE 104 COST ESTIMATE - REHABILITATION**

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>A GENERAL</b>					
A.1	Mobilization, Demobilization and Miscellaneous Project Costs	100%	L.S.	\$ 40,000.00	\$ 40,000.00
A.2	Supply and Install Temporary Working Platform	100%	L.S.	\$ 300,000.00	\$ 300,000.00
A.3	Environmental Protection	100%	L.S.	\$ 15,000.00	\$ 15,000.00
<b>TOTAL SECTION A</b>					<b>\$ 355,000.00</b>
<b>B GIRDER SPAN REHABILITATION</b>					
B.1	Temporary Bridge Jacking	100%	L.S.	\$ 150,000.00	\$ 150,000.00
B.2	Form, Supply and Install Concrete for Bearing Seat	100%	L.S.	\$ 20,000.00	\$ 20,000.00
B.3	Remove and Replace Existing Girder Bearings	8	each	\$ 4,000.00	\$ 32,000.00
B.4	Cast In Place Concrete Patch in Abutment Walls and Wingwalls	100%	L.S.	\$ 35,000.00	\$ 35,000.00
B.5	Reinforce Girder Webs	13.5	m	\$ 2,000.00	\$ 27,000.00
B.6	Reinforce Stringer Webs	45	m	\$ 2,000.00	\$ 90,000.00
B.7	Reinforce Girder Lower Shelf Angles	9	m	\$ 1,000.00	\$ 9,000.00
B.8	Reinforce Stringer Lower Shelf Angles	4.5	m	\$ 1,000.00	\$ 4,500.00
B.9	Supply and Install New Girder Stiffeners	35	each	\$ 500.00	\$ 17,500.00
B.10	Supply and Install New Stringer Stiffeners	80	each	\$ 500.00	\$ 40,000.00
B.11	Supply and Install New Lateral Braces Including Connection Plates	20	each	\$ 2,000.00	\$ 40,000.00
<b>TOTAL SECTION B</b>					<b>\$ 465,000.00</b>
<b>C TRUSS SPAN REHABILITATION</b>					
C.1	Temporary Bridge Jacking	100%	L.S.	\$ 200,000.00	\$ 200,000.00
C.2	Form, Supply and Install Concrete for Bearing Seat	100%	L.S.	\$ 20,000.00	\$ 20,000.00
C.3	Remove and Replace Existing Truss Bearings	8	each	\$ 4,000.00	\$ 32,000.00
C.4	Cofferdams and Dewatering around West Pier	100%	L.S.	\$ 20,000.00	\$ 20,000.00
C.5	Underpinning of West Pier	100%	L.S.	\$ 20,000.00	\$ 20,000.00
C.6	Cast In Place Concrete Patch in Piers	100%	L.S.	\$ 50,000.00	\$ 50,000.00
C.7	Reinforce Bottom Chord Webs	5	each	\$ 2,000.00	\$ 10,000.00
C.8	Reinforce Bottom Chord Lower Shelf Angle Legs at Lateral Brace Connections	24	each	\$ 1,000.00	\$ 24,000.00
C.9	Reinforce Bottom Chord Lower Shelf Angle Legs at Bearings	3	each	\$ 1,500.00	\$ 4,500.00
C.10	Reinforce Floor Beam Lower Shelf Angles	1	each	\$ 2,500.00	\$ 2,500.00
C.11	Reinforce Intermediate Diaphragms at Lower Connection to Stringer	48	each	\$ 500.00	\$ 24,000.00
C.12	Reinforce Verticals at Bottom Chord	20	each	\$ 500.00	\$ 10,000.00
C.13	Supply and Install New Vertical Stiffener Plates on Stringers	80	each	\$ 500.00	\$ 40,000.00
C.14	Supply and Install New Lateral Braces Including Connection Plates	24	each	\$ 2,000.00	\$ 48,000.00

**STRUCTURE 104 COST ESTIMATE - REHABILITATION**

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>TOTAL SECTION C</b>					<b>\$ 505,000.00</b>
<b>D MISCELLANEOUS COSTS</b>					
D.1	Remove and Dispose of Abandoned Watermain	100%	L.S.	\$ 30,000.00	\$ 30,000.00
D.2	Site Restoration	100%	L.S.	\$ 4,000.00	\$ 4,000.00
D.3	Contingency	100%	L.S.	\$ 340,000.00	\$ 340,000.00
<b>TOTAL SECTION D</b>					<b>\$ 374,000.00</b>
<b>E NON-CONSTRUCTION COSTS</b>					
E.1	Engineering Design and Construction Administration	100%	L.S.	\$ 200,000.00	\$ 200,000.00
E.2	Load Limit Analysis	100%	L.S.	\$ 100,000.00	\$ 100,000.00
E.3	Municipal Class Environmental Assessment	100%	L.S.	\$ 100,000.00	\$ 100,000.00
<b>TOTAL SECTION E</b>					<b>\$ 400,000.00</b>
<b>TOTAL REHABILITATION COST</b>					<b>\$ 2,099,000.00</b>



**STRUCTURE 104 COST ESTIMATE - REPLACEMENT**

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>A CONSTRUCTION COSTS</b>					
A.1	Mobilization, Bonding, Insurance, Demobilization	100%	L.S.	\$150,000.00	\$ 150,000.00
A.2	Environmental Protection	100%	L.S.	\$20,000.00	\$ 20,000.00
A.3	Contractor Layout	100%	L.S.	\$10,000.00	\$ 10,000.00
A.4	Cofferdams and Dewatering around Piers	100%	L.S.	\$40,000.00	\$ 40,000.00
A.5	Underpinning of Pier Footings	40	m3	\$1,100.00	\$ 44,000.00
A.6	Removal of Existing Deck, Railings, Railway Ties and Abandoned Watermain	430	m2	\$350.00	\$ 150,500.00
A.7	Construction of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$150,000.00	\$ 150,000.00
A.8	Removal of Existing Superstructure	100%	L.S.	\$300,000.00	\$ 300,000.00
A.9	Suspended Platforms at Piers	3	each	\$15,000.00	\$ 45,000.00
A.10	Cast In Place Concrete Patch in Piers	100%	L.S.	\$ 50,000.00	\$ 50,000.00
A.11	Platforms at Abutments	2	each	\$5,000.00	\$ 10,000.00
A.12	Cast In Place Concrete Patch in Abutment Walls and Wingwalls	100%	L.S.	\$ 35,000.00	\$ 35,000.00
A.13	Modifications to Existing Abutments and Piers	100%	L.S.	\$15,000.00	\$ 15,000.00
A.14	Design and Supply of new Superstructures for end Spans (23.3m)	100%	L.S.	\$260,000.00	\$ 260,000.00
A.15	Design and Supply of new Superstructures for middle Spans (37.7m)	100%	L.S.	\$360,000.00	\$ 360,000.00
A.16	Install new Superstructures	100%	L.S.	\$150,000.00	\$ 150,000.00
A.17	Removal of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$20,000.00	\$ 20,000.00
A.18	Site Restoration	100%	L.S.	\$4,000.00	\$ 4,000.00
A.19	Contingency at approximately 25%	100%	L.S.	\$ 455,000.00	\$ 455,000.00
<b>TOTAL SECTION A</b>					<b>\$ 2,268,500.00</b>
<b>B NON-CONSTRUCTION COSTS</b>					
B.1	Engineering Design and Construction Administration	100%	L.S.	\$200,000.00	\$ 200,000.00
B.2	Municipal Class Environmental Assessment	100%	L.S.	\$100,000.00	\$ 100,000.00
B.3	Approvals (est.)	100%	L.S.	\$15,000.00	\$ 15,000.00
<b>TOTAL SECTION B</b>					<b>\$ 315,000.00</b>
<b>TOTAL REPLACEMENT COST</b>					<b>\$ 2,583,500.00</b>

**STRUCTURE 104 COST ESTIMATE - SUPERSTRUCTURE REMOVAL**

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>A CONSTRUCTION COSTS</b>					
A.1	Mobilization, Bonding, Insurance, Demobilization	100%	L.S.	\$50,000.00	\$ 50,000.00
A.2	Environmental Protection	100%	L.S.	\$10,000.00	\$ 10,000.00
A.3	Contractor Layout	100%	L.S.	\$2,000.00	\$ 2,000.00
A.4	Removal of Existing Deck, Railings, Railway Ties and Abandoned Watermain	430	m2	\$350.00	\$ 150,500.00
A.5	Construction of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$150,000.00	\$ 150,000.00
A.6	Removal of Existing Superstructure	100%	L.S.	\$300,000.00	\$ 300,000.00
A.7	Removal of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$20,000.00	\$ 20,000.00
A.8	Site Restoration	100%	L.S.	\$4,000.00	\$ 4,000.00
A.9	Contingency at approximately 25%	100%	L.S.	\$ 170,000.00	\$ 170,000.00
<b>TOTAL SECTION A</b>					<b>\$ 856,500.00</b>
<b>B NON-CONSTRUCTION COSTS</b>					
B.1	Engineering Design and Construction Administration	100%	L.S.	\$100,000.00	\$ 100,000.00
B.2	Municipal Class Environmental Assessment	100%	L.S.	\$100,000.00	\$ 100,000.00
B.3	Approvals (est.)	100%	L.S.	\$15,000.00	\$ 15,000.00
<b>TOTAL SECTION B</b>					<b>\$ 215,000.00</b>
<b>TOTAL SUPERSTRUCTURE REMOVAL COST</b>					<b>\$ 1,071,500.00</b>



## 2021 Structural Evaluation Report

---

### Appendix III Summary of Load Factors used In Evaluation



## BRANT'S CROSSING BRIDGE (STRUCTURE 104) STRUCTURAL EVALUATION REPORT

### Summary of Loads Factors for Evaluation

Element	Dead Load Category	System Behaviour	Element Behaviour	Inspection Level	Reliability Index, $\beta$	Dead Load Factor, $\alpha_D$	*Live Load Factor, $\alpha_L$
Wood Deck	D2	3	3	3	2.50	1.10	1.35
Stringer	D1	3	3	3	2.50	1.05	1.35
Floor Beam	D1	2	3	3	2.75	1.06	1.42
Plate Girder	D1	1	3	3	3.00	1.07	1.49
Top Chord	D1	1	1	3	3.75	1.10	1.70
Bottom Chord	D1	1	1	3	3.75	1.10	1.70
Vertical	D1	2	1	3	3.50	1.09	1.63
Diagonal	D1	2	1	3	3.50	1.09	1.63

\* Live Load Factors for Maintenance vehicle

Prepared By:



City of Brantford

# TH&B Crossing Bridge (Structure 143) Structural Evaluation Report

GMBP File: 119104  
May 2021





## **TABLE OF CONTENTS**

<b>1.</b>	<b>INTRODUCTION .....</b>	<b>1</b>
<b>2.</b>	<b>BACKGROUND INFORMATION .....</b>	<b>1</b>
2.1	Existing Structure .....	1
2.2	2018 Structural Inspection.....	1
<b>3.</b>	<b>NOMENCLATURE .....</b>	<b>2</b>
<b>4.</b>	<b>METHODOLOGY .....</b>	<b>4</b>
4.1	Existing Conditions .....	4
4.2	Evaluation Procedure .....	4
4.2.1	Dead Loads.....	4
4.2.2	Live Loads.....	5
4.2.3	Load Factors .....	5
<b>5.</b>	<b>LOAD LIMIT EVALUATION .....</b>	<b>6</b>
<b>6.</b>	<b>CONCLUSION AND RECOMMENDATIONS .....</b>	<b>6</b>
<b>7.</b>	<b>LIMITATIONS .....</b>	<b>8</b>
<b>8.</b>	<b>BIBLIOGRAPHY .....</b>	<b>8</b>

## **APPENDICES**

**APPENDIX I: HISTORICAL DRAWINGS**

**APPENDIX II: 2018 ENHANCED OSIM SUMMARY REPORT**

**APPENDIX III: SUMMARY OF LOAD FACTORS USED IN EVALUATION**

---

## TH&B CROSSING BRIDGE (STRUCTURE 143) STRUCTURAL EVALUATION REPORT

CITY OF BRANTFORD

GMBP FILE: 119104

---

### 1. INTRODUCTION

**GM BluePlan Engineering Limited (GMBP)** was retained by the City of Brantford (City) to complete a load limit evaluation of the TH&B Railway River Crossing (Structure 143), located north of the Veterans Memorial Parkway bridge and spanning the Grand River in the City of Brantford. As a part of this assignment, the existing structure was inspected within an arm's reach and analyzed for the purposes of determining the current load limit and to identify and assess the various rehabilitation and replacement options as part of the Municipal Class Environmental Assessment (MCEA) process.

### 2. BACKGROUND INFORMATION

#### 2.1 Existing Structure

Structure 143 is a four-span bridge that was originally designed to convey railway traffic and was constructed in 1893. It has since been converted to a pedestrian bridge to carry pedestrian traffic and an electrical utility across the Grand River. The superstructure consists of four through plate girder spans. A rehabilitation project occurred in approximately 2006 that converted Structure 143 to a pedestrian bridge, as well as repaired several elements on the bridge. Design drawings for the rehabilitation project were provided by the City and are included in **Appendix I**.

#### 2.2 2018 Structural Inspection

Following an ice jam event in the Grand River on February 21, 2018, the structure was subject to a detailed structural inspection in accordance with the Ontario Structure Inspection Manual (OSIM). All elements of the bridge were safely accessed within an arm's reach by Acuren using ropes tied to the structure. The ropes access inspection occurred over a period of 2 days from June 4, 2018, to June 5, 2018. During the inspection, element geometry, orientation, and defects were measured and recorded, and the overall condition of each element was determined following the OSIM guidelines.


The complete Enhanced OSIM Summary Report for Structure 143 is provided in **Appendix II**.

Within the Enhanced OSIM Summary Report, both major and minor deficiencies were noted. Major deficiencies are considered to be critical and should be addressed in the next 1-5 years to maintain the structural integrity of the bridge. Minor deficiencies are not classified as urgent and can be addressed at a later time; however, consideration should be given to addressing all deficiencies under one project.

Major deficiencies are included in **Table 4** at the end of this report.

### 3. NOMENCLATURE

Steel members in each span of Structure 143 generally consist of built-up steel sections. Refer to **Figure 1** below for the standard terminology used for these built-up sections. Refer to **Figure 2** for standard terminology used for the structural elements in the bridge. Note that Figure 2 is provided for glossary of terms only; it is not representative of the actual dimensions of Structure 143. Refer to **Figure 3** for a cross section of the pedestrian platform installed in approximately 2006.



FLOOR BEAMS, STRINGERS, GIRDERS (TYP.)

**Figure 1: Cross Sections of Typical Built-Up Sections**




Figure 2: Typical Elements of Through Plate Girder Bridge




Figure 3: Existing Pedestrian Platform (Wiebe Engineering Group Inc., 2006)

## 4. METHODOLOGY

The structural evaluation was made in accordance with Section 14 of the CSA-S6-19 Canadian Highway Bridge Design Code (CHBDC). Provided below is a detailed description of the methodology used for this evaluation. It should be noted that our evaluation refers to the capacity of superstructure elements only. Section 14 of the CHBDC does not refer to the evaluation of the substructure. Based on the defects noted during the site visit completed by GMBP, we do not believe that the substructure elements are a limiting factor in the capacity of the evaluated structure.

### 4.1 Existing Conditions

The historical drawings do not provide details regarding the structural steel sections used to construct Structure 143. Therefore, the structural steel sections for load rating individual elements were derived based on dimensions taken during the Enhanced OSIM inspection. All recorded element dimensions were taken using tape measure and Vernier caliper.

Structural steel strength was determined in accordance with Table 14.1 in Section 14 of the CHBDC, using construction year dating before 1901. Based on the table, the existing steel was evaluated using a yield and tensile strength of 180 MPa and 360 MPa respectively.

Wood deck strength was determined in accordance with Section 9 of the CHBDC using Red Pine, as specified on the 2006 rehabilitation drawings.

### 4.2 Evaluation Procedure

#### 4.2.1 Dead Loads

Dead loads, such as the self-weight of all bridge components, were calculated in accordance with the CHBDC Table 3.4 and Clause 14.8 “Permanent Loads”. The weights of materials used for the evaluation of each structure (where applicable) are summarized in **Table 1**.

**Table 1: Summary of Dead Loads for Evaluations**

Material	Weight
Steel	77.0 kN/m <sup>3</sup>
Timber (Rail Ties)	9.5 kN/m <sup>3</sup>
Wood Planks (Deck)	6.0 kN/m <sup>3</sup>

Dead loads are apportioned into three categories: D1 (factory produced products, cast-in-place concrete – excluding decks), D2 (cast-in-place concrete decks, wood, field-measured asphalt, non-structural components), and D3 (asphalt, where the thickness is assumed to be 90 mm). In general, where the geometry could not be verified by field measurement the dead load was considered to be categorized as a D3 dead load.

Dead loads, such as the self-weight of all bridge components, were calculated in accordance with CSA S6-19 Table 3.4 and Clause 14.8 “Permanent Loads”. The weights of materials used for the evaluation of the structure are summarized in Table 3.

The dead loads include self weight of all steel elements, 305x203mm (12”x8”) rail ties spaced at 254mm (10”), 76x152mm (3”x6”) wood deck and supporting 6”x8” wood sleepers.



## 4.2.2 Live Loads

Two distinct live loads were considered for the load rating evaluation. First, a 4.0 kPa pedestrian load specified in Clause 3.8.12 of the CHBDC was applied to the pedestrian platform. The second live load considered was the maintenance vehicle load specified in Clause 3.8.12 with a gross weight of 80 kN (approximately 18,000 lbs). As per Clause 3.8.11, the maintenance vehicle and pedestrian load were not considered to act simultaneously.

The Live Load Capacity Factor,  $F$ , for Ultimate Limit State was calculated to determine the residual strength in the structural elements that is available to resist applied live loads once all permanent loads (i.e., dead loads) have been accounted for by the member's strength. As per Clause 14.17.2 of the CHBDC,  $F$  factors greater than or equal to 1, do not require a load posting, meaning the evaluated bridge is capable of supporting loads used to derive the  $F$  factors. The overall bridge posting is determined based on the smallest value of  $F$  derived for each individual bridge element.

## 4.2.3 Load Factors

Reliability Indices were used to determine the appropriate load factors for dead and live loads. These indices were dependent upon the element being analyzed, and its system behaviour, element behaviour and inspection level as outlined below:

- System behaviour, classified as one of the following:
  - (S1) Element failure will lead to total collapse
  - (S2) Element failure will likely not lead to total collapse
  - (S3) Element failure will lead to local failure only
- Element behaviour, classified as one of the following:
  - (E1) Element is subject to a sudden loss of capacity with little or no warning
  - (E2) Element is subject to a sudden loss of capacity with little or no warning but will retain post-failure capacity
  - (E3) Element is subject to gradual failure with warning of probable failure
- Inspection level, classified as one of the following:
  - (INSP1) Element is not accessible for inspection
  - (INSP2) Element is accessible for inspection to the satisfaction of the evaluator
  - (INSP3) Element is accessible for inspection and inspection is directed by the evaluator

Once the system behaviour, element behaviour and inspection level have been determined for the failure mode of each element being evaluated, a Reliability Index can be used to determine the appropriate dead and live load factors. It should be noted that a single element may have different load factors depending on the mode of failure being analyzed (i.e., a concrete beam analyzed for shear may have different load factors for analysis than the same beam analyzed for bending). For the purpose of this evaluation, pedestrian live load factors were assigned based on Table 3.1 in Section 3 of the CHBDC ( $\alpha_L = 1.7$ ). The target reliability index, a measure of the level of safety of a component(s), used during the evaluation of various elements, and respective live and dead load factors are summarized in the table in **Appendix III**.

In addition to the live load factor  $\alpha_L$ , no Dynamic Load Allowance (DLA) was considered for maintenance vehicle loading. According to Clause 3.8.4.5.1 of the CHBDC, maintenance vehicle load of 80 kN includes an allowance for dynamic effect.

## 5. LOAD LIMIT EVALUATION

Both hand calculations and finite element model analysis were completed to determine the member-by-member shear forces and bending moments as per the CHBDC. The finite element model analysis was completed using 2D model in S-Frame Version 11 software.

Resistance of steel structural components and the wood deck was determined using Section 9 and 10 of the CHBDC, respectively. To account for an overall light to medium corrosion, an average 15% steel thickness reduction was applied to all steel members. An additional 5% reduction in steel thickness was used to account for potential future steel corrosion that may take place before the next bridge evaluation. As a result, the resistance of steel members was based on 80% of the steel thickness measured in the field. Additionally, some steel members were measured to have less than 80% of the steel thickness remaining. For these steel members with additional section loss, a resistance associated to the remaining section of the member was individually applied. To account for the isolated severe cracking and splintering noted in the wood deck, an average resistance adjustment factor of 0.8 was applied to wood elements.

See **Table 2** below for the summary of F factors for individual elements:

**Table 2: Load Posting Summary**

Element	Pedestrian Live Load Capacity Factor, F	Maintenance Vehicle Live Load Capacity Factor, F	Load Posting
Wood Deck	> 1.0	0.05	**Required
Stringer	> 1.0	> 1.0	Not Required
Floor Beam	> 1.0	> 1.0	Not Required
Plate Girder	> 1.0	> 1.0	Not Required

*\*\* Load Posting required only for maintenance vehicle (No load rating required for pedestrian loading)*

Upon completion of the structural analysis, it was determined that all structural elements have a Load Capacity Factor, F larger than 1.0 for the pedestrian load. Therefore, no load limit is required in reference to pedestrian loading.

It was determined that all structural elements, with the exception of the existing wood deck, have a Load Capacity Factor, F, larger than 1.0 for the CHBDC 80 kN maintenance vehicle.

Note, the above findings align with the 2006 rehabilitation drawings involving deck replacement. Based on the drawings, the deck was designed for pedestrian load of 4.0 kPa and a maximum 2.8 kN (approximately 285 kg) maintenance vehicle axle load.

## 6. CONCLUSION AND RECOMMENDATIONS

Based on the load rating and deficiencies stated in this report, the existing bridge does not require a load posting, provided it is only subject to pedestrian or maintenance vehicle loading with a maximum axle loading of 2.8kN (285kg). If the bridge was to be used by a maintenance vehicle with a maximum gross weight in excess of that stated above, or the CHBDC maintenance vehicle of 80 kN (approximately 8,155 kg) as specified in Clause 3.8.11 of the CHBDC, we recommend that the existing wood deck be modified or fully replaced.

The existing deck could be modified by placing additional sleepers spaced at 600mm and replacing the existing 76x152mm (3"x6") planks with 38x140 (2"x6") planks nailed together. The additional dead load caused by thicker wood planks will change the steel element load capacity factors F; however, the revised F factors will still remain greater than 1.0, meaning no load posting would be required.

Please note that the inspection completed was at a single point in time. To our knowledge, this is the first Enhanced OSIM completed on this structure. Therefore, there is no reference benchmark to help assess the rate of deterioration of steel elements. The recommended work implementation timeframes and extension of service life may vary depending on the actual rate of deterioration. Please note that the use of salt to maintain this structure in the winter months is expected to result in accelerated deterioration of the structure. It is therefore recommended that winter maintenance of this structure avoid the use of salt.

In accordance with the 2018 Ontario Structure Inspection Manual (OSIM), with structures greater than 30 years old with critical components in poor condition, it is recommended that an Enhanced OSIM inspection be completed every 6 years in order to monitor member deterioration, until such time that a major rehabilitation is completed to address the poor condition members. The last Enhanced inspection was completed in spring of 2018. Prior to detailed design of major rehabilitation work, it is recommended that an additional Enhanced OSIM take place to confirm the scope of the major rehabilitation work.

In addition to modifying the existing deck to increase the load limit, there are several other deficiencies identified in the 2018 Enhanced OSIM that could be addressed as part of a capital project. A summary of the recommended rehabilitation work, based on the desired service life for Structure 143, is provided in **Table 3** and **Table 4** below. Refer to Appendix A of the 2018 Enhanced OSIM Summary Report included in **Appendix II** of this report for a diagram describing node locations referenced in the table below.

**Table 3: Option 1 – Minimum Rehabilitation Works Required for a 10 to 15 Year Service Life**

Item	Rehabilitation Work	Location
1.0	Modify or replace existing wood deck* <sup>1</sup>	<ul style="list-style-type: none"> <li>All four spans</li> </ul>
2.0	Install anchor bolts / guide plates at elastomeric bearings	<ul style="list-style-type: none"> <li>East abutment</li> </ul>
3.0	Install nuts and washers on bearing anchors	<ul style="list-style-type: none"> <li>South bearing in east pier in span no. 1</li> <li>South bearing in east pier in span no. 2</li> <li>South bearing in west pier in span no. 3</li> </ul>
4.0	Repair lateral brace and connection plate	<ul style="list-style-type: none"> <li>Node A32</li> </ul>

\*<sup>1</sup> Rehabilitation work required if bridge is to be used by maintenance vehicle specified in Clause 3.8.11 of the CHBDC

**Table 4: Option 2 – Rehabilitation Works Required for a 15 to 30 Year Service Life**

Item	Rehabilitation Work	Location
1.0	Modify or replace existing wood deck* <sup>1</sup>	<ul style="list-style-type: none"> <li>All four spans</li> </ul>
2.0	Concrete repair work	<ul style="list-style-type: none"> <li>West abutment and wingwalls</li> <li>West piers</li> </ul>
3.0	Repointing of stone blocks	<ul style="list-style-type: none"> <li>East abutment and wingwalls</li> </ul>
4.0	Install anchor bolts / guide plates at elastomeric bearings	<ul style="list-style-type: none"> <li>East abutment</li> </ul>
5.0	Install nuts and washers on bearing anchors	<ul style="list-style-type: none"> <li>South bearing in east pier in span no. 1</li> <li>South bearing in east pier in span no. 2</li> <li>South bearing in west pier in span no. 3</li> </ul>
6.0	Repair steel crack	<ul style="list-style-type: none"> <li>South column in east pier</li> </ul>
7.0	Repair lateral brace and connection plate	<ul style="list-style-type: none"> <li>Node A32</li> </ul>

\*<sup>1</sup> Rehabilitation work required if bridge is to be used by maintenance vehicle specified in Clause 3.8.11 of the CHBDC

Further to the recommendations provided above, we strongly suggest that the City ensures the following maintenance procedures are implemented or continued:

- Avoid use of de-icing chemicals, using sand as an alternative
- Regularly cut back and maintain vegetation around the abutments and deck of the structure
- Regularly clean structure of accumulated debris

## 7. LIMITATIONS

The following limitations are applicable to this load limit evaluation report:

- This report is intended exclusively for the Client(s) named in the report. The material in it reflects our best judgment in light of the information reviewed by GM BluePlan Engineering Limited at the time of preparation. Unless otherwise agreed in writing by GM BluePlan Engineering Limited, this report shall not be used to imply warranty as to the fitness of the property for a particular purpose. This report is not a certification of compliance with past or present regulations. No portion of this report may be used as a separate entity, it is written to be read in its entirety.
- Only the specific information identified has been reviewed. GM BluePlan Engineering Limited is not obligated to identify mistakes or insufficiencies in the information obtained from the various sources or to verify the accuracy of the information. GM BluePlan Engineering Limited may use such specific information obtained in performing its services and is entitled to rely upon the accuracy and completeness thereof.
- This assessment does not wholly eliminate uncertainty regarding the potential for existing or future losses in connection with a property. No physical or destructive testing has been performed unless specifically recorded. Conditions existing, but not recorded, were not apparent given the level of study undertaken. We can perform further investigation on items of concern, if so required.

## 8. BIBLIOGRAPHY

1. The Canadian Highway Bridge Design Code, CSA S6-19 (CHBDC)
2. Bakht, B. and Jaeger, L.G (1988). Document SRR-88-04 “Bridge Testing – A Surprise Every Time.” The Research and Development Branch, Ministry of Transportation of Ontario

We thank you for engaging in the services of GM BluePlan Engineering Limited, and trust that this report provides the information that you require at this time. If you have any questions, or if we may be of further assistance, please do not hesitate to contact us.

Your truly,

GM BLUEPLAN ENGINEERING LIMITED

Per:



Adam Galezowski, P.Eng.



Per:



Jack Turner, P.Eng.







## 2021 Structural Evaluation Report

---

### Appendix I Historical Drawings



# CONVERSION OF FORMER CN BRIDGE OVER GRAND RIVER TO PEDESTRIAN WALKWAY



**DRAWING LIST:**

- SP1 SITE PLAN
- S1 PEDESTRIAN WALKWAY DETAILS
- S2 ABUTMENT APPROACH DETAILS
- S3 ABUTMENT APPROACH DETAILS
- S4 ABUTMENT REPAIR DETAILS
- S5 RETAINING WALL DETAILS
- CS1 CONSTRUCTION SPECIFICATIONS



KEY PLAN




**CITY OF BRANTFORD**  
PROJECT No. 2006.201

WIEBE ENGINEERING GROUP INC. PROJECT No.: BR04077










ELEVATION OF WEST ABUTMENT

ELEVATION OF EAST ABUTMENT



PLAN VIEW OF RETAINING WALL @ WEST ABUTMENT

PLAN VIEW OF RETAINING WALL @ EAST ABUTMENT

1. PROJECT NO.	100-1000
2. PROJECT NAME	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
3. PROJECT LOCATION	100-1000
4. PROJECT DATE	APRIL 2006
5. PROJECT STATUS	ISSUED FOR PERMIT
6. PROJECT OWNER	BRANTFORD CITY
7. PROJECT ENGINEER	WIEBE ENGINEERING GROUP INC.
8. PROJECT ARCHITECT	BRANTFORD CITY
9. PROJECT CONTRACT VALUE	\$2,000,000
10. PROJECT START DATE	APRIL 2006
11. PROJECT END DATE	APRIL 2006
12. PROJECT PERMIT NO.	100-1000
13. PROJECT PERMIT EXPIRES	APRIL 2006
14. PROJECT PERMIT STATUS	ISSUED FOR PERMIT
15. PROJECT PERMIT COMMENTS	



**WIEBE**  
Engineering  
Group Inc.

CONCRETE RETAINING WALLS  
BRANTFORD, ONTARIO  
100-1000  
100-1000





DESIGNER	WIEBE
CHECKER	WIEBE
DATE	APRIL 2006
SCALE	AS SHOWN
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
LOCATION	BRANTFORD, ONTARIO
DATE	APRIL 2006
SCALE	AS SHOWN
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY

**BRANTFORD**  
Engineering  
Group Inc.

CONCRETE RETAINING WALLS  
BRANTFORD, ONTARIO  
100-1000  
100-1000

DATE	APRIL 2006
SCALE	AS SHOWN
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
LOCATION	BRANTFORD, ONTARIO
DATE	APRIL 2006
SCALE	AS SHOWN
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY





NO.	DESCRIPTION	QTY	UNIT
1	REINFORCING BAR #4	100.00	LB
2	REINFORCING BAR #4	100.00	LB
3	REINFORCING BAR #4	100.00	LB
4	REINFORCING BAR #4	100.00	LB
5	REINFORCING BAR #4	100.00	LB
6	REINFORCING BAR #4	100.00	LB
7	REINFORCING BAR #4	100.00	LB
8	REINFORCING BAR #4	100.00	LB
9	REINFORCING BAR #4	100.00	LB
10	REINFORCING BAR #4	100.00	LB









**Webe Engineering Group Inc.**  
 CONSULTING ENGINEERS & PROJECT MANAGERS  
 1000 YORK STREET, SUITE 100, BRANTFORD, ONTARIO  
 N6A 1A1  
 TEL: 519-753-1111  
 WWW.WEBEENGINEERING.COM



**CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY**  
 BRANTFORD, ONTARIO  
 PROJECT NO. 2005-01  
 SHEET NO. 53

**ABUTMENT APPROACH DETAILS**



**SECTION A-A**

**SECTION B-B**

**SECTION C-C**

**SECTION D-D**


**SECTION E-E**

**SECTION F-F**

**SECTION G-G**


**SECTION H-H**

**SECTION I-I**



**NOTES:**

- ALL DIMENSIONS UNLESS OTHERWISE NOTED ARE IN FEET AND INCHES.
- CONCRETE SHALL BE 4000 PSI STRENGTH AND SHALL BE PLACED AND FINISHED IN ACCORDANCE WITH THE SPECIFICATIONS.
- ALL REINFORCEMENT SHALL BE EPOXY COATED UNLESS OTHERWISE NOTED.
- ALL REINFORCEMENT SHALL BE 1/2\"/>




**SECTION**




NORTH CORNER OF EAST ABUTMENT



EXIST. BEARING



SOUTH CORNER OF EAST ABUTMENT



BEARING SEAT DETAIL

NO.	DESCRIPTION	QUANTITY	UNIT
1	CONCRETE	100.00	CY
2	REINFORCING	100.00	LB
3	FORMWORK	100.00	SQ. FT.
4	PAINT	100.00	GA.
5	LABOR	100.00	HOUR
6	EQUIPMENT	100.00	HOUR
7	TRAVEL	100.00	MILE
8	PROFIT	100.00	PERCENT
9	TOTAL		



**W** Wiebe Engineering Group Inc.  
 10000 100th Street, Suite 100  
 Edmonton, Alberta T5A 0A6  
 Phone: (780) 443-1111  
 Fax: (780) 443-1112  
 Email: info@wiebe.com

PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
CLIENT	TRANSCANADIAN CORP.
DATE	APRIL 2009
SCALE	AS SHOWN
DRAWN BY	LS SHOWN
CHECKED BY	LS SHOWN
DATE	APRIL 2009
PROJECT NO.	09-001
DRAWING NO.	09-001-01

**CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY**  
 ABUTMENT REPAIR DETAILS

DATE	APRIL 2009
SCALE	AS SHOWN
DRAWN BY	LS SHOWN
CHECKED BY	LS SHOWN
DATE	APRIL 2009
PROJECT NO.	09-001
DRAWING NO.	09-001-01







## 2021 Structural Evaluation Report

---

### Appendix II 2018 Enhanced OSIM Summary Report





Prepared By:



City of Brantford

# TH&B Railway River Crossing (Structure 143) Enhanced OSIM Summary Report

**GMBP File: 118074**

**December 2018**



## **TABLE OF CONTENTS**

<b>1. INTRODUCTION .....</b>	<b>1</b>
1.1 Background .....	1
1.2 Nomenclature .....	2
<b>2. INSPECTION SUMMARY .....</b>	<b>2</b>
<b>3. DEFICIENCIES AND CONCERNS .....</b>	<b>4</b>
<b>4. EVALUATION OF ALTERNATIVES .....</b>	<b>5</b>
4.1 Alternative 1: Rehabilitation .....	5
4.2 Alternative 2: Replacement .....	5
4.3 Alternative 3: Removal/Permanent Closure .....	6
4.4 Other Considerations .....	6
4.5 Cost Estimate .....	7
<b>5. SUMMARY AND RECOMMENDATIONS .....</b>	<b>7</b>

## **APPENDICES**

- APPENDIX A: DESIGN DRAWINGS FOR CONVERSION TO PEDESTRIAN WALKWAY FOR STRUCTURE 143**
- APPENDIX B: ACUREN GROUP INC. INSPECTION REPORT**
- APPENDIX C: STRUCTURE 143 SKETCH - NAMING CONVENTION**
- APPENDIX D: GLOSSARY OF TECHNICAL TERMS**
- APPENDIX E: ENHANCED OSIM PHOTOS**
- APPENDIX F: COST ESTIMATE**

---

## TH&B RAILWAY RIVER CROSSING (STRUCTURE 143) ENHANCED OSIM SUMMARY REPORT

CITY OF BRANTFORD

DECEMBER 2018

GMBP FILE: 118074

---

### 1. INTRODUCTION

**GM BluePlan Engineering Limited (GMBP)** was retained by the City of Brantford (City) to complete an Enhanced OSIM inspection and summary report of the TH&B Railway River Crossing (Structure 143), located north of Veterans Memorial Parkway and spanning the Grand River in the City of Brantford. The City requested this inspection in response to flooding and ice jamming events in February of 2018 in order to obtain a more detailed understanding of the condition of the bridge and to estimate costs for rehabilitation or replacement options.

The following is a summary description of the structure based on the results of our Enhanced OSIM inspection. The recommended capital works for rehabilitation and superstructure replacement are summarized below, complete with cost estimates attached. Capital costs have been estimated based on our recent experience in similar bridge construction projects, including recent tender prices received by GMBP, and discussions with suppliers and contractors. The capital cost estimates are presented in 2018 dollar values and do not include HST; however, cost estimates do include associated costs such as engineering design and contingencies. The estimated costs contained in this report should be considered as preliminary, as no pre-design work has been completed that may influence costs of items such as environmental considerations, transportation requirements, geotechnical conditions, regulatory authority requirements, as well as any ancillary work beyond the limits of the bridge.

It should also be noted that projects involving railway bridges converted to pedestrian bridges are quite unique and can often be difficult to accurately estimate.


#### 1.1 Background

Structure 143 is a four-span bridge that was originally designed to convey railway traffic and was constructed prior to 1901. It has since been converted to a pedestrian bridge to carry pedestrian traffic and an electrical utility crossing across the Grand River. The superstructure consists of four through plate girder spans. A rehabilitation project occurred in approximately 2005 that converted Structure 143 to a pedestrian bridge, as well as repaired several elements on the bridge. Design drawings for the rehabilitation project were provided by the City and are included in **Appendix A**.

An ice jam event in the Grand River on February 21, 2018, prompted a preliminary visual inspection that was completed by GMBP. Based on the findings of the preliminary visual inspection, it was recommended that an arm's length inspection be completed in the form of an Enhanced OSIM inspection to properly assess the condition of Structure 143. To safely assess all elements of the bridge within an arm's reach, Acuren Group Inc. (Acuren) was retained to perform a ropes access inspection of all elements beyond an arm's reach, which included the underside of the structure. The ropes access inspection occurred over a period of 2 days from June 4, 2018, to June 5, 2018. All inspections were completed under the supervision of Adam Galezowski, P.Eng., of GMBP. A copy of the Acuren report is provided in **Appendix B**.

## 1.2 Nomenclature

For the purpose of this report, all bridge elements have followed a naming convention to inform their location. A sketch of Structure 143 that has adopted this naming convention has been included in **Appendix C**. For definitions of some of the technical terms used in this report refer to **Appendix D**. Steel members in each span generally consist of built-up sections. Refer to **Figure 1** below for the standard terminology used for these built-up sections.



**Figure 1: Cross Sections of Typical Built-Up Sections in Structure 143**

## 2. INSPECTION SUMMARY

**Table 1** includes a summary of observations from the 2018 Enhanced OSIM inspection. The observations have been summarized based on inspection reports provided by Acuren, as well as our inspector's observations and have been categorized as being major or minor depending on our opinion of their structural significance. Major deficiencies are considered to be critical and should be addressed in the next 1-5 years to maintain the structural integrity of the bridge. Minor deficiencies are not classified as urgent and can be addressed at a later time; however, consideration should be given to addressing all deficiencies under one project. Refer to **Appendix E** for photos referenced in **Table 1**.

**Table 1: Summary of Deficiencies**

Structure Element	Observations	Photo Ref#
<b>East Abutment/ Wingwalls</b>	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>Narrow to medium cracks in stone</li> <li>Light to severe loss of mortar in joints</li> </ul>	<p>-</p> <p>4</p>
<b>West Abutment/ Wingwalls</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Light to severe spalling and delamination with narrow to wide cracks throughout west abutment and ballast wall.</li> </ul>	<p>2</p>
<b>Steel Piers</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Wide crack on west face of south column of east pier (visible in previous biennial inspections).</li> </ul>	<p>10</p>
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>The east pier has isolated severe permanent deformations on the north face of the north column (visible in previous biennial inspections).</li> </ul>	<p>9</p>
	<ul style="list-style-type: none"> <li>The centre pier has isolated severe permanent deformations and cracking on the north face of the north column (visible in previous biennial inspections).</li> </ul>	<p>8</p>
<b>Concrete Pier</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Light to severe delamination and spalling throughout.</li> </ul>	<p>6, 7</p>
<b>Abutment and Pier Bearings</b>	<u>Major Deficiencies</u> <ul style="list-style-type: none"> <li>Elastomeric bearings on the east abutment appear to have been installed without anchor bolts (confirmed with 2005 drawings).</li> </ul>	<p>5</p>
	<ul style="list-style-type: none"> <li>Anchor bolts on bearings are missing nuts and washers at locations D9, D24 and D25.</li> </ul>	<p>13</p>
	<u>Minor Deficiencies</u> <ul style="list-style-type: none"> <li>The bearing at location A17 appears to have shifted 20mm south. In the absence of previous monitoring data, the movement of the bearing was determined based on the measured displacement between plates.</li> </ul>	<p>11</p>
	<ul style="list-style-type: none"> <li>Medium corrosion with up to 10% material loss isolated at the base of anchor bolts on bearings at locations A16, A17, D17, A24 and A25.</li> <li>Bearings on the west abutment are covered in debris.</li> </ul>	<p>12</p> <p>-</p>



Structure Element	Observations	Photo Ref#
<b>Girders</b>	<u>Minor Deficiencies</u>	
	<ul style="list-style-type: none"> <li>Evidence of a weld repair on the lower shelf angle of the north girder in Bay 28. There is a very minor crack in the weld at location A32.</li> <li>Overall light to medium corrosion noted throughout with up to 10% material loss.</li> </ul>	16 14-16
<b>Stringers</b>	<u>Minor Deficiencies</u>	
	<ul style="list-style-type: none"> <li>Overall light to medium corrosion noted throughout with up to 10% material loss.</li> </ul>	14
<b>Floor Beams</b>	<u>Minor Deficiencies</u>	
	<ul style="list-style-type: none"> <li>Overall light to medium corrosion noted throughout with up to 10% material loss.</li> </ul>	14,18
<b>Lateral Bracing</b>	<u>Major Deficiencies</u>	
	<ul style="list-style-type: none"> <li>Isolated severe corrosion with 100% material loss in lateral brace at location A32.</li> <li>Isolated severe corrosion with 100% material loss in lateral brace connection plate at location A32.</li> </ul>	18 17
	<u>Minor Deficiencies</u>	
	<ul style="list-style-type: none"> <li>Overall light to medium corrosion noted throughout with up to 10% material loss.</li> </ul>	17, 18
<b>Wood Deck</b>	<u>Major Deficiencies</u>	
	<ul style="list-style-type: none"> <li>Isolated severe cracking and splintering.</li> </ul>	19, 20

### 3. DEFICIENCIES AND CONCERNS

Overall, Structure 143 is in fair condition. In prior biennial OSIM inspections, severe corrosion in girders, stringers and floor beams was noted, with repairs to these members recommended in 1-5 years. Based on the results of the Enhanced OSIM inspection, we observed that these elements had overall light to medium corrosion and do not require rehabilitation. During the inspection, it was confirmed that the columns of the steel piers are filled with concrete. The deficiencies noted in the steel columns during the enhanced inspection were also noted in previous biennial inspections. Therefore, we do not believe that the deformations in the steel columns warrant urgent repair. The wide crack in the south column of the east pier should continue to be monitored with biennial inspections. Based on its location and that the columns are filled with concrete, visual monitoring may be considered in lieu of a formal crack monitoring program. As the steel columns provide confinement strength to the fill concrete, they should be repaired as part of the next capital project.

A suspected movement of approximately 20mm was noted at the centre pier on Span 2. This was determined by the deflected angle of the anchor bolt of the bearing. This location is inaccessible for typical biennial visual inspections, so we are unable to confirm whether this deflection was caused by the ice jam events in February 2018.

The wood deck appears to be in fair condition, with isolated sections requiring replacement. Based on conversations with City staff, we understand that City maintenance vehicles have broken through the wood deck in the past. We note

that the 2005 rehabilitation project accounted for a pedestrian load of 4.0 kPa and a maximum 2.8 kN maintenance vehicle axle load in the design. Any anticipated loading beyond these values should be confirmed through a structural evaluation.

The repair to the lower shelf angle of the main girders may be indicative of a previous coupon testing investigation, which would typically be required to confirm the suitability of welding for repairs. These areas should be monitored visually as part of the biennial inspections.

We believe the following deficiencies should be addressed as part of a capital project in the next 1-5 years to maintain the structure in working order:

- Concrete patch repairs to the west pier;
- Concrete patch repairs to the west abutment and wingwalls;
- Install missing nuts and washers on bearings;
- Install missing anchor bolts or guide plates at elastomeric bearings on the east abutment;
- Repointing of east abutment and wingwalls;
- Repair crack in south column of east pier;
- Repair lateral brace and connection plate; and,
- Replace wood deck.

To our knowledge, this is the first detailed inspection of Structure 143 since it was converted to a pedestrian bridge in approximately 2005. Therefore, it is difficult to determine the rate of deterioration of the bridge, and its remaining useful service life. Increased frequency of enhanced inspections may be warranted to better understand the performance of the structure. The next enhanced inspection of this structure should be scheduled in the next 3-5 years, or in advance of any rehabilitation work. We estimate that this inspection would cost approximately \$30,000+HST.

## 4. EVALUATION OF ALTERNATIVES

We have evaluated three alternatives for the City's consideration regarding Structure 143: rehabilitation, replacement and removal. The following sections summarize each alternative, with pre-design cost estimates presented at the end of the section. Itemized cost estimates are provided in **Appendix F**.

### 4.1 Alternative 1: Rehabilitation

In this alternative, all major and minor deficiencies would be addressed. Major cost items would include concrete repairs to the west abutment and west pier and replacement of the wood deck. Our experience with wood bridge decks is that their useful life is typically 10-15 years.

A hydraulic assessment could be considered to determine whether the superstructure should be raised to increase hydraulic capacity. The costs to complete a hydraulic assessment, raise the bridge, potential modifications to the abutment walls and wingwalls, and potential modifications to the approach pathways have not been included in the cost estimate provided in **Appendix F**. We estimate that raising the existing superstructure would greatly increase the complexity and cost of rehabilitation.

Based on our experience, a change in hydraulic capacity of the bridge crossing would necessitate the completion of a Municipal Class Environmental Assessment (MCEA).

### 4.2 Alternative 2: Replacement

In this alternative, the existing superstructure would be removed and replaced. To complete removals, construction of temporary pads and access roads to staging areas within the Grand River may be required. For the purposes of this report we have considered the replacement structure to be four prefabricated steel truss bridge spans. The truss bridge spans could bear on existing piers and abutments, provided that concrete and steel repairs are completed as required.

A hydraulic assessment should be considered to determine the capacity of the replacement structure and its bearing elevations. One of the benefits of the prefabricated truss system shown in **Figure 2** below is that the underside of the superstructure would be raised by approximately 1.0 m in comparison to the existing structure while maintaining the same deck elevation. Therefore, the bearing elevation would need to increase just to maintain the existing deck elevation. This could be accomplished using similar construction details to those provided in the 2005 rehabilitation of the east abutment. If the hydraulic assessment determines that the deck elevation is to be raised above the current elevations, additional modifications to the abutment walls, wingwalls, and the approach pathways would be required. The costs of these additional modifications have not been included in the pre-engineering cost estimate provided in **Appendix D**.

Based on our experience, a change in hydraulic capacity of the bridge structure would necessitate the completion of a MCEA.

It should be noted that the replacement superstructure types assumed for our estimated capital costs would not represent a sympathetic or replica replacement structure type. Replacement superstructures would be similar to a typical pre-fabricated steel truss structure, similar to the WGP Overhead Trail Bridge (Structure 152) shown below.



**Figure 2: Prefabricated steel truss superstructure (Structure 152)**

### 4.3 Alternative 3: Removal/Permanent Closure

In this alternative, the crossing would be closed permanently. The existing superstructure would either remain or be removed. The piers and abutments may also be removed; however, these could possibly be left in place as an indication that a structure once stood there and to mitigate the impacts to the environment from removal activities.

Should the crossing have heritage significance, various options would be considered including, but not limited to, removal of the superstructure for relocation to an adjacent location for a monument or commemorative display at the existing location.

Based on our experience, removal of a bridge would necessitate the completion of a MCEA.

The pre-engineering cost estimate provided in **Appendix F** accounts for the removal of the superstructure; however, it was assumed that the abutments and piers would remain and a commemorative plaque/display would be installed on both sides of the Grand River.

### 4.4 Other Considerations

If the City wishes to pursue superstructure replacement or wishes to rehabilitate the existing structure and raise the superstructure to provide more hydraulic capacity, the City should consider a MCEA to determine the appropriate means for addressing the condition of Structure 143. Based on our understanding of the MCEA process, without raising the superstructure we estimate that the appropriate schedule of MCEA for rehabilitation would be a Schedule 'A+'. We note that the ultimate decision on schedule should be reviewed as part of the MCEA process.

We have not completed a cultural heritage evaluation of Structure 143; however, we believe there is a strong possibility that the structure has heritage value due to its age, superstructure type, location and views. As part of a MCEA, a Cultural Heritage Evaluation Report will be required to determine whether the structure has any heritage significance.

#### 4.5 Cost Estimate

**Table 2** below includes our pre-design cost estimates for the rehabilitation, replacement and removal of Structure 143. The price below is presented in 2018 dollars and exclude HST, but include engineering at approximately 15% of construction costs and a 25% contingency. A breakdown of the cost estimate can be found in **Appendix F**.

**Table 2: Pre-Design Rehabilitation Cost Estimate for Structure 143**

Description	Estimated Capital Costs (2018 Dollars)	Estimated Remaining Life Upon Completion of Work
Alternative 1: Rehabilitation	\$710,000	15-30 years
Alternative 2: Replacement	\$2,500,000	75 years
Alternative 3: Removal	\$1,100,000	Not Applicable

Please note that no design work has been completed that may influence costs of items such as environmental considerations, transportation requirements, geotechnical conditions, regulatory authority requirements, as well as any ancillary work beyond the limits of the bridge.

### 5. SUMMARY AND RECOMMENDATIONS

GMBP supervised an arm’s length inspection of the TH&B Railway River Crossing (Structure 143). This inspection involved ropes access to inspect the superstructure and above-water substructure elements. The results of this inspection determined that Structure 143 is in fair condition. Rehabilitation in the next 1-5 years or replacement in the next 6-10 years should be considered. An option for removal was also considered for comparison purposes. The next enhanced inspection should be completed in 3-5 years, or in advance of rehabilitation. The crack on the south column of the east pier should be monitored visually through biennial OSIM inspections.

Further to the recommendations provided above, we strongly suggest that the City ensures the following maintenance procedures are followed:


- Avoid use of de-icing chemicals, using sand as an alternative
- Regularly cut back and maintain vegetation around the abutments and deck of the structure
- Regularly clean structure of accumulated debris

We thank you for engaging in the services of GM BluePlan Engineering Limited, and trust that this report provides the information that you require at this time. If you have any questions, or if we may be of further assistance, please do not hesitate to contact us.

All of which is respectfully submitted,


GM BLUEPLAN ENGINEERING LIMITED

Per:



Adam Galezowski, P.Eng.

Per:



Jack Turner, P.Eng.



**APPENDIX A:**  
Structure 143 Conversion and Repair Drawings

# CONVERSION OF FORMER CN BRIDGE OVER GRAND RIVER TO PEDESTRIAN WALKWAY



**DRAWING LIST:**

- SP1 SITE PLAN
- S1 PEDESTRIAN WALKWAY DETAILS
- S2 ABUTMENT APPROACH DETAILS
- S3 ABUTMENT APPROACH DETAILS
- S4 ABUTMENT REPAIR DETAILS
- S5 RETAINING WALL DETAILS
- CS1 CONSTRUCTION SPECIFICATIONS



KEY PLAN



**CITY OF BRANTFORD**  
PROJECT No. 2006.201

WIEBE ENGINEERING GROUP INC. PROJECT No.: BR04077







**KEY PLAN**

1. 1/2" DIA. WOOD JOIST	SPC
2. 1/2" DIA. WOOD JOIST	SPC
3. 1/2" DIA. WOOD JOIST	SPC
4. 1/2" DIA. WOOD JOIST	SPC
5. 1/2" DIA. WOOD JOIST	SPC
6. 1/2" DIA. WOOD JOIST	SPC
7. 1/2" DIA. WOOD JOIST	SPC
8. 1/2" DIA. WOOD JOIST	SPC
9. 1/2" DIA. WOOD JOIST	SPC
10. 1/2" DIA. WOOD JOIST	SPC
11. 1/2" DIA. WOOD JOIST	SPC
12. 1/2" DIA. WOOD JOIST	SPC
13. 1/2" DIA. WOOD JOIST	SPC
14. 1/2" DIA. WOOD JOIST	SPC
15. 1/2" DIA. WOOD JOIST	SPC
16. 1/2" DIA. WOOD JOIST	SPC
17. 1/2" DIA. WOOD JOIST	SPC
18. 1/2" DIA. WOOD JOIST	SPC
19. 1/2" DIA. WOOD JOIST	SPC
20. 1/2" DIA. WOOD JOIST	SPC
21. 1/2" DIA. WOOD JOIST	SPC
22. 1/2" DIA. WOOD JOIST	SPC
23. 1/2" DIA. WOOD JOIST	SPC
24. 1/2" DIA. WOOD JOIST	SPC
25. 1/2" DIA. WOOD JOIST	SPC
26. 1/2" DIA. WOOD JOIST	SPC
27. 1/2" DIA. WOOD JOIST	SPC
28. 1/2" DIA. WOOD JOIST	SPC
29. 1/2" DIA. WOOD JOIST	SPC
30. 1/2" DIA. WOOD JOIST	SPC
31. 1/2" DIA. WOOD JOIST	SPC
32. 1/2" DIA. WOOD JOIST	SPC
33. 1/2" DIA. WOOD JOIST	SPC
34. 1/2" DIA. WOOD JOIST	SPC
35. 1/2" DIA. WOOD JOIST	SPC
36. 1/2" DIA. WOOD JOIST	SPC
37. 1/2" DIA. WOOD JOIST	SPC
38. 1/2" DIA. WOOD JOIST	SPC
39. 1/2" DIA. WOOD JOIST	SPC
40. 1/2" DIA. WOOD JOIST	SPC
41. 1/2" DIA. WOOD JOIST	SPC
42. 1/2" DIA. WOOD JOIST	SPC
43. 1/2" DIA. WOOD JOIST	SPC
44. 1/2" DIA. WOOD JOIST	SPC
45. 1/2" DIA. WOOD JOIST	SPC
46. 1/2" DIA. WOOD JOIST	SPC
47. 1/2" DIA. WOOD JOIST	SPC
48. 1/2" DIA. WOOD JOIST	SPC
49. 1/2" DIA. WOOD JOIST	SPC
50. 1/2" DIA. WOOD JOIST	SPC
51. 1/2" DIA. WOOD JOIST	SPC
52. 1/2" DIA. WOOD JOIST	SPC
53. 1/2" DIA. WOOD JOIST	SPC
54. 1/2" DIA. WOOD JOIST	SPC
55. 1/2" DIA. WOOD JOIST	SPC
56. 1/2" DIA. WOOD JOIST	SPC
57. 1/2" DIA. WOOD JOIST	SPC
58. 1/2" DIA. WOOD JOIST	SPC
59. 1/2" DIA. WOOD JOIST	SPC
60. 1/2" DIA. WOOD JOIST	SPC
61. 1/2" DIA. WOOD JOIST	SPC
62. 1/2" DIA. WOOD JOIST	SPC
63. 1/2" DIA. WOOD JOIST	SPC
64. 1/2" DIA. WOOD JOIST	SPC
65. 1/2" DIA. WOOD JOIST	SPC
66. 1/2" DIA. WOOD JOIST	SPC
67. 1/2" DIA. WOOD JOIST	SPC
68. 1/2" DIA. WOOD JOIST	SPC
69. 1/2" DIA. WOOD JOIST	SPC
70. 1/2" DIA. WOOD JOIST	SPC
71. 1/2" DIA. WOOD JOIST	SPC
72. 1/2" DIA. WOOD JOIST	SPC
73. 1/2" DIA. WOOD JOIST	SPC
74. 1/2" DIA. WOOD JOIST	SPC
75. 1/2" DIA. WOOD JOIST	SPC
76. 1/2" DIA. WOOD JOIST	SPC
77. 1/2" DIA. WOOD JOIST	SPC
78. 1/2" DIA. WOOD JOIST	SPC
79. 1/2" DIA. WOOD JOIST	SPC
80. 1/2" DIA. WOOD JOIST	SPC
81. 1/2" DIA. WOOD JOIST	SPC
82. 1/2" DIA. WOOD JOIST	SPC
83. 1/2" DIA. WOOD JOIST	SPC
84. 1/2" DIA. WOOD JOIST	SPC
85. 1/2" DIA. WOOD JOIST	SPC
86. 1/2" DIA. WOOD JOIST	SPC
87. 1/2" DIA. WOOD JOIST	SPC
88. 1/2" DIA. WOOD JOIST	SPC
89. 1/2" DIA. WOOD JOIST	SPC
90. 1/2" DIA. WOOD JOIST	SPC
91. 1/2" DIA. WOOD JOIST	SPC
92. 1/2" DIA. WOOD JOIST	SPC
93. 1/2" DIA. WOOD JOIST	SPC
94. 1/2" DIA. WOOD JOIST	SPC
95. 1/2" DIA. WOOD JOIST	SPC
96. 1/2" DIA. WOOD JOIST	SPC
97. 1/2" DIA. WOOD JOIST	SPC
98. 1/2" DIA. WOOD JOIST	SPC
99. 1/2" DIA. WOOD JOIST	SPC
100. 1/2" DIA. WOOD JOIST	SPC








**Wiebe Engineering Group Inc.**  
 1000 WEST BUCKINGHAM STREET SUITE 100  
 BRANTFORD, ONTARIO L7R 4K7  
 TEL: 519-751-1100  
 FAX: 519-751-1101  
 www.wiebeengineering.com

DESIGNED BY	SPC
CHECKED BY	SPC
DATE	APRIL 2006
PROJECT NO.	BR04877
SCALE	AS SHOWN
DATE	APRIL 2006
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY

**CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY**  
 BRANTFORD, ONTARIO  
 PROJECT NO. BR04877


SCALE	AS SHOWN
DATE	APRIL 2006
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
PROJECT NO.	BR04877
SCALE	AS SHOWN
DATE	APRIL 2006
PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
PROJECT NO.	BR04877





ELEVATION OF WEST ABUTMENT

ELEVATION OF EAST ABUTMENT



PLAN VIEW OF RETAINING WALL @ WEST ABUTMENT

PLAN VIEW OF RETAINING WALL @ EAST ABUTMENT

1. PROJECT NO.	100-0000	DATE	04/01/2006
2. PROJECT NAME	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY	DATE	04/01/2006
3. PROJECT LOCATION	100-0000	DATE	04/01/2006
4. PROJECT CLIENT	BRANTFORD CITY	DATE	04/01/2006
5. PROJECT ENGINEER	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006
6. PROJECT CHECKER	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006
7. PROJECT APPROVED BY	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006
8. PROJECT NO.	100-0000	DATE	04/01/2006
9. PROJECT NAME	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY	DATE	04/01/2006
10. PROJECT LOCATION	100-0000	DATE	04/01/2006
11. PROJECT CLIENT	BRANTFORD CITY	DATE	04/01/2006
12. PROJECT ENGINEER	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006
13. PROJECT CHECKER	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006
14. PROJECT APPROVED BY	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006







**Wiebe Engineering Group Inc.**  
 CONSULTING ENGINEERS  
 100-0000  
 100-0000

PROJECT	CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY
DATE	04/01/2006
BY	WIEBE ENGINEERING GROUP INC.
CHECKED BY	WIEBE ENGINEERING GROUP INC.
APPROVED BY	WIEBE ENGINEERING GROUP INC.

BRANTFORD, ONTARIO  
 CONSULTING ENGINEERS

DATE	18 SHOWN	DATE	04/01/2006
BY	WIEBE ENGINEERING GROUP INC.	DATE	04/01/2006
PROJECT NO.	100-0000	DATE	04/01/2006





NO.	DESCRIPTION	QTY	UNIT
1	REINFORCING BARS	1000000	KG
2	FORMWORK	1000000	M <sup>2</sup>
3	CONCRETE	1000000	M <sup>3</sup>
4	STEEL	1000000	KG
5	PAINT	1000000	L
6	REINFORCING BARS	1000000	KG
7	FORMWORK	1000000	M <sup>2</sup>
8	CONCRETE	1000000	M <sup>3</sup>
9	STEEL	1000000	KG
10	PAINT	1000000	L

**BRANTFORD**

**Webe Engineering Group Inc.**

ENGINEERING CONSULTANTS & PROJECT MANAGERS

1000 KENNEDY STREET, SUITE 100, BRANTFORD, ONTARIO L7R 4K6

TEL: (519) 753-1111 FAX: (519) 753-1112

WWW.WEBEENGINEERING.COM

**CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY**

BRANTFORD, ONTARIO

APPROVED FOR THE CITY OF BRANTFORD

**ABUTMENT APPROACH DETAILS**





DATE: 15-NOV-2005

BY: UVEL 2005

PROJECT NO: BRN04077

SCALE: AS SHOWN

ISSUE NO: 53




SECTION 4-1

SECTION 4-2

SECTION 4-3

SECTION 4-4




**NOTES:**

1. ALL DIMENSIONS UNLESS OTHERWISE NOTED ARE IN FEET AND INCHES.
2. ALL REINFORCEMENT SHALL BE #4 BARS UNLESS OTHERWISE NOTED.
3. ALL REINFORCEMENT SHALL BE PLACED IN ACCORDANCE WITH THE REINFORCEMENT SCHEDULE.
4. ALL REINFORCEMENT SHALL BE PLACED IN ACCORDANCE WITH THE REINFORCEMENT SCHEDULE.
5. ALL REINFORCEMENT SHALL BE PLACED IN ACCORDANCE WITH THE REINFORCEMENT SCHEDULE.

**NORTH CORNER OF EAST ABUTMENT - REPAIR DETAILS**



**BEARING SEAT DETAIL**



**SECTION**



**NORTH CORNER OF EAST ABUTMENT**



**EXIST. BEARING**



**SOUTH CORNER OF EAST ABUTMENT**

EXIST. BEARING AREA WITH REPAIR AREA INDICATED BY DASHED LINE.

NO.	DESCRIPTION	QUANTITY	UNIT
1	CONCRETE	10.00	CU YD
2	REINFORCEMENT	10.00	TONS
3	FORMWORK	10.00	SQ YD
4	PAINT	10.00	GALES
5	LABOR	10.00	HOURS
6	TRUCK	10.00	HOURS
7	WATER	10.00	CU YD
8	ADDITIONAL MATERIALS	10.00	CU YD
9	ADDITIONAL LABOR	10.00	HOURS
10	ADDITIONAL TRUCK	10.00	HOURS
11	ADDITIONAL WATER	10.00	CU YD
12	ADDITIONAL ADJUSTMENTS	10.00	CU YD
13	ADDITIONAL REPAIRS	10.00	CU YD
14	ADDITIONAL FINISHES	10.00	CU YD
15	ADDITIONAL PROTECTIVE COATINGS	10.00	CU YD
16	ADDITIONAL CLEANING	10.00	CU YD
17	ADDITIONAL DEMOLITION	10.00	CU YD
18	ADDITIONAL DISPOSAL	10.00	CU YD
19	ADDITIONAL PROTECTIVE MEASURES	10.00	CU YD
20	ADDITIONAL SAFETY MEASURES	10.00	CU YD
21	ADDITIONAL INSURANCE	10.00	CU YD
22	ADDITIONAL PERMITS	10.00	CU YD
23	ADDITIONAL TESTING	10.00	CU YD
24	ADDITIONAL RECORDING	10.00	CU YD
25	ADDITIONAL CONTINGENCY	10.00	CU YD



**Wielbe Engineering Group Inc.**  
 1000 WEST 10TH AVENUE, SUITE 100  
 CALGARY, ALBERTA T2C 1L5  
 TEL: (403) 243-1111  
 FAX: (403) 243-1112  
 WWW.WIELEBE.COM

NO.	DESCRIPTION	QUANTITY	UNIT
1	CONCRETE	10.00	CU YD
2	REINFORCEMENT	10.00	TONS
3	FORMWORK	10.00	SQ YD
4	PAINT	10.00	GALES
5	LABOR	10.00	HOURS
6	TRUCK	10.00	HOURS
7	WATER	10.00	CU YD
8	ADDITIONAL MATERIALS	10.00	CU YD
9	ADDITIONAL LABOR	10.00	HOURS
10	ADDITIONAL TRUCK	10.00	HOURS
11	ADDITIONAL WATER	10.00	CU YD
12	ADDITIONAL ADJUSTMENTS	10.00	CU YD
13	ADDITIONAL REPAIRS	10.00	CU YD
14	ADDITIONAL FINISHES	10.00	CU YD
15	ADDITIONAL PROTECTIVE COATINGS	10.00	CU YD
16	ADDITIONAL CLEANING	10.00	CU YD
17	ADDITIONAL DEMOLITION	10.00	CU YD
18	ADDITIONAL DISPOSAL	10.00	CU YD
19	ADDITIONAL PROTECTIVE MEASURES	10.00	CU YD
20	ADDITIONAL SAFETY MEASURES	10.00	CU YD
21	ADDITIONAL INSURANCE	10.00	CU YD
22	ADDITIONAL PERMITS	10.00	CU YD
23	ADDITIONAL TESTING	10.00	CU YD
24	ADDITIONAL RECORDING	10.00	CU YD
25	ADDITIONAL CONTINGENCY	10.00	CU YD

**CONVERSION OF FORMER CN BRIDGE TO PEDESTRIAN WALKWAY**  
 EXISTING CONCRETE  
 REPAIR AND FINISHES

NO.	DESCRIPTION	QUANTITY	UNIT
1	CONCRETE	10.00	CU YD
2	REINFORCEMENT	10.00	TONS
3	FORMWORK	10.00	SQ YD
4	PAINT	10.00	GALES
5	LABOR	10.00	HOURS
6	TRUCK	10.00	HOURS
7	WATER	10.00	CU YD
8	ADDITIONAL MATERIALS	10.00	CU YD
9	ADDITIONAL LABOR	10.00	HOURS
10	ADDITIONAL TRUCK	10.00	HOURS
11	ADDITIONAL WATER	10.00	CU YD
12	ADDITIONAL ADJUSTMENTS	10.00	CU YD
13	ADDITIONAL REPAIRS	10.00	CU YD
14	ADDITIONAL FINISHES	10.00	CU YD
15	ADDITIONAL PROTECTIVE COATINGS	10.00	CU YD
16	ADDITIONAL CLEANING	10.00	CU YD
17	ADDITIONAL DEMOLITION	10.00	CU YD
18	ADDITIONAL DISPOSAL	10.00	CU YD
19	ADDITIONAL PROTECTIVE MEASURES	10.00	CU YD
20	ADDITIONAL SAFETY MEASURES	10.00	CU YD
21	ADDITIONAL INSURANCE	10.00	CU YD
22	ADDITIONAL PERMITS	10.00	CU YD
23	ADDITIONAL TESTING	10.00	CU YD
24	ADDITIONAL RECORDING	10.00	CU YD
25	ADDITIONAL CONTINGENCY	10.00	CU YD

**LS SHOWN**  
**APRIL 2009**  
**54**  
**DRW0077**






**APPENDIX C:**  
Structure 104 Sketch - Naming Convention



# Structure 143 - TH&B Railway River Crossing



**APPENDIX D:**  
Glossary of Technical Terms

## **GLOSSARY OF TECHNICAL TERMS**

### **Concrete Deficiencies**

---

**Delamination:** A discontinuity of the surface concrete which is substantially separated but not completely detached from concrete below or above it

**Spalling:** A continuation of the delamination process whereby the actions of external loads, pressures exerted by the corrosion of reinforcement or by the formation of ice in the delaminated area results in the breaking off of the delaminated concrete

### **Steel Deficiencies**

---

**Corrosion:** The deterioration of steel by chemical or electro-chemical reaction resulting from exposure to air, moisture, de-icing salts, industrial fumes and other chemicals and contaminants in the environment in which it is placed, also referred to as rust

**Material loss:** A continuation of corrosion, material loss refers to the percentage of cross sectional area that has corroded away

### **General Deficiencies**

---

**Scour:** The removal of material from the stream bed or bank due to the erosive action of moving water in the stream.

**Undermining:** The loss in support at the base of a foundation as a result of scour.

**APPENDIX D:**  
Inspection Photos



**Photograph 1: South elevation**



**Photograph 2: West abutment**





**Photograph 3:** East abutment, north corner



**Photograph 4:** East abutment



**Photograph 5:** East abutment, south bearing



**Photograph 6:** West pier





**Photograph 7:** West pier



**Photograph 8:** Center pier, north steel column (north face)



**Photograph 9:** East pier, north steel column (north face)



**Photograph 10:** East pier, south steel column





**Photograph 11:** Center pier, Span #2, north bearing



**Photograph 12:** East pier, anchor bolt at location A25





**Photograph 13:** West pier, bearing at location D9



**Photograph 14:** Underside, looking west



**Photograph 15:** North plate girder, looking west



**Photograph 16:** North girder at east abutment



**Photograph 17:** East span, lateral bracing connection plate



**Photograph 18:** East span, lateral bracing





**Photograph 19:** Deck top, looking east



**Photograph 20:** Deck top

**APPENDIX F:**  
Cost Estimates



## STRUCTURE 143 COST ESTIMATE - REHABILITATION

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>A CONSTRUCTION COSTS</b>					
A.1	Mobilization, Bonding, Insurance, Demobilization	100%	L.S.	\$ 40,000.00	\$ 40,000.00
A.2	Environmental Protection	100%	L.S.	\$ 10,000.00	\$ 10,000.00
A.3	Cofferdams and Dewatering around West Pier	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.4	Cast In Place Concrete Repair in West Pier	14	m3	\$ 6,000.00	\$ 84,000.00
A.5	Cast In Place Concrete Patch in West Abutment Wall, Ballast Wall and Wingwalls	10	m3	\$ 5,000.00	\$ 50,000.00
A.6	Work Platform at Centre Pier	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.7	Repair North Steel Column, Centre Pier	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.8	Work Platform at East Pier	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.9	Repair North Steel Column, East Pier	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.10	Repair South Steel Column, East Pier	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.11	Install Missing Nuts and Washers on East Abutment Bearings	3	ea	\$ 500.00	\$ 1,500.00
A.12	Work Platform at East Abutment	100%	L.S.	\$ 10,000.00	\$ 10,000.00
A.13	Install Anchor Bolts / Guide Plates at Elastomeric Bearings on East Abutment	2	ea	\$ 7,500.00	\$ 15,000.00
A.14	Repointing of East Abutment Wall and Wingwalls	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.15	Repair Lateral Brace and Connection Plate	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.16	Remove and Replace Wood Deck	670	ea	\$ 300.00	\$ 201,000.00
A.17	Site Restoration	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.18	Contingency at approximately 25%	100%	L.S.	\$ 90,000.00	\$ 125,000.00
<b>TOTAL SECTION A</b>					<b>\$ 626,500.00</b>
<b>B NON-CONSTRUCTION COSTS</b>					
B.1	Engineering Design and Construction Administration	100%	L.S.	\$ 70,000.00	\$ 70,000.00
B.2	Approvals (est.)	100%	L.S.	\$ 10,000.00	\$ 10,000.00
<b>TOTAL SECTION B</b>					<b>\$ 80,000.00</b>
<b>TOTAL REPLACEMENT COST</b>					<b>\$ 706,500.00</b>

**STRUCTURE 143 COST ESTIMATE - REPLACEMENT**

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>A CONSTRUCTION COSTS</b>					
A.1	Mobilization, Bonding, Insurance, Demobilization	100%	L.S.	\$ 150,000.00	\$ 150,000.00
A.2	Environmental Protection	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.3	Contractor Layout	100%	L.S.	\$ 10,000.00	\$ 10,000.00
A.3	Cofferdams and Dewatering around West Pier	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.4	Cast In Place Concrete Repair in West Pier	14	m3	\$ 6,000.00	\$ 84,000.00
A.5	Cast In Place Concrete Patch in West Abutment Wall, Ballast Wall and Wingwalls	10	m3	\$ 5,000.00	\$ 50,000.00
A.6	Removal of Existing Deck and Railway Ties	670	m2	\$ 250.00	\$ 167,500.00
A.7	Construction of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$ 150,000.00	\$ 150,000.00
A.8	Removal of Existing Superstructure	100%	L.S.	\$ 250,000.00	\$ 250,000.00
A.9	Suspended Platforms at Piers	3	each	\$ 15,000.00	\$ 45,000.00
A.7	Repair North Steel Column, Centre Pier	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.9	Repair North Steel Column, East Pier	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.10	Repair South Steel Column, East Pier	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.11	Platforms at Abutments	2	each	\$ 5,000.00	\$ 10,000.00
A.14	Repointing of East Abutment Wall and Wingwalls	100%	L.S.	\$ 5,000.00	\$ 5,000.00
A.13	Modifications to Existing Abutments and Piers	100%	L.S.	\$ 50,000.00	\$ 50,000.00
A.14	Design and Supply of new Superstructures (approx. 4 x 31.1m)	100%	L.S.	\$ 550,000.00	\$ 550,000.00
A.16	Install new Superstructures	100%	L.S.	\$ 150,000.00	\$ 150,000.00
A.17	Removal of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.18	Site Restoration	100%	L.S.	\$ 4,000.00	\$ 4,000.00
A.19	Contingency at approximately 25%	100%	L.S.	\$ 450,000.00	\$ 450,000.00
<b>TOTAL SECTION A</b>					<b>\$ 2,200,500.00</b>
<b>B NON-CONSTRUCTION COSTS</b>					
B.1	Engineering Design and Construction Administration	100%	L.S.	\$200,000.00	\$ 200,000.00
B.2	Municipal Class Environmental Assessment	100%	L.S.	\$100,000.00	\$ 100,000.00
B.3	Approvals (est.)	100%	L.S.	\$15,000.00	\$ 15,000.00
<b>TOTAL SECTION B</b>					<b>\$ 315,000.00</b>
<b>TOTAL REPLACEMENT COST</b>					<b>\$ 2,515,500.00</b>

**STRUCTURE 143 COST ESTIMATE - REMOVAL**

ITEM NO.	DESCRIPTION	ESTIMATED QUANTITY	UNIT OF MEASURE	UNIT PRICE	TOTAL AMOUNT
<b>A CONSTRUCTION COSTS</b>					
A.1	Mobilization, Bonding, Insurance, Demobilization	100%	L.S.	\$ 50,000.00	\$ 50,000.00
A.2	Environmental Protection	100%	L.S.	\$ 10,000.00	\$ 10,000.00
A.3	Contractor Layout	100%	L.S.	\$ 2,000.00	\$ 2,000.00
A.4	Removal of Existing Deck and Railway Ties	670	m2	\$ 250.00	\$ 167,500.00
A.5	Construction of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$ 150,000.00	\$ 150,000.00
A.6	Removal of Existing Superstructure	100%	L.S.	\$ 250,000.00	\$ 250,000.00
A.7	Removal of Temporary Access Paths and Staging Areas in Grand River	100%	L.S.	\$ 20,000.00	\$ 20,000.00
A.8	Site Restoration	100%	L.S.	\$ 4,000.00	\$ 4,000.00
A.9	Contingency at approximately 25%	100%	L.S.	\$ 160,000.00	\$ 160,000.00
<b>TOTAL SECTION A</b>					<b>\$ 813,500.00</b>
<b>B NON-CONSTRUCTION COSTS</b>					
B.1	Engineering Design and Construction Administration	100%	L.S.	\$100,000.00	\$ 100,000.00
B.2	Municipal Class Environmental Assessment	100%	L.S.	\$100,000.00	\$ 100,000.00
B.3	Approvals (est.)	100%	L.S.	\$15,000.00	\$ 15,000.00
<b>TOTAL SECTION B</b>					<b>\$ 215,000.00</b>
<b>TOTAL REPLACEMENT COST</b>					<b>\$ 1,028,500.00</b>



## 2021 Structural Evaluation Report

---

### Appendix III Summary of Load Factors used In Evaluation



## TH&B CROSSING BRIDGE (STRUCTURE 143) STRUCTURAL EVALUATION REPORT

### Summary of Loads Factors for Evaluation

Element	Dead Load Category	System Behaviour	Element Behaviour	Inspection Level	Reliability Index, $\beta$	Dead Load Factor, $\alpha_D$	*Live Load Factor, $\alpha_L$
Wood Deck	D2	3	3	3	2.50	1.10	1.35
Stringer	D1	3	3	3	2.50	1.05	1.35
Floor Beam	D1	2	3	3	2.75	1.06	1.42
Plate Girder	D1	1	3	3	3.00	1.07	1.49

\* Live Load Factors for Maintenance vehicle